11 KV Feeder Outage for the Month of July 2026

Sr No	Town Name	Substation	Feeder Name	Feeder Code	Rural / Urban	No.Of Consumers	No.Of Outages	Duration Of Outage (Sec)	Average Hours of Steady Supply	Reason for power disruptions
1	MAPUSA	220/33KV Thivim	11KV Thivim Village	1S03-1105	RURAL				24:00:00	
2	MAPUSA	33KV Bicholim	11KV MAYEM	1S05-1107	RURAL	2471	7	4920	23:48:17	O/C, E/F, M/T for Tree cutting
3	MAPUSA	33KV Sanquelim	11KV Sanquelim	1S08-1102	URBAN	4460	0	0	24:00:00	Nil
4	MAPUSA	33KV Porvorim	11KV Porvorim Bazar	1S09-1109	RURAL	861	8	10260	23:54:29	E/F, O/C. Cable fault - Faulty portion isolated and supply restored, Jumper open - rejumpering done.
5	MAPUSA	33KV Porvorim	Audit bhavan	1S09-1112	URBAN	679	7	1020	23:59:27	M/T, E/F, O/C. AB Switch faulty , Flashover at HT Consumer metering cubical
6	MAPUSA	33KV Valpoi	11KV Bhironda	1S11-1101	RURAL	680	1	1860	23:29:00	Tree fallen on line
7	MAPUSA	33KV Candolim	11KV Candolim	1S12-1103	RURAL	2097	0	0	24:00:00	
8	PANJIM	33KV Nagali hills(IT Park)	11KV BSNL	2S07-1105	URBAN				24:00:00	
9	PANJIM	33KV Madkai	11KV Industry I	2S15-1104	URBAN	71	9	359	23:54:01	Breakdown/ transient Fault/Planned Maintenace
10	MORMUGAO	33KV Bogda	HEADLAND	3S06-1101	URBAN	1912	11	4620	23:54:01	1) 33KV Incomer I supply failed, supply failed from Verna substation, 2) 33KV Incomer I supply failed, supply failed from Verna substation, 3) 33KV Incomer I supply failed, supply failed from Verna substation, 4) 33KV Incomer I supply failed, supply failed from Verna substation, 5) 33KV Incomer I supply failed, supply failed from Verna substation, 6) 33KV Incomer I supply failed, supply failed from Verna substation, 7) 33KV Incomer I supply failed, supply failed from Verna substation, 8) 33KV Incomer I supply failed, supply failed from Verna substation, 9) 33KV Incomer I supply failed, supply failed from Verna substation, 10) 33KV Incomer I supply failed, supply failed from Verna substation, 11) 33KV Incomer I supply failed, 110KV failure from Ponda
11	MARGAO	33KV Monte Hill	11KV Hari Mandir	4S03-1105	URBAN	1663	2	4620	23:21:30	33KV incomming Margao Express - II Failed, Substation yard AB Switch Maintenance

12	MARGAO	33KV Aquem	11KV Khareband	4S04-1101	URBAN	3267	3	3660	23:39:40	Feeder trripped on OCR & EFR after opening at Bajaj TLBS feeder charged stood mosture found at Alisha RMU transformer side, 10 MVA Transformer II Manually Tripped to attend Red Hot on VCB - Secondary side, 'B' Phase
13	MARGAO	33KV Carmona	11KV Zalor	4S08-1101	RURAL				24:00:00	
14	MARGAO	33KV Cuncolim	11KV Dharmapur	4S09-1106	RURAL				24:00:00	
15	MARGAO	33KV Pontemol	11KV Bansai	4S13-1105	RURAL				24:00:00	
16	MAPUSA	33KV Mapusa	11KV Althino	1S04-1105	URBAN				24:00:00	
17	MAPUSA	33KV Mapusa	11KV Siolim	1S04-1112	RURAL	4945	6	356	23:30:00	Load shedding from Mapusa Sub Station due to maintance of from at 220KV Thivin S/S
18	MAPUSA	33KV Nachinola	11KV Aldona UG	1S06-1105	RURAL				24:00:00	
19	MAPUSA	33KV Nagoa	11KV AGARWADDO	1S07-1109	RURAL				24:00:00	
20	MAPUSA	33KV Saligao	11KV Betim	1S10-1105	RURAL	3202	2	120	23:59:56	M/T to change supply of Betim, O/C Tripping due to Earth Fault
21	MAPUSA	33 KV Anjuna	11KV Starco	1S15-1103	RURAL				24:00:00	
22	PANJIM	33KV Corlim	11KV New Ind.Estate	2S01-1103	URBAN				24:00:00	
23	PANJIM	33KV EDC	11KV Patto-Plaza	2S02-1103	URBAN				24:00:00	
24	PANJIM	33KV Bambolim	11KV Siridao	2S05-1101	RURAL				24:00:00	
25	PANJIM	33KV Nagali hills(IT Park)	11KV Adraar	2S07-1101	URBAN				24:00:00	
26	PANJIM	33KV Nagali hills(IT Park)	11KV CARANZALEM	2S07-1102	URBAN				24:00:00	
27	PANJIM	33KV Curti	11KV Shanti Nagar	2S10-1105	URBAN				24:00:00	
28	PANJIM	33KV Kundaim	11KV Mardol	2S14-1101	RURAL	4225	29	34	23:59:26	Breakdown/ transient Fault/Planned Maintenace/
29	MORMUGAO	110/33/11 KV Verna	11KV IFB	3S04-1104	URBAN		1	300	24:00:00	Earth fault
30	MARGAO	33KV Benaulim	11KV Colva	4S07-1102	RURAL				24:00:00	
31	MARGAO	33KV Velim	11KV Dramapur	4S10-1105	RURAL				24:00:00	
32	MARGAO	33KV Canacona	11KV Agonda	4S11-1101	RURAL				24:00:00	
33	MARGAO	33KV Canacona	11KV Gaondongri	4S11-1104	RURAL				24:00:00	
34	MARGAO	33KV Pontemol	11KV Kakoda	4S13-1108	URBAN				24:00:00	
35	MARGAO	33KV Shigao	11KV Dhat	4S14-1103	RURAL	861	23	95640	23:06:54	Shutdown taken for tree cutting
36	MARGAO	33KV Xelpem	11KV Ponsamol	4S18-1102	RURAL	2179	9	71760	23:59:02	Due to frequent failure of AB Cable terminations kit, AB Cable puncture, tree fallen fallen on line, pole damaged due to tree fallen
37	MAPUSA	220/33KV Thivim	11KV Industrial Estate I (U/G)	1S03-1102	RURAL				24:00:00	
38	MAPUSA	33KV Mapusa	11KV Guirim	1S04-1109	RURAL				24:00:00	
39	MAPUSA	33KV Bicholim	11KV Karapur	1S05-1102	RURAL	0	0	0	24:00:00	
40	MAPUSA	33KV Nagoa	11KV Nagoa	1S07-1104	RURAL				24:00:00	
41	MAPUSA	33KV Porvorim	11KV Housing board	1S09-1106	RURAL	926	1	120	23:59:56	M/T, For load shifting.
42	MAPUSA	33KV Porvorim	Devashri Feeder	1S09-1113	URBAN	493	2	240	23:59:52	M/T, O/C. Circuity Breaker faulty.
43	MAPUSA	33KV Valpoi	11KV Nagargao (New)	1S11-1104	RURAL	2730	1	1860	23:29:00	Tree fallen on line
44	MAPUSA	220KV Amona	11KV Maina	1S13-1101	RURAL	375	2	360	23:57:00	M/T for change over

45	MAPUSA	33 KV Anjuna	11KV chapora	1S15-1104	URBAN				24:00:00	
46	MAPUSA	33KV Sal	11KV Mencurem	1S16-1104	RURAL	372	3	1800	23:50:00	O/C, E/F, M/T for Tree cutting
47	MAPUSA	33/11 KV GIS CALANGUTE	11KV Maria Rosa	1S18-1101	RURAL				24:00:00	
48	MAPUSA	33/11 KV GIS CALANGUTE	11KV Weena	1S18-1106	RURAL	454	2	3300	23:58:14	Manuel tripped, due to load shedding.
49	PANJIM	33KV Campal	11KV Ideal School	2S03-1106	URBAN				24:00:00	
50	PANJIM	33KV NIO	11KV Odxel	2S08-1102	URBAN				24:00:00	
51	PANJIM	33KV Dharbandora	11KV Sonarbag	2S11-1101	RURAL	1049	87	63960	06:14:00	Transient Fault,Breakdown,Planed shutdown, tree branch fallen on line
52	PANJIM	33KV Bethora	11KV Bonbag	2S13-1103	RURAL				24:00:00	
53	PANJIM	33KV Kundaim	11KV Industry I	2S14-1103	URBAN				24:00:00	
54	MORMUGAO	33KV Harbour	11KV Vasco city	3S01-1105	URBAN	1610	3	6720	23:56:30	Manually tripped 01 jumper open and attended 05 jumpers at Hindustan petrolum
55	MORMUGAO	33KV Sancoale	11KV Sicgil	3S03-1104	RURAL				24:00:00	
56	MORMUGAO	110/33/11 KV Verna	11KV Quellosim	3S04-1111	RURAL	4151	20	13140	23:59:53	1)Earth fault and Over current 2)Manually Tripped by Sancoale SS
57	MARGAO	33KV Cuncolim	11KV Balli	4S09-1103	RURAL				24:00:00	
58	MARGAO	33KV Poinguinim	11KV Khotigao	4S12-1103	RURAL				24:00:00	
59	MAPUSA	220/33KV Thivim	11KV Tivim	1S03-1108	RURAL	3780	9	33000	14:50:00	1. The feeder tripped on Over Current (Y Phase). After attending open jumper it trip again on overcurrent and charge upto main section feeder stood ok. No visible fault was observed during the inspection. After Sectionalizing the feeder was test-charged again and was found to be holding satisfactorily full feeder charged 2. The feeder tripped on Over Current (Y Phase). Post insulator found puncture at main section AB Switch same was replaced and full feeder charged 3. Feeder triped on Overcurrent, after petrolling and sectionalizing the feeder, found Consumer service wire was in contact with the 11 kV line, same was realigned by maitaining safety and mandatory clearence, same time Dhanva AB switch male contact of AB Switch were attended and full feeder charged. 4. The entire feeder was manually tripped to carry out tree trimming and creeper removing simultaneously at multiple locations along the feeder and Upon completion of the work, the full feeder charged. 5. Feeder tripped on Sensitive Earth Fault. Feeder charged after opening Palni & Indira nagar AB Switch feeder Holding. 6. Tripped on E/F, Manually tripped to sectionlise Dhanwa tapping AB Switch, after patrolling line palm leaves found on line, but feeder tripped again on Over current.Manually tripped to close Dhanwa tapping AB Switch, after petrolling line Crow found on line. same was removed and full feeder charged. 7. Feeder tripped on Earth Fault. After patrolling and sectionalizing the feeder Monkey on line same was removed and full feeder charged. 8. Feeder tripped on Earth Fault. After patrolling and sectionalizing the feeder found Monkey on line same was removed and full feeder charged. 9.Feeder was manually tripped to open compound tapping AB Switch for tree-cutting work and 11KV jumpering work of commissioning of a new transformer Center. feeder charged.

60	MAPUSA	33KV Nagoa	11KV Arpora	1S07-1105	RURAL				24:00:00	
61	PANJIM	33KV EDC	11KV Kanaka	2S02-1107	URBAN				24:00:00	
62	PANJIM	33KV Bambolim	11KV Santacruz	2S05-1105	RURAL				24:00:00	
63	PANJIM	33KV Nagali hills(IT Park)	11KV MANIPAL	2S07-1106	URBAN				24:00:00	
64	PANJIM	33KV NIO	11KV Alto-Nagali	2S08-1106	URBAN				24:00:00	
65	PANJIM	33KV Colony	11KV Ponda II	2S10-1101	URBAN	3439	2	240	23:56:00	Transient fault
66	PANJIM	33KV Curti	11KV Ponda II	2S10-1101	URBAN				24:00:00	
67	PANJIM	33KV Shiroda	11KV Shiroda Bazar	2S12-1102	RURAL	1758	7	1080	23:42:00	Transient Fault
68	MORMUGAO	33KV Harbour	11KV Harbour	3S01-1101	URBAN				24:00:00	
69	MORMUGAO	110/33/11 KV Verna	11KV Lokmat	3S04-1108	URBAN	94	347	283080	23:37:00	1)Load restrictions 2.Earth faultyand Over current tripping 3) Manually Tripped by S/D-I, Verna 4) Manually Tripped by Verna s/S for emergency work and testing
70	MORMUGAO	33KV Majorda	11KV Utorda	3S05-1103	RURAL				24:00:00	
71	MORMUGAO	33KV Majorda	11KV Arrosim	3S05-1104	RURAL	1563	7	11340	23:56:51	1) Banana tree fell on line near spana Building also conductor snapped , & supply backfed on utorda feeder by closing Cansaulim Railway Gate upto Konkan railway ABS ,Arossim Feeder full Charged at 15.10 Hrs. 2) after opening Domnic Bar ABS Feeder charged stood ok, as per public given message is ie coconut tree feel on line , after patrolling coconut tree fell on LT line ,full feeder charged at 17.02 . 3) Line patrolling found jumper cut at Arossim band ABS attend full feeder charged ok. 4) Delay due to staff on Nagoa Feeder Full line petrolling no fault found 5) Open baga Section ABS;s for tree cutting (4 Nos Transformers Affected) 6) Cansaulim Bazaar A.B. Switch opened on 11 KV Arossim feeder, and feeder was charged, stook okay. Thereafter, line was patrolled and Peter A.B. Switch was opened at 16:29. It was discovered that a coconut tree had uprooted and crashed on the line, thereby snapping the conductor and 4-pin crossarm. Upon rectifying the damage and completing the work, full feeder was charged at 19:25, which stood okay. 7) Opened Cansaulim Section Office AB Switch to remove creepers that were climbing on HT pole.
72	MARGAO	33KV Aquem	11KV KHAREBAND II	4S04-1109	RURAL				24:00:00	
73	MARGAO	33KV KRC	11KV MES	4S05-1103	RURAL	2899	3	6120	23:26:00	Tree branch touching 11 KV line,Shutdown taken by KRC S/S staff to attend HT work.,Conductor snapped
74	MARGAO	33KV Carmona	11KV Cavellossim	4S08-1104	RURAL				24:00:00	
75	MARGAO	33KV Cuncolim	11KV Pattem	4S09-1107	RURAL				24:00:00	
76	MARGAO	33KV Canacona	11KV Palolem	4S11-1105	URBAN				24:00:00	
77	MAPUSA	33KV Mapusa	11KV Market	1S04-1108	URBAN				24:00:00	
78	MAPUSA	33KV Bicholim	11KV IDC	1S05-1101	RURAL	163	2	120	23:59:00	O/C, E/F, M/T for Tree cutting
79	MAPUSA	33KV Nagoa	11KV Parra	1S07-1103	RURAL				24:00:00	
80	MAPUSA	33KV Porvorim	11KV Torda	1S09-1107	RURAL				24:00:00	
81	MAPUSA	33KV Porvorim	Highland Villa	1S09-1114	URBAN				24:00:00	
82	MAPUSA	220KV Amona	11KV Navelim	1S13-1102	RURAL	538	4	1320	23:54:30	M/T for change over

83	MAPUSA	33/11 KV GIS CALANGUTE	11KV Calculo	1S18-1102	RURAL	579	5	4680	23:57:29	Manuel tripped,due to safety purpuse, Manuel tripped,requested by JE
84	PANJIM	33KV EDC	11KV Neugi Nagar	2S02-1105	URBAN				24:00:00	
85	PANJIM	33KV Altinho	11KV Lydia Garden	2S04-1110	URBAN				24:00:00	
86	PANJIM	33KV NIO	11KV Taligao	2S08-1108	URBAN				24:00:00	
87	PANJIM	33KV Bethora	11KV Nirankal	2S13-1102	RURAL	2389	17	3960	22:54:00	Transient Fault,Breakdown,Planed shutdown, monkey fallen on line
88	MORMUGAO	33KV Kadamba	11KV New Waddem	3S02-1101	URBAN	5071	7	7860	23:55:54	OCR and earth fault, section AB switch belt cut and pin insulator found faulty near PWD water tank.
89	MORMUGAO	33KV Sancoale	11KV Cortalim	3S03-1105	RURAL	1833	5	20340	23:49:04	To Attend snapped Conductor,Jumper fault near Kala Bhavan,Maintenenace of AB/S in yard
90	MARGAO	33KV Monte Hill	11KV Lohia	4S03-1103	URBAN	3514	3	6420	23:24:20	Transformer flashover - Radha Medicals, Substation yard AB Switch Maintenance
91	MARGAO	33KV KRC	11KV Navelim UG	4S05-1105	URBAN	0	16	45660	23:12:26	To attend jumperTo attend jumper and guarding 3 poles damagedTo attend jumper which was found faultyTree fallen on lineTree Creeper fallen on lineCoconut leaves fallen on the line and jumper cutTo attend jumper near Tulsi AB switchPole bent near Avertano OfficeTo cut creepersTo attend RMU near Janata BarTo attend jumpers on Tulsi and Dyna AB switchTo replace faulty post insulator near Tulsi AB Switch
92	MARGAO	33KV Cuncolim	11KV Chinchinim	4S09-1104	RURAL				24:00:00	
93	MARGAO	33KV Poinguinim	11KV Poinguinim	4S12-1104	RURAL				24:00:00	
94	MAPUSA	33KV Pernem	11KV Dhargal	1S01-1105	RURAL	4015	8	25320	23:08:00	Tree branch fallen on line at Valpe, Virnoda; Manaswada to Oxelbag Patekar DTC section faulty; Jumper open at Sub station yard; Pin insulator faulty at Valpe, Virnoda
95	MAPUSA	33KV Saligao	11KV Navy	1S10-1107	RURAL				24:00:00	
96	MAPUSA	33KV Valpoi	11KV Thana	1S11-1103	RURAL	1580	5	9420	23:28:36	Tree fallen on line
97	MAPUSA	33KV Candolim	11KV Ximer	1S12-1101	RURAL				24:00:00	
98	MAPUSA	33 KV Anjuna	11KV Temvi	1S15-1101	URBAN	990	1	2460	23:19:00	1. Load Shedding due to emergency Shutdown on 33KV Feeder's from EHV Tivim Sub-station. Reason: To attend Jumper of 33KV Incomer-II Isolator at Tivim Substation.
99	MAPUSA	33/11 KV GIS CALANGUTE	11KV Post Office	1S18-1103	RURAL	932	8	3840	23:57:56	Manuel tripped,to take test charge at Sarvodaya Post office RMU over current earth fault, over current and earth fault,declared faulty, Manuel tripped to take test charge.
100	PANJIM	33KV Corlim	11KV Kadamba	2S01-1110	RURAL		2	8700	23:59:51	1. Navelkar Pride Flash Over. 2.Tripped on Over currrent & Earth Fault Relay.
101	PANJIM	33KV PILAR	11KV Neura	2S06-1101	RURAL				24:00:00	
102	PANJIM	33KV Shiroda	11KV Borim	2S12-1101	RURAL	5513	6	2400	23:20:00	Transient Fault
103	PANJIM	33KV Shiroda	11KV Torla Paz	2S12-1104	RURAL	2131	4	600	23:50:00	Transient Fault
104	MORMUGAO	33KV Kadamba	11KV Airport	3S02-1105	URBAN	2508	3	10200	23:54:42	Shutdown taken to attend to 3 red-hot jumpers on yard AB switch; switch then closed.
105	MORMUGAO	33KV Majorda	11KV Majorda	3S05-1102	RURAL				24:00:00	
106	MARGAO	33KV Monte Hill	11KV Lohia-II	4S03-1107	URBAN	54	2	4620	23:21:30	33KV incomming Margao Express - II Failed, Substation yard AB Switch Maintenance
107	MARGAO	33KV Canacona	11KV Gulem	4S11-1106	RURAL				24:00:00	
108	MARGAO	33KV Pontemol	11KV IDC	4S13-1103	RURAL				24:00:00	
109	MARGAO	33KV Shigao	11KV Collem	4S14-1101	RURAL	1244	10	13800	23:52:18	Shutdown taken for tree cutting

110	MAPUSA	33KV Pernem	11KV Torse	1S01-1102	RURAL	3597	16	6638	22:10:00	Cashew tree fallen on line at Mopa; Conductor snapped at Mopa; 11 KV guarding touch to LT line near Maria Bar, Torxe; Conductor touch to V cross arm at Mopa; To attend cut jumper at Highway AB switch, Naibag; Beetlenut tree fallen on line at Mopa; Coconut tree fallen on line at Mopa near Gure's house; Conductor snapped at Bhatpavni; Beatle nut tree fallen on line at Mopa tapping
111	MAPUSA	33KV Mapusa	11KV Khorlim	1S04-1107	URBAN				24:00:00	
112	MAPUSA	33KV Porvorim	11KV Salai	1S09-1108	RURAL	728	1	120	23:59:56	M/T, Load shifting.
113	MAPUSA	33KV Porvorim	11KV GURUDWARA	1S09-1111	URBAN	483	12	5640	23:56:58	M/T, E/F, O/C. Heavy wind and rain, Jumper open, insulator failed, underground cable phase sequence correction, load shifting and tree trimming.
114	MAPUSA	33KV Saligao	11KV PILERNE (UG)	1S10-1110	RURAL				24:00:00	
115	MAPUSA	33KV Valpoi	11KV Dabose	1S11-1106	RURAL				24:00:00	
116	MAPUSA	33KV Sal	11KV Ibrampur	1S16-1102	RURAL	375	7	3600	23:51:30	O/C, E/F, M/T for Tree cutting
117	PANJIM	33KV Altinho	11KV Tonca Miramar	2S04-1108	URBAN				24:00:00	
118	PANJIM	33KV PILAR	11KV Agasaim	2S06-1102	RURAL				24:00:00	
119	PANJIM	33KV Bethora	11KV Shiroda	2S13-1101	RURAL	715	16	1740	23:31:00	Transient Fault,Planed shutdown
120	MORMUGAO	33KV Kadamba	11KV Vasco church	3S02-1102	URBAN	3181	3	5700	23:57:00	Manually tripped for trimming tree branches near Roy Petrol pump.
121	MORMUGAO	33KV Sancoale	11KV Vasco-II	3S03-1106	RURAL	2463	15	39420	23:38:48	Jumper open in Yard, Conductor Snapped at Sai Service side, Line tightening,Due to falling of tree,To attend jumper on single pole near Karma School, Coconut Palm leaf fallen on 11KV line near Chicalim Panchayat Ground ,11 KV Line jumper was opened opposite Reliance Smart Bazaar ABS, cut the tree which was under 11 KV Vasco-II & 11 KV Dabolim Double circuit,for the replacement of faulty 11 KV disc on Vasco-I feeder,11 KV Jumper had opened on Chicalim four pole structure and was touching the metallic channel,Feeder was manually tripped as 11KV jumper was open on 11KV AB switch connecting to Vishal Megamart RMU. Flash over was observed inside the RMU., Feeder was manually tripped to reconnect the cable of Vishal Mega Mart RMU after attending flashover RMU.,HT Guard ing snapped and fell on LT Line,Planned shutdown for trimming of trees near lines
122	MARGAO	33KV Monte Hill	11KV GVN1	4S03-1102	URBAN	609	3	8280	23:14:00	Tree Fallen on Hospicio Side TransformerSubstation yard AB Switch Maintenance33KV incomming Margao Express - II Failed.
123	MARGAO	33KV Cuncolim	11KV IDC II	4S09-1101	RURAL				24:00:00	
124	MARGAO	33KV Poinguinim	11KV Loliem	4S12-1105	RURAL				24:00:00	
125	MAPUSA	33KV Pernem	11KV Sawal	1S01-1104	RURAL	1030	4	17640	19:06:00	Tree branch cutting at Sawalwada DTC; To attend main cut point near ITI tapping
126	MAPUSA	33KV Tuem	11KV Industry	1S02-1101	URBAN	452	1	1200	23:40:00	HT / LT line restringing work in IDC for safety purpose

127	MAPUSA	220/33KV Thivim	11KV Colvale	1S03-1104	RURAL	2849	6	31800	15:10:00	1. The feeder tripped on Sensitive Earth fault During patrolling, an 11 mtr rcc pole was found bent, same was straightened full feeder charged. 2. The feeder tripped on Over Current (Y Phase). Conductor snapped at Sainagar same was attended and full Feeder charged. 3. The feeder tripped on Over Current, phase unbalance. Charged after opening Bagkar AB Switch. Tree branch fallen on line, same was removed and full feeder charged. 4. The feeder was manually tripped to open the Manas AB Switch and Koni AB Switch for carrying out a scheduled shutdown for tree-cutting work. During the shutdown, the power supply was back-fedded to maintain continuity of supply to the affected area. Upon completion of the work, the Manas AB Switch and Koni AB Switch was closed, the back-feed arrangement was withdrawn, and the entire feeder was charged. 5. Feeder tripped on Earth fault after sectinalizing the feeder found Gurd channel of 33KV Pernem-I and II touching to 11KV Line. Same section was made dead by opening near by AB Switch, rest full feeder charged by back feeding. 6. Feeder tripped on Over Curent Earth fault after sectinalizing the feeder found Tree branch found on line near Cooperation bank Revora Same was removed and full feeder charged.
128	MAPUSA	33KV Mapusa	11KV Duler	1S04-1102	URBAN				24:00:00	
129	MAPUSA	33KV Mapusa	11KV City	1S04-1103	RURAL	2350	3	420	23:59:46	Overcurrent R,Y,B phases
130	MAPUSA	33KV Sanquelim	11KV Poriem	1S08-1101	RURAL	2376	1	2400	23:58:40	WRD Plant LA Failed.Same Isolated and Feeder Charge.
131	MAPUSA	33KV Valpoi	11KV Saleli	1S11-1102	RURAL	3205	2	120	23:59:00	To normalise the supply anf backfeed to city
132	MAPUSA	33KV Candolim	11KV Highland	1S12-1106	RURAL	2431	6	1200	23:59:21	Tripping due to Earth Fault
133	MAPUSA	33 KV Anjuna	11KV vagator	1S15-1102	RURAL	1053	1	3480	23:02:00	1. Load Shedding due to emergency Shutdown on 33KV Feeder's from EHV Tivim Sub-station. Reason: To attend Jumper of 33KV Incomer-II Isolator at Tivim Substation.
134	PANJIM	33KV EDC	11KV Old bus stand	2S02-1101	URBAN	741	1	1740	23:31:00	Plastic sheet found on Patto Colony DTC, same has been removed
135	PANJIM	33KV Curti	11KV Durbhat	2S10-1106	RURAL	3308	5	480	23:52:00	Transient fault
136	PANJIM	33KV Madkai	11KV Karanzal	2S15-1103	RURAL	822	10	398	23:53:22	Breakdown/ transient Fault/Planned Maintenace/
137	MORMUGAO	33KV Sancoale	11KV Cansualim	3S03-1102	RURAL	1761	5	15480	23:55:42	1) Dando Section conductor snapped after restringing conductor fabrica side faulty (coconut palm fell on line , full feeder charged at 17.51 hrs. 2) Upasnagar A.B. Switch was opened, after which feeder was charged, which stood okay. Thereafter, line patrolling was done, and HT jumper was found snapped onn 4-pole Mudder Transformer. The same was attended and replaced by staff and full feeder was charged, which stood okay. 3) 33 KV Power Transformer No: 03 tripped due to failure of Lightning Arrestor at Verna S/S 4) Feeder tripped on EFR. Cuelim AB switch was opened and feeder was test charged. Feeder stood uninterrupted. Later upon patrolling, it was found that coconut tree had fallen on line, which was cleared and full feeder was charged at 01:00 hrs 5) Attend cut jumper at Sancoale Sub-Station 11 KV Yard.

138	MORMUGAO	110/33/11 KV Verna	11KV Verna	3S04-1101	RURAL	3433	11	20700	23:59:49	1)Earth fault and Over current
139	MORMUGAO	110/33/11 KV Verna	11KV Nagoa	3S04-1106	RURAL	2012	14	10800	23:59:54	1)Earth fault and Over current
140	MARGAO	33KV Raia	11KV Curtorim	4S01-1105	RURAL				24:00:00	
141	MARGAO	33KV Fatorda	11KV Ambaji	4S02-1101	URBAN	4198	1	2520	23:18:00	11 KV Cable faulty between Dovondem DTC & TLBS Near MLA House
142	MARGAO	33KV Monte Hill	11KV Mutt	4S03-1106	URBAN	668	3	4740	23:33:40	Substation yard AB Switch Maintenance, 33KV incomming Margao Express - II Failed.
143	MARGAO	33KV Aquem	11KV Margao I	4S04-1107	URBAN	30	3	3180	23:42:20	10 MVA Transformer II Manually Tripped to attend Red Hot on VCB - Secondary side, 'B' Phase, 33KV incomming Failed.
144	MARGAO	33KV Nessai	11KV Goa Carbon	4S06-1104	URBAN	2231	12	19320	23:33:10	Tripped on sensitive EFR. Patrolling done upto Kings school AB switch. Took test charge. Line not holding Tripped on sensitive EFR. Found one jumper touching the line near Sonu Township ground. Feeder tripped on sensitive earth fault relay and HT Jumper Cut attended near Bethany Convent School By Linestaff Feeder got tripped on over current relay as tree branch had fallen on Nallah HT AB Switch
145	MARGAO	33KV Carmona	11KV Janoth Bazar	4S08-1102	URBAN				24:00:00	
146	MARGAO	33KV Cuncolim	11KV Cuncolim	4S09-1105	RURAL				24:00:00	
147	MARGAO	33KV Pontemol	11KV Panchwadi	4S13-1102	RURAL	3115	5	11700	23:53:30	Manual trippings, I/C supply failure , transient faults
148	MARGAO	33KV Xelpem	11KV Malkarne	4S18-1104	RURAL				24:00:00	
149	MAPUSA	33KV Pernem	11KV Nagzar	1S01-1101	RURAL	3676	16	74220	22:43:00	Jumper open at Amai, Virnoda; Jackfruit tree fallen on line at Sangaowada, Ozarim; To attend open jumper at Purva main section; Jumper attended on Chichule tapping; Tree branch fallen on line at Ozarim; Conductor snapped at Varkhand interlink AB switch; Pin punctured at Surangali, Hassapur; Tree branch found on line at Ozarim
150	MAPUSA	33KV Tuem	11KV Morjim	1S02-1104	RURAL	3096	4	165	23:30:00	To change 3 way RMU Newwada, Tree stick fallen on Jockey transformer
151	MAPUSA	220/33KV Thivim	11KV Industrial Estate II (U/G)	1S03-1107	URBAN				24:00:00	
152	MAPUSA	33KV Mapusa	11KV Sodiem	1S04-1111	RURAL	2350	5	420	23:59:46	Overcurrent R,Y,B phases
153	MAPUSA	33KV Nagoa	11KV Sanqwadi	1S07-1106	RURAL				24:00:00	
154	MAPUSA	33KV Saligao	11KV Candolim church	1S10-1102	RURAL				24:00:00	
155	MAPUSA	33KV Saligao	11KV Shervani Calangute	1S10-1103	RURAL	3598	17	8040	23:55:41	M/T to close hilltop RMU , O/C Tripping due to Earth Fault, M/T to close hilltop RMU, M/T to cut creepers
156	MAPUSA	33KV Pale	11KV Nanus	1S14-1101	RURAL	1284	1	300	23:59:50	Trip on Earth Fault,Ambegal pale Faulty
157	MAPUSA	33KV Pale	11KV Kotumbi	1S14-1102	RURAL	215	1	2400	23:58:41	New Tishe RMU was not operating,rectified fault and feeder charged
158	MAPUSA	33/11 KV GIS CALANGUTE	11KV Tivaiwaddo	1S18-1108	RURAL	951	4	1860	23:59:00	Manuel tripped,by JE.Diksha to reolace Flora residency fuse, Manuel tripped, due to load shedding.
159	PANJIM	33KV Corlim	11KV Old Goa	2S01-1102	RURAL				24:00:00	
160	PANJIM	33KV Corlim	11KV Old Industry	2S01-1105	URBAN				24:00:00	
161	PANJIM	33KV Altinho	11KV Circuit House	2S04-1103	URBAN				24:00:00	
162	PANJIM	33KV Bambolim	11KV MES	2S05-1102	RURAL				24:00:00	
163	PANJIM	33KV Nagali hills(IT Park)	11KV OITIYANT	2S07-1103	URBAN				24:00:00	
164	PANJIM	33KV Colony	11KV Rajiv Gandhi Kala Mandir	2S09-1106	URBAN	1366	1	240	23:56:00	Transient fault
165	PANJIM	33KV Curti	11KV Sarvoiverem	2S10-1104	RURAL	3350	13	5760	22:48:00	Transient fault & breakdown

166	MORMUGAO	33KV Majorda	11KV Duguem	3S05-1105	RURAL				24:00:00	
167	MORMUGAO	33KV Majorda	11KV Nuvem	3S05-1106	RURAL				24:00:00	
168	MORMUGAO	33KV Bogda	ANTARTICA -Headland II	3S06-1104	URBAN	1659	10	9780	23:35:20	1) 33KV Incomer II supply failed, supply failed from Sancoale S/S, 2) 33KV Incomer II supply failed, change over done and load shifted to incomer I, 3) 33KV Incomer II supply failed, supply failed from Sancoale S/S, 4) 33KV Incomer II supply failed, supply failed from Sancoale S/S, 5) 33KV Incomer II supply failed, supply failed from Sancoale S/S, 6) 33KV Incomer II supply failed, shutdown taken by Kadamba sub station to replace jumper, 7) 33KV Incomer II supply failed, supply failed from Sancoale S/S, 8)33KV Incomer II supply failed, PTR-3 LA faulty supply failed from Sancoale sub station, 9) 33KV Incomer I supply failed, 110KV failure from Ponda 10) 33KV Incomer II supply failed on earth fault, On inspection found 33KV lightening arrestor failed in substation yard so the same is replaced
169	MORMUGAO	33KV Bogda	MASJID	3S06-1105	RURAL	2301	12	4680	23:51:01	1) Feeder tripped on inst. E/F, feeder charged and stood ok, line patrolling done no fault was traced 2) 33KV Incomer I supply failed, supply failed from Verna substation, 3) 33KV Incomer I supply failed, supply failed from Verna substation, 4) 33KV Incomer I supply failed, supply failed from Verna substation, 5) 33KV Incomer I supply failed, supply failed from Verna substation, 6) 33KV Incomer I supply failed, supply failed from Verna substation, 7) 33KV Incomer I supply failed, supply failed from Verna substation, 8) 33KV Incomer I supply failed, supply failed from Verna substation, 9) 33KV Incomer I supply failed, supply failed from Verna substation, 10) 33KV Incomer I supply failed, supply failed from Verna substation, 11) 33KV Incomer I supply failed, supply failed from Verna substation, 12) 33KV Incomer I supply failed, 110KV failure from Ponda
170	MARGAO	33KV KRC	11KV Navelim	4S05-1101	RURAL	3778	10	20640	23:25:36	Manually tripped on request of M/S Pristine Engineering Services for servicing of breakerConductor snapped at NalandaM/T for tree cuttingTo cut creepersJumper cut at Tulsi AB switchM/T to attend jumperJumper cut at Dyna AB switchTree branch fallen on line
171	MARGAO	33KV KRC	11KV Mandopa	4S05-1102	RURAL	5308	3	2400	23:46:40	To remove creepers near Mandopa Bridge, M/T for tree cutting, Shutdown taken by LT staff to attend fuse
172	MARGAO	33KV Benaulim	11KV Betal Betim	4S07-1103	RURAL				24:00:00	
173	MARGAO	33KV Velim	11KV Kumbia bhat	4S10-1103	RURAL				24:00:00	
174	MARGAO	33KV Shigao	11KV Mollem	4S14-1102	RURAL	961	4	20730	23:48:30	Shutdown taken for tree cutting
175	MAPUSA	33KV Pernem	11KV Keri	1S01-1106	RURAL	1869	7	13380	23:29:00	Conductor snapped at Konadi; To carryout tree prunning work at Devsu, Korgao; Availed shutdown for maintenance work
176	MAPUSA	33KV Tuem	11KV Mandrem	1S02-1102	RURAL	3830	21	801	23:30:00	Tree fallen on line, M/T to repair ABS in Satchebhatlle, To open bhandarwada tapping ABS, To attend open jumper at Bhumika temple palyem
177	MAPUSA	33KV Mapusa	11KV Industry	1S04-1101	URBAN	2056			24:00:00	

178	MAPUSA	33KV Mapusa	11KV Karaswada	1S04-1104	URBAN	3052			24:00:00	
179	MAPUSA	33KV Mapusa	11KV Parra	1S04-1113	RURAL	3764	2	7740	23:55:50	1. After sectionizing foult not found and supply restored. 2.Planned Shutdown Taken By Thivim Substation.
180	MAPUSA	33KV Bicholim	11KV Lamgao	1S05-1112	RURAL	859	4	5400	23:37:30	O/C, E/F, M/T for Tree cutting
181	MAPUSA	33KV Nachinola	11KV Pomburpa	1S06-1101	RURAL	1451	2	6600	23:56:27	1. Declared foulty on OC,Charged after opening Olalim Church RMU stood OK. 2. To closed Olalim RMU and open Cardo ,but Tripped again.
182	MAPUSA	33KV Porvorim	11KV Malim	1S09-1104	RURAL	857	3	240	23:59:52	E/F, O/C.
183	PANJIM	33KV EDC	11KV BAL BHARTI	2S02-1108	URBAN				24:00:00	
184	MORMUGAO	33KV Kadamba	11KV Waddem Lake	3S02-1104	URBAN	3152	4	4200	23:57:48	OCR, Vaddem lake AB switch opened n yard and charged.
185	MORMUGAO	33KV Sancoale	11KV Sesa Goa	3S03-1101	URBAN	1484	3	10080	23:54:35	As 11 KV Sesa Goa feeder was interlinked with 11KV Tata feeder &11 KV Line Jumper was opened on TATA feeder near Birla Masjid DTC, UG Cable faulty from RMU Rua de Maria To Shantadurga, To attend jumper
186	MORMUGAO	110/33/11 KV Verna	11KV SMARTLINK	3S04-1109	URBAN	123	17	12600	23:37:00	1) Manually Tripped by S/D-I, Verna, 2) Over current 3) Manually Tripped by Verna S/S Emgercey work
187	MARGAO	33KV Fatorda	11KV Gogol	4S02-1106	RURAL	5308			24:00:00	
188	MARGAO	33KV Aquem	11KV Davorlim	4S04-1106	RURAL	0	1	1200	23:40:00	Shutdown taken by KRC S/S staff to attend HT work. Load shifted to aquem sub station
189	MARGAO	33KV Nessai	11KV Chandor	4S06-1103	RURAL	3389	8	12900	23:33:08	Feeder tripped due to over current relay. Full Line Patrolling was done by the Staff and found that HT AB Switch was opened near Mahalaxmi Temple Feeder tripped due to over current relay. Tree branch was fallen on HT Line near Mashroom Garden Feeder Manually Tripped to attend jumper cut near Guirdolim Section Office Tripped on EFR. Section wise patrolling done upto moll area. Found one pin insulator faulty at Moll area
190	MARGAO	33KV Benaulim	11KV Mobor	4S07-1104	RURAL				24:00:00	
191	MARGAO	33KV Velim	11KV Assolna	4S10-1101	RURAL				24:00:00	
192	MARGAO	33KV Poinguinim	11KV Link line	4S12-1101	RURAL				24:00:00	
193	MARGAO	33KV Xelpem	11KV Dando	4S18-1105	RURAL				24:00:00	
194	MAPUSA	33KV Tuem	11KV Tuem	1S02-1103	RURAL	2145	0	0	24:00:00	

195	MAPUSA	220/33KV Thivim	11KV Power Grid	1S03-1103	RURAL	2259	6	14580	19:57:00	1. The feeder tripped on Earth fault.Top fitting dameged and touches to Vshap same was replaced and full feeder charged. 2. Feeder tripped on Over Current (RY Phase). During fault investigation, the Cococala AB Switch was opened and the feeder was test-charged, after which it remained healthy. Subsequently, the feeder was charged up to the Old Khadpani AB Switch. No visible fault was observed during the inspection. The feeder was test-charged again and was found to be holding satisfactorily. 3. Feeder tripped on Earth Fault. After patrolling and sectionalizing the feeder, an jumper found open on cutpoint near People High School. The same was attended and full feeder charged. 4. Feeder tripped on Over Current. After patrolling and sectionalizing the feeder, a jumper found open on cutpoint near IDC AB Switch . The same was attended and full feeder charged. 5. Feeder tripped on Sensitive Earth Fault. After patrolling and sectionalizing the feeder, a jumper found opened on cutpoint near Housing board. The same was attended and full feeder charged. 6. Feeder was manually tripped to open Cocola tapping AB Switch to carry out tree cutting work same AB Switch was closed and full feeder charged
196	MAPUSA	33KV Bicholim	11KV Pilgao	1S05-1104	RURAL	998	6	4080	23:48:42	O/C, E/F, M/T for Tree cutting
197	MAPUSA	33KV Bicholim	11KV Bordem	1S05-1109	URBAN	2655	4	3800	23:44:12	O/C, E/F, M/T for Tree cutting
198	MAPUSA	33KV Sanquelim	11KV Honda	1S08-1104	RURAL	574	3	19260	23:49:18	For tree cutting work and line maintenance.
199	MAPUSA	33KV Saligao	11KV Saligao	1S10-1104	RURAL	2694	4	480	23:59:45	O/C Tripping due to Earth Fault.
200	MAPUSA	33KV Candolim	11KV Sinquerim	1S12-1105	RURAL	2087	0	0	24:00:00	
201	MAPUSA	33KV Pale	11KV Barazen	1S14-1103	RURAL				24:00:00	
202	MAPUSA	33/11 KV GIS CALANGUTE	11KV Kamat	1S18-1107	RURAL	529	9	1320	23:59:17	Manuel tripped,due to safety purpuse, Manuel tripped, due to load shedding, Earth fault and over current
203	PANJIM	33KV EDC	11KV Ribandar	2S02-1102	URBAN				24:00:00	
204	PANJIM	33KV Campal	11KV Market	2S03-1101	URBAN	1762	1	1020	23:43:00	Tripped on O/C & E/F, Flashover at Greenland LBS
205	PANJIM	33KV Altinho	11KV Inox	2S04-1102	URBAN				24:00:00	
206	PANJIM	33KV Altinho	11KV Campal	2S04-1105	URBAN				24:00:00	
207	PANJIM	33KV Bambolim	11KV Merces	2S05-1104	RURAL				24:00:00	
208	PANJIM	33KV NIO	11KV Models	2S08-1101	URBAN				24:00:00	
209	PANJIM	33KV Curti	11KV Usgao	2S10-1102	RURAL	2896	9	3000	23:10:00	Transient Fault,Planed shutdown
210	PANJIM	33KV Madkai	11KV Madkai	2S15-1102	RURAL	2004	7	320	23:54:40	Breakdown/ transient Fault/Planned Maintenace/To servicing braker
211	MORMUGAO	110/33/11 KV Verna	11KV Cortalim	3S04-1107	RURAL	1410	27	65460	23:59:25	1)Earth fault and Over current 2) Manually Tripped by Sancoal SS
212	MARGAO	33KV Raia	11KV Santamol	4S01-1103	RURAL				24:00:00	
213	MARGAO	33KV Fatorda	11KV Chowgule College	4S02-1103	URBAN	3819	2	24360	20:37:00	Planned Power Outage on PTR-3 to Replace Bay Conductor at Substation Yard, Manually Tripped to attend Red Hot on R phase L.V Side of Power Transformer - III
214	MARGAO	33KV Monte Hill	11KV Hari Mandir-II	4S03-1108	URBAN	2332	5	10620	23:24:36	Flashover at Mendes Tower Transformer, Cable fault between sapna legacy to urban building , Substation yard AB Switch Maintenance

215	MARGAO	33KV Aquem	11KV Housing Board O/H	4S04-1103	URBAN				24:00:00	
216	MARGAO	33KV Aquem	11KV Margao III	4S04-1104	URBAN				24:00:00	
217	MARGAO	33KV Velim	11KV Chinchinim	4S10-1104	RURAL				24:00:00	
218	MARGAO	33KV Pontemol	11KV Dabal	4S13-1107	RURAL	2873	22	23160	23:47:06	Trasient trippings , Manual trippings , snapping of conductor , jumper opening , tree branches fell on line , I/C supply failure , broken of poles
219	MARGAO	220/33/11KV Xeldem	11KV Xelvona	4S15-1101	RURAL				24:00:00	
220	MAPUSA	33KV Pernem	11KV City	1S01-1103	RURAL	1488	3	19800	22:30:00	Gulmohar tree fallen on line at Surbanwada, Pernem; Maintenance work
221	MAPUSA	220/33KV Thivim	11KV Industrial Estate	1S03-1101	URBAN				24:00:00	
222	MAPUSA	33KV Nagoa	11KV Calangute	1S07-1101	RURAL				24:00:00	
223	MAPUSA	33KV Porvorim	11KV Sangolda	1S09-1105	RURAL	627	13	6840	23:56:19	E/F, O/C. Cable fault - Faulty portion isolated and supply restored.
224	MAPUSA	33KV Saligao	11KV Gaurawaddo	1S10-1109	URBAN	10	0	0	24:00:00	
225	MAPUSA	33KV Valpoi	11KV City New	1S11-1105	RURAL	6380	4	7200	23:30:00	UG cable termination , tree cutting
226	MAPUSA	33KV Sal	11KV Kasarpal	1S16-1103	RURAL	452	7	2100	23:55:00	O/C, E/F, M/T for Tree cutting
227	MAPUSA	33/11 KV GIS CALANGUTE	11KV Mark Memorial	1S18-1105	URBAN	456	5	5760	23:56:54	Manuel tripped, due to load shedding, O/C Tripping due to Earth Fault
228	PANJIM	33KV Campal	11KV St. Inez	2S03-1107	URBAN				24:00:00	
229	PANJIM	33KV Altinho	11KV Cabo	2S04-1112	URBAN				24:00:00	
230	PANJIM	33KV PILAR	11KV Batim	2S06-1103	RURAL				24:00:00	
231	PANJIM	33KV NIO	11KV NIO	2S08-1103	URBAN				24:00:00	
232	PANJIM	33KV Colony	11KV Bazaar	2S09-1101	URBAN				24:00:00	
233	PANJIM	33KV Bethora	11KV Industrial	2S13-1104	URBAN	421	4	540	23:51:00	Transient Fault,Planed shutdown
234	PANJIM	33KV Kundaim	11KV Kundaim	2S14-1104	RURAL	2501	7	9	23:59:51	Breakdown/ transient Fault/Planned Maintenace
235	MORMUGAO	33KV Kadamba	11KV Vasco city	3S02-1103	URBAN	1715	3	360	23:59:48	HTC Gomantak fuse blown.
236	MORMUGAO	33KV Sancoale	11KV Vasco-I	3S03-1103	URBAN	2369	12	74340	23:20:02	To attend jumper 3 nos hollant side tree fallen on wire,jumper touching pole due to rusting of metal part near naval museum, Jumper opened at cutpoint near substation,Coconut Palm leaf had fallen on 11KV line in Hollant., 11 KV Disc insulator was faulty in Zari.,Planned shutdown for trimming of trees and to make JIO Tower DP a cutpoint, feeder tripped on Sensitive E/F due to snapping of conductor, Feeder tripped on Sensitive E/F due to falling of coconut tree on line (Line snapped),Manually tripped to replace Hollant AB Switch pipe nut bolt, planned shut down for tree trimming at hollant AB switch was opened.
237	MORMUGAO	110/33/11 KV Verna	11KV Oxynitro	3S04-1110	RURAL	22	17	18900	23:59:50	1) Manually Tripped by S/D-I, Verna, 2) Earth fault 3) Manually Tripped by Verna S/S for maintenance work
238	MARGAO	33KV Fatorda	11KV Fatorda	4S02-1105	URBAN	3552	1	16800	19:20:00	Planned Power Outage on PTR-2 to Replace Bay Conductor at Substation Yard
239	MARGAO	33KV Monte Hill	11KV GVN2	4S03-1101	URBAN	1860	3	6420	23:24:20	Canara Bank Transformer BreakdownSubstation yard AB Switch Maintenance33KV incomming Margao Express - II Failed.
240	MARGAO	33KV Cuncolim	11KV IDC I	4S09-1102	RURAL				24:00:00	
241	MARGAO	33KV Velim	11KV Betul	4S10-1102	RURAL				24:00:00	
242	MARGAO	33KV Poinguinim	11KV Marli Tirval	4S12-1102	RURAL				24:00:00	
243	MARGAO	33KV Pontemol	11KV Town 1	4S13-1101	URBAN				24:00:00	
244	MARGAO	33KV Rivona	11KV Maina	4S16-1101	RURAL				24:00:00	
245	MAPUSA	33KV Nagoa	11KV Baga	1S07-1107	RURAL				24:00:00	
246	MAPUSA	33KV Porvorim	11KV Soccorro	1S09-1101	RURAL	784	1	120	23:59:56	E/F,

247	MAPUSA	33KV Saligao	11KV Industry O/H	1S10-1106	URBAN	2339	5	11400	20:50:00	1. Feeder tripped on RY Phase due to snapping of the 33 kV Bicholim-I conductor over the Industry O/H Feeder line. Jumper of 11KV Industru feeder open outside Station Cut point and feeder rest back feeded on 11KV Tivim Village Feeder. 2. Rejumpering of open Jumper on 11KV Industry OH Feeder. 3. Feeder was manually tripped to open Ghotnicho val tapping AB Switch to cut Creeper near Line same AB Switch was closed and full feeder charged. 4. Feeder tripped on Sensitive Earth Fault. After patrolling and sectionalizing the feeder, found Post insulator faulty of petrol pump DTC . The same was attended and full feeder charged. 5. Feeder was manually tripped to open Khanir tapping AB Switch to cut Creeper near Line same AB Switch was closed and full feeder charged.
248	MAPUSA	33KV Saligao	11KV Nerul	1S10-1108	RURAL	3701	7	2040	23:58:54	O/C Tripping due to Earth Fault,M/T fortree cutting
249	MAPUSA	220/33KV Amona	11 KV Pissurlem IDC	1S13-1104	RURAL	11	1	60	23:59:00	M/T for change over
250	MAPUSA	33/11 KV GIS CALANGUTE	11KV Shivam	1S18-1104	RURAL	1378	11	2640	23:58:35	over current and earth fault Earth fault,hard rock RMU opened and charged stood okay Manuel tripped,to charge RMU of hard rock hotel
251	PANJIM	33KV Corlim	11KV Molar	2S01-1106	RURAL	2162	1	1200	23:59:48	Jumper cut at cut point
252	PANJIM	33KV Campal	11KV City	2S03-1103	RURAL				24:00:00	
253	PANJIM	33KV Nagali hills(IT Park)	11KV STATUS	2S07-1104	URBAN				24:00:00	
254	PANJIM	33KV Colony	11KV Curti	2S09-1105	URBAN	746	25	3601	22:59:00	Transient fault
255	PANJIM	33KV Dharbandora	11KV Dharbandora	2S11-1104	RURAL	2456	53	33000	14:50:00	Transient Fault,Planed shutdown, pole breakdown due to falling of trees, conductor snapping
256	MORMUGAO	33KV Sancoale	11KV College	3S03-1107	RURAL				24:00:00	
257	MARGAO	33KV Benaulim	11KV Colva Exp	4S07-1107	URBAN				24:00:00	
258	MARGAO	220/33/11KV Xeldem	11KV Rivona	4S15-1102	RURAL	2528	123	54000	23:30:00	Because of birds and monkey activity in Rivona area and Failure of AB Cable termination kit.
259	MARGAO	33KV Rivona	11KV Colomba	4S16-1103	RURAL	316	50	18000	23:50:00	Due to frequent failure of AB cable termination kit and planned shutdown taken for tree cutting
260	MARGAO	33KV Xelpem	11KV Sanguem	4S18-1101	URBAN				24:00:00	
261	MAPUSA	33KV Tuem	11KV Ashvem Cable	1S02-1105	RURAL	89	-	-	24:00:00	-
262	MAPUSA	33KV Mapusa	11KV Anjuna	1S04-1106	RURAL	4950	2	13380	20:17:00	1. Load Shedding due to emergency Shutdown on 33KV Feeder for carrying out work at EHV Tivim Sub-station. 2. Load Shedding due to emergency Shutdown on 33KV Feeder's from EHV Tivim Sub-station. Reason: To attend Jumper of 33KV Incomer-II Isolator at Tivim Substation.

263	MAPUSA	33KV Mapusa	11KV Assagao	1S04-1110	RURAL	2825	5	22380	17:47:00	1. Feeder tripped on Over Current, Delayed due to Heavy rain feeder test charged stook ok no fault found. 2. Load Shedding due to emergency Shutdown on 33KV Feeder for carrying out work at EHV Tivim Sub-station. 3. Load Shedding due to emergency Shutdown on 33KV Feeder's from EHV Tivim Sub-station. Reason: To attend Jumper of 33KV Incomer-II Isolator at Tivim Substation. 4. Feeder was manually tripped to attend Red Hot on cable termination lug at Mapusa Sub-station. 5. Feeder was manually tripped to open Tale tapping AB Switch to dismental Old Panchayat transformer DP same AB Switch was closed and full feeder charged.
264	MAPUSA	33KV Bicholim	11KV Ladphem	1S05-1103	RURAL	511	5	2160	23:52:48	O/C, E/F, M/T for Tree cutting
265	MAPUSA	33KV Bicholim	11KV Narva	1S05-1106	RURAL	585	6	2880	23:52:00	O/C, E/F, M/T for Tree cutting
266	MAPUSA	33KV Nachinola	11KV Moira	1S06-1103	RURAL	3569	12	54300	08:55:00	1. Feeder manually tripped on the request of LT Staff, S/o Moira, to attend a bent 11 mtr RCC pole causing phase-to-phase conductor contact. The defect was rectified and Full feeder charged. 2. The feeder tripped on Over Current, the incomer pulled and patrolling was carried out. A huge tree was found to have fallen on the 11 kV Line near the Moira Crematorium, causing the fault. The outgoing AB Switch at the Nachinola Sub-station yard was kept open, and the damaged section was isolated by opening the jumper near the Crematorium. The feeder was subsequently charged and was found to be holding satisfactorily. 3. The jumper was found in contact with the conductor., same was attended and full feeder charged. 4. The feeder tripped on Sensitive Earth fault, after petrolling, GI pipe put for support service connection wire, was found in contact with the 11 kV line, same was removed and full feeder charged. 5. Feeder tripped on Over current Earth Fault, also power transformer pulled.Power Transformer Charged. Feeder Test Charging Delayed due to heavy rain and Wind. after opening Main Section AB Switch, Feeder tripped again on Over current. 6. Feeder tripped on Over current Earth Fault, after removing tree branch and creeper near main section the full feeder charged. 7. Feeder tripped on Over current Earth Fault. Feeder Test Charging Delayed due to heavy rain and Wind, No visible fault found after patroll. 8. Feeder tripped on Over Current. After patroling ans sectionalizing and opening Jaidev waddo tapping ,feeder charged. 9. After patrolling jaidev waddo tapping section, Pin insulator found faulty same was replaced and full feeder charged. 10. Feeder Manually tripped due to tree cutting work near Moira Panchayat. 11. Feeder was manually tripped to open Panari tapping AB Switch for tree-
267	MAPUSA	33KV Nachinola	11KV Bastora	1S06-1104	RURAL				24:00:00	
268	MAPUSA	33KV Sal	11KV Sal	1S16-1101	RURAL	797	4	4800	23:40:00	O/C, E/F, M/T for Tree cutting
269	PANJIM	33KV Corlim	11KV Dhulapi	2S01-1101	RURAL	1659	1	1200	23:59:48	Jumper cut at cut point
270	PANJIM	33KV EDC	11KV Vidyut Bhawan	2S02-1104	URBAN				24:00:00	
271	PANJIM	33KV Altinho	11KV Alcon	2S04-1104	URBAN				24:00:00	

272	PANJIM	33KV Bambolim	11KV Donapaula	2S05-1103	RURAL				24:00:00	
273	PANJIM	33KV Curti	11KV OPA	2S10-1103	RURAL				24:00:00	
274	PANJIM	33KV Kundaim	11KV Marcel	2S14-1102	RURAL	7853	16	36	23:59:24	Breakdown/ transient Fault/Planned Maintenace
275	PANJIM	33KV Madkai	11KV Undir	2S15-1101	RURAL	2015	4	326	23:54:34	Breakdown/ transient Fault/Planned Maintenace/To servicing braker
276	MORMUGAO	110/33/11 KV Verna	11KV Herald	3S04-1102	URBAN	84	17	19860	23:59:49	1) Earth fault 2) Manually Tripped by S/D-I, Verna
277	MORMUGAO	110/33/11 KV Verna	11KV Jordan	3S04-1105	URBAN	61	10	4620	23:59:58	1) Earth fault 2) Manual Tripping by S/D-I, Verna
278	MORMUGAO	33KV Majorda	11KV Ramesh Hotel	3S05-1101	URBAN				24:00:00	
279	MARGAO	33KV Raia	11KV Raia	4S01-1101	RURAL				24:00:00	
280	MARGAO	33KV Raia	11KV Rachol	4S01-1104	RURAL	1361	1	1800	23:30:00	East Damon DTC. HT jumper cut fault attended and DTC charged.
281	MARGAO	33KV Fatorda	11KV Old market U/G	4S02-1102	URBAN	4176	1	16800	19:20:00	Planned Power Outage on PTR-2 to Replace Bay Conductor at Substation Yard
282	MARGAO	33KV Aquem	11KV Housing Board U/G	4S04-1102	RURAL				24:00:00	
283	MARGAO	33KV Aquem	11KV Malbhat	4S04-1105	URBAN	2411	3	22560	21:54:40	Flashover observed at Fire Station, Oil factory, Section wised charged by 07:40 , Flashover due to moisture, 33KV incomming Failed.
284	MARGAO	33KV Nessai	11KV MIE	4S06-1101	RURAL				24:00:00	
285	MARGAO	33KV Carmona	11KV XIRO	4S08-1103	RURAL				24:00:00	
286	MARGAO	33KV Canacona	11KV Shristhal	4S11-1102	RURAL				24:00:00	
287	MARGAO	33KV Canacona	11KV Kindlem	4S11-1103	RURAL				24:00:00	
288	MARGAO	33KV Pontemol	11KV Town 2	4S13-1106	URBAN				24:00:00	
289	MARGAO	33KV Pontemol	11KV HODAR	4S13-1109	RURAL				24:00:00	
290	MARGAO	33KV Xelpem	11KV Barazan	4S18-1103	RURAL	1247	16	84180	23:59:02	Due to frequent failure of AB Cable terminations kit, AB Cable puncture,tree fallen on line,Attended the same and suply normalised
291	MAPUSA	33KV Bicholim	11KV Assnora	1S05-1110	RURAL	1963	5	7290	23:35:42	O/C, E/F, M/T for Tree cutting
292	MAPUSA	33KV Nagoa	11KV Sauntawada	1S07-1102	RURAL				24:00:00	
293	MAPUSA	33KV Nagoa	11KV Dharwadkar	1S07-1108	RURAL				24:00:00	
294	MAPUSA	33KV Porvorim	11KV Pundalic Nagar	1S09-1102	RURAL	828	7	1860	23:59:00	M/T, E/F, O/C. Gaurding snapped same was restrung, Testing charging of RMU.
295	MAPUSA	220KV Amona	11KV Amona Marcel	1S13-1103	URBAN				24:00:00	
296	PANJIM	33KV Corlim	11KV Khumarjau	2S01-1107	RURAL	3378	4	15960	23:59:44	1. Shutdown taken to repiar Tonca AB Switch. 2.11KV Khumbharjua Feeder was faulty at 14.42 hrs. After sectionalising it was found that Cupa section faulty. Full feeder charged at 14.56 hrs except Cupa Section. After petrolling one bird found on line. The same was removed and Cupa Section charged. 3. Tripped on Earth fault Realay. 4. Tripped on EFR.
297	PANJIM	33KV Corlim	11KV Diwar	2S01-1109	RURAL	4604	2	7260	23:59:53	1.Tripped on O/C, Tree branch fallen on line AatDock near Diwar. 2. Tripped on Earth fault Relay.
298	PANJIM	33KV EDC	11KV Ginger	2S02-1106	URBAN				24:00:00	
299	PANJIM	33KV Campal	11KV LA-Campal	2S03-1102	URBAN				24:00:00	
300	PANJIM	33KV Campal	11KV Indoor Stadium	2S03-1104	URBAN				24:00:00	
301	PANJIM	33KV Bambolim	11KV Chimbel	2S05-1106	RURAL				24:00:00	
302	PANJIM	33KV NIO	11KV Rajbhawan	2S08-1104	URBAN				24:00:00	
303	PANJIM	33KV Colony	11KV Ponda-I	2S09-1104	URBAN	3893	3	480	23:52:00	Transient fault
304	PANJIM	33KV Dharbandora	11KV Bondla	2S11-1103	RURAL	3145	65	58020	07:53:00	Transient Fault,Planed shutdown for changing supply fromOH to UG network, Xmer erection, tree branches fallen on line
305	PANJIM	33KV Kundaim	11KV Industry III	2S14-1105	URBAN	131	2	2	23:59:58	Breakdown/ transient Fault/Planned Maintenace/

306	MORMUGAO	33KV Harbour	11KV Vasco-I	3S01-1102	URBAN				24:00:00	
307	MORMUGAO	33KV Sancoale	11KV Industrial	3S03-1108	URBAN				24:00:00	
308	MARGAO	33KV Fatorda	11KV Borda	4S02-1104	URBAN	5479	1	2880	23:12:00	Flashover on Norberts Gym TLBS
309	MARGAO	33KV Aquem	11KV AQUEM BAIXO	4S04-1108	URBAN	562	1	1020	23:43:00	33KV incomming Failed.
310	MARGAO	33KV Benaulim	11KV Benaulim	4S07-1101	RURAL				24:00:00	
311	MARGAO	33KV Benaulim	11KV Trinity	4S07-1106	RURAL				24:00:00	
312	MARGAO	220/33/11KV Xeldem	11KV Quepem	4S15-1103	URBAN	4866	40	7200	23:56:00	Because of Conductor snapped and birds and monkey activity in ambaulim area
313	MARGAO	33KV Rivona	11KV Sulcorna	4S16-1102	RURAL	388	70	50400	23:32:00	Due to frequent failure of AB cable termination kit and planned shutdown taken for tree cutting
314	MARGAO	33KV Waddem	11KV Netravali	4S17-1102	RURAL	214	1	108840	23:59:02	Tripped on OCR,3 nos 9 mtr pole damaged at kadel,due to falling of tree attended And Supply Normalised
315	MAPUSA	220/33KV Thivim	11KV Sirsaim	1S03-1106	RURAL	2211	4	22080	17:52:00	1. The feeder tripped on Over Current,Tree fallen on line same was removed and feeder charged. 2. The feeder was manually tripped to erection of brocken stay wire for 2 nos. of 11Mtr pole. 3. Feeder Manually tripped to open Seza Tapping AB Switch to cut Coconut leaves touching to line same AB Switch was closed and full feeder charged. 4. Feeder tripped on E/F after sectionalizing the feeder Post Insulator of AB Switch on Naik waddo DTC found faulty, same was attended and full feeder charged.
316	MAPUSA	33KV Bicholim	11KV ADVALPAL	1S05-1105	RURAL	558	3	4680	23:34:00	O/C, E/F, M/T for Tree cutting
317	MAPUSA	33KV Bicholim	11KV City	1S05-1108	RURAL	1920	4	2260	23:50:35	O/C, E/F, M/T for Tree cutting
318	MAPUSA	33KV Bicholim	11KV Kudchirem	1S05-1111	RURAL	733	9	6600	23:47:47	O/C, E/F, M/T for Tree cutting
319	MAPUSA	33KV Nachinola	11KV Aldona OH	1S06-1102	RURAL				24:00:00	
320	MAPUSA	33KV Sanquelim	11KV Amona	1S08-1103	URBAN	4194	2	18000	23:50:00	Line Maintenance and tree pruning work,Urgent AB Switch Repair Works on 11 kV line.
321	MAPUSA	33KV Porvorim	11KV RND	1S09-1103	RURAL	931	4	420	23:59:46	E/F, O/C.
322	MAPUSA	33KV Porvorim	11KV Chogum	1S09-1110	RURAL	716	1	120	23:59:56	M/T, Load shifting.
323	PANJIM	33KV Corlim	11KV Carambolim	2S01-1104	RURAL	3283	3	10020	23:59:50	1. Tripped on Earth fault Relay as jumper cut in Sub Station yard. 2.Manual Tripping to remove cripper. 3.Jumper cut at cut point
324	PANJIM	33KV Campal	11KV Adarsh	2S03-1105	URBAN				24:00:00	
325	PANJIM	33KV Altinho	11KV National	2S04-1101	URBAN	1244	1	480	23:52:00	Tripped on O/C & E/F, Bombay Bazaar Int LBS Flashover
326	PANJIM	33KV Altinho	11KV Manoshanti	2S04-1106	URBAN				24:00:00	
327	PANJIM	33KV NIO	11KV NIO Colony	2S08-1105	URBAN				24:00:00	
328	PANJIM	33KV Colony	11KV Khadpabandh	2S09-1103	URBAN	4668	2	180	23:57:00	Transient fault
329	PANJIM	33KV Curti	11KV Curti	2S10-1108	URBAN				24:00:00	
330	PANJIM	33KV Kundaim	11KV Industry II	2S14-1106	URBAN				24:00:00	
331	PANJIM	33KV Madkai	11KV Industry II	2S15-1105	URBAN	274	13	506	23:51:34	Breakdown/ transient Fault/Planned Maintenace/To servicing braker
332	PANJIM	33KV Kundaim	Undergound 4	2S14-1109	URBAN	67	2	4	23:59:56	Breakdown/ transient Fault/Planned Maintenace/To servicing braker
333	PANJIM	33KV Kundaim	Kunkolim-Keri	2S14-1107	RURAL	1386	34	64	23:58:56	Breakdown/ transient Fault/Planned Maintenace/
334	MORMUGAO	33KV Harbour	11KV Mangor	3S01-1104	URBAN	5808	17	44040	23:37:06	Navy gate DTC found faulty, multiple transformer centre fuse blown causing tripping on test charge.
335	MORMUGAO	33KV Sancoale	11KV Dabolim	3S03-1109	URBAN	1605	2	5760	23:56:54	Feeder was manually tripped to cut the tree which was under 11 KV Vasco-II & 11 KV Dabolim Double circuit

336	MORMUGAO	110/33/11 KV Verna	11KV Industrial	3S04-1103	URBAN	50	4	1020	23:59:59	1) Earth fault
337	MORMUGAO	110/33/11 KV Verna	11KV Tulip	3S04-1112	URBAN	38	8	13440	23:59:53	1) Manually Tripped by S/D-I, Verna, 2) Over current 3) Manually Tripped by Verna S/S for maintenance work
338	MORMUGAO	33KV Bogda	Brahmasthal - vasco 1	3S06-1102	URBAN	4244	10	9780	23:23:54	1) 33KV Incomer II supply failed, supply failed from Sancoale S/S, 2)33KV Incomer II supply failed, change over done and load shifted to incomer I, 3) 33KV Incomer II supply failed, supply failed from Sancoale S/S, 4) 33KV Incomer II supply failed,supply failed from Sancoale S/S, 5) 33KV Incomer II supply failed, supply failed from Sancoale S/S, 6) 33KV Incomer II supply failed, shutdown taken by Kadamba sub station to replace jumper, 7) 33KV Incomer II supply failed,supply failed from Sancoale S/S, 8) 33KV Incomer II supply failed, PTR-3 LA faulty supply failed from Sancoale sub station, 9) 33KV Incomer I supply failed, 110KV failure from Ponda, 10) 33KV Incomer II supply failed on earth fault, On inspection found 33KV lightening arrestor failed in substation yard so the same is replaced
339	MORMUGAO	33KV Bogda	HARBOUR	3S06-1103	URBAN	953	12	4740	23:48:00	1) Feeder tripped on inst. E/F, feeder charged and stood ok, line patrolling done no fault was traced 2)33KV Incomer I supply failed, supply failed from Verna substation, 3) 33KV Incomer I supply failed, supply failed from Verna substation, 4) 33KV Incomer I supply failed, supply failed from Verna substation, 5) 33KV Incomer I supply failed, supply failed from Verna substation, 6)33KV Incomer I supply failed, supply failed from Verna substation, 7) 33KV Incomer I supply failed, supply failed from Verna substation, 8) 33KV Incomer I supply failed, supply failed from Verna substation, 9) 33KV Incomer I supply failed, supply failed from Verna substation, 10) 33KV Incomer I supply failed, supply failed from Verna substation, 11) 33KV Incomer I supply failed, supply failed from Verna substation, 12) 33KV Incomer I supply failed, 110KV failure from Ponda
340	MARGAO	33KV Raia	11KV Loutalim	4S01-1102	RURAL	1872	1	3600	23:00:00	Manually tripped to attended 11 KV breaker at Raia SS. TNC switch found faulty during inspection by Pristine Engineering services same was replaced
341	MARGAO	33KV Monte Hill	11KV Adarsh	4S03-1104	URBAN	2536	3	4920	23:32:40	Substation yard AB Switch Maintenance, 33KV incomming Margao Express - II Failed.
342	MARGAO	33KV Nessai	11KV Paroda	4S06-1102	RURAL	2071	6	6840	23:41:00	M/T on the request of LT staff to repair AB switch of Chamunda transformerM/T for tree cuttingTripped on EFR. Section wise patrolling done upto Sarzora AB switch. Found one jumper cut on Sarzora AB switchM/T on request by LT staff to work on LT line as the pole was LT and HT common poleTripped on OCR
343	MARGAO	33KV Benaulim	11KV Varca	4S07-1105	RURAL				24:00:00	
344	MARGAO	33KV Pontemol	11KV Kalay	4S13-1104	RURAL	177	8	20940	23:48:24	Trasient trippings , Manual trippings , snapping of conductor , jumper opening , tree branches fell on line , I/C supply failure , broken of poles

345	MARGAO	220/33/11KV Xeldem	11KV Assolda	4S15-1104	RURAL	1695	10	2580	23:58:36	Because of Conductor snapped and Pin insulator Faulty
346	MARGAO	33KV Waddem	11KV Bhati	4S17-1101	RURAL	635	1	11760	23:59:00	Due to failure of AB Cable terminations kit,2 nos Termination KIT Replaced,Cable Insulation fault attended, and supply normalised
347	MAPUSA	33KV Sanquelim	11KV Karapur	1S05-1102	RURAL	3080	1	480	23:59:44	Lalbag Transformer HG fuse blown off,LA was faulty
348	MAPUSA	33KV Pale	11KV Guleli	1S14-1104	RURAL	364	1	2100	23:58:50	Manually trip due to L.T conductor snapped at Paikul
349	MAPUSA	33KV Sanquelim	11 KV Keri	1S08-1106	RURAL	2376	1	2400	23:58:41	AB Cable faulty
350	MAPUSA	33KV Mapusa	11KV Canca	1S04-1110	RURAL	964	1	5640	23:56:58	Planned Shutdown Taken By Thivim Substation.
351	MAPUSA	33KV Saligao	11KV Industry Cable 1	1S10-1112	RURAL	31	0	0	24:00:00	
352	MAPUSA	33KV Saligao	11KV Industry Cable 2	1S10-1113	RURAL	23	1	1740	23:59:04	O/C Tripping due to Earth Fault,M/T to attend red hot
353	MAPUSA	33KV Candolim	11KV Kamat	1S12-1104	RURAL	1001	10	2820	23:58:29	Manually tripped to charge RMU of Viva Goa TC, Tripping due to Earth Fault, Manual trip to change Viva Goa RMU fuse plate
354	MAPUSA	33KV Saligao	11KV Kegdevlim	1S10-1114	RURAL	583	4	600	23:59:41	, O/C Tripping due to Earth Fault
355	MAPUSA	33KV Candolim	11KV Marquis waddo	1S12-1107	RURAL	561	9	4740	23:57:27	tweek fallen on oh line near dp structure, O/C Tripping due to Earth Fault,Manual trip – Removal of temporary earth. Manual trip– Charging of feeder
356	MAPUSA	33KV Candolim	11KV Tarcar	1S12-1102	RURAL	1067	0	0	24:00:00	
357	MAPUSA	33KV Saligao	11KV Urja industry	1S10-1111	RURAL	29	0	0	24:00:00	