11 KV Feeder Outage for the Month of August 2026

Sr No	Town Name	Substation	Feeder Name	Feeder Code	Rural/Urban	No.Of Consumers	No.Of Outages	Duration Of Outage (Sec)	Average Hours of Steady Supply	Reason for power disruptions
1	MAPUSA	220/33KV Thivim	11KV Thivim Village	1S03-1105	RURAL	2165	7	18000	23:17:08	1. Feeder was manually tripped to open Fukat waddo tapping AB Switch to carryout tree cutting work same AB Switch was closed and full feeder charged 2. Feeder was manually tripped to open Ground tapping AB Switch to carryout tree cutting work same AB Switch was closed and full feeder charged. 3. Feeder was manually tripped to open Main section AB Switch for restringing of the loose HT line same AB Switch was closed and full feeder charged. 4. Feeder was manually tripped due to an unbalanced load on the 11 kV Tivim Village Feeder. After patrolling found jumper open at main section AB Switch, same was attended and full feeder charged. 5. Feeder tripped on Sensitive Earth Fault. After opening Madel AB Switch, Feeder holding. 6. After patrolling and sectionalizing,Madel AB Switch Closed & test charged feeder holding, no fault found 7. Feeder was manually tripped to open Compund section AB Switch to restringe gurding near Major bakery Tivim.
2	MAPUSA	33KV Bicholim	11KV MAYEM	1S05-1107	RURAL	2471	1	1770	23:38:50	Insulator failure
3	MAPUSA	33KV Sanquelim	11KV Sanquelim	1S08-1102	URBAN	4253	0	0	24:00:00	Nil
4	MAPUSA	33KV Porvorim	11KV Porvorim Bazar	1S09-1109	RURAL	2602	0	0	24:00:00	NIL
5	MAPUSA	33KV Porvorim	Audit bhavan	1S09-1112	URBAN	1580	1	3540	23:58:06	jumper opened
6	MAPUSA	33KV Valpoi	11KV Bhironda	1S11-1101	RURAL	600	6	24960	22:50:40	Tree fallen , M/T for change over, 33KV line fault
7	MAPUSA	33KV Candolim	11KV Candolim	1S12-1103	RURAL	2097	4	4320	23:57:41	Manual trip for cable jointing near Whispering Palm Hotel,Shutdown taken at Nachinola SS on Porvorim I & II Circuits,Manual trip for maintenace of control panel by M/S Ashida control panels
8	PANJIM	33KV Nagali hills(IT Park)	11KV BSNL	2S07-1105	URBAN				24:00:00	
9	PANJIM	33KV Madkai	11KV Industry I	2S15-1104	URBAN	71	11	4440	23:58:46	Breakdown/ transient Fault/Planned Maintenace
10	MORMUGAO	33KV Bogda	HEADLAND	3S06-1101	URBAN	1921	9	4320	21:00:00	1) 33KV Incomer I supply failed, supply failed from Verna substation, 2) 33KV Incomer I supply failed, supply failed from Verna substation, 3)33KV Incomer I supply failed from Verna substation, 4) 33KV Incomer I supply failed, supply failed from Kadamba substation, 5) 33KV Incomer I supply failed, supply failed from Kadamba substation, 6) 33KV Incomer I supply failed, supply failed from Verna substation, 7)33KV Incomer I supply failed from Verna substation, 8) 33KV Incomer I supply failed, due to lightening arrestor failed in sub station yard 9) Feeder manually tripped to replace 33 KV lightening arrestor at Bogda sub station yard.
11	MARGAO	33KV Monte Hill	11KV Hari Mandir	4S03-1105	URBAN		3	6060	23:26:20	Flashover at Chamundi Transformer, Shutdown taken to take nameplate details of CT/PT in yard
12	MARGAO	33KV Aquem	11KV Khareband	4S04-1101	URBAN				24:00:00	
13	MARGAO	33KV Carmona	11KV Zalor	4S08-1101	RURAL				24:00:00	
14	MARGAO	33KV Cuncolim	11KV Dharmapur	4S09-1106	RURAL				24:00:00	
15	MARGAO	33KV Pontemol	11KV Bansai	4S13-1105	RURAL				24:00:00	
16	MAPUSA	33KV Mapusa	11KV Althino	1S04-1105	URBAN	3524	0	0	24:00:00	NIL
17	MAPUSA	33KV Mapusa	11KV Siolim	1S04-1112	RURAL	4985	6	26	23:30:00	E/F D/F, flashover occurred in 3 way RMU at Fernandeswada
18	MAPUSA	33KV Nachinola	11KV Aldona UG	1S06-1105	RURAL	1598	1	3840	23:57:56	MT Shutdown taken to attend cut jumper on 33kv Porvorim-I & II at Nachinola Substatation & Charged.
19	MAPUSA	33KV Nagoa	11KV AGARWADDO	1S07-1109	RURAL				24:00:00	
20	MAPUSA	33KV Saligao	11KV Betim	1S10-1105	RURAL	3218	1	3420	23:58:10	Shutdown taken at Nachinola SS on Porvorim I & II Circuits
21	MAPUSA	33 KV Anjuna	11KV Starco	1S15-1103	RURAL				24:00:00	

22	PANJIM	33KV Corlim	11KV New Ind.Estate	2S01-1103	URBAN				24:00:00	
23	PANJIM	33KV EDC	11KV Patto-Plaza	2S02-1103	URBAN				24:00:00	
24	PANJIM	33KV Bambolim	11KV Siridao	2S05-1101	RURAL				24:00:00	
25	PANJIM	33KV Nagali hills(IT Park)	11KV Adraar	2S07-1101	URBAN				24:00:00	
26	PANJIM	33KV Nagali hills(IT Park)	11KV CARANZALEM	2S07-1102	URBAN				24:00:00	
27	PANJIM	33KV Curti	11KV Shanti Nagar	2S10-1105	URBAN	5169	3	64800	06:00:00	Incoming supply failed from 220KV S/S, Instructed to trip main RMU Shantinagar & to charge both Usgao & Farmagudi. Charged ok. 6.3 MVA tripped, Faulty, Bhagwati TC cable fault ,Told to trip RMU Rajangad ABS, closed and backfeed from Kala Mandir feeder, Shutdown from 220KV S/S for panel servicing and also to put lugs at 6.3 MVA transformer and As per instruction 220 KV S/S due to cable work. Shantinagar RMU Tripped and supply restored through backfeed.
28	PANJIM	33KV Kundaim	11KV Mardol	2S14-1101	RURAL	4225	22	5520	23:59:55	Breakdown/ transient Fault/Planned Maintenace/
29	MORMUGAO	110/33/11 KV Verna	11KV IFB	3S04-1104	URBAN	44	2	24300	23:46:56	tree cutting
30	MARGAO	33KV Benaulim	11KV Colva	4S07-1102	RURAL				24:00:00	
31	MARGAO	33KV Velim	11KV Dramapur	4S10-1105	RURAL				24:00:00	
32	MARGAO	33KV Canacona	11KV Agonda	4S11-1101	RURAL				24:00:00	
33	MARGAO	33KV Canacona	11KV Gaondongri	4S11-1104	RURAL				24:00:00	
34	MARGAO	33KV Pontemol	11KV Kakoda	4S13-1108	URBAN				24:00:00	
35	MARGAO	33KV Shigao	11KV Dhat	4S14-1103	RURAL				24:00:00	
36	MARGAO	33KV Xelpem	11KV Ponsamol	4S18-1102	RURAL				24:00:00	
37	MAPUSA	220/33KV Thivim	11KV Industrial Estate I (U/G)	1S03-1102	RURAL					
38	MAPUSA	33KV Mapusa	11KV Guirim	1S04-1109	RURAL	3359	1	2220	23:58:48	MT,for safety purpose as 11KV Assagao Feeder was declared foulty.(11kv Assagoa Feeder partaions to S/D-II,Div-XVII,Mapusa)
39	MAPUSA	33KV Bicholim	11KV Karapur	1S05-1102	RURAL				24:00:00	
40	MAPUSA	33KV Nagoa	11KV Nagoa	1S07-1104	RURAL				24:00:00	
41	MAPUSA	33KV Porvorim	11KV Housing board	1S09-1106	RURAL				24:00:00	
42	MAPUSA	33KV Porvorim	Devashri Feeder	1S09-1113	URBAN				24:00:00	
43	MAPUSA	33KV Valpoi	11KV Nagargao (New)	1S11-1104	RURAL				24:00:00	
44	MAPUSA	220KV Amona	11KV Maina	1S13-1101	RURAL				24:00:00	
45	MAPUSA	33 KV Anjuna	11KV chapora	1S15-1104	URBAN	1268	1	2040	23:26:00	Feeder tripped on Earth Fault. After sectionalizing the feeder, it was found that the 400 kVA transformer had failed. The transformer RMU breaker was opened and full feeder charged.
46	MAPUSA	33KV Sal	11KV Mencurem	1S16-1104	RURAL	372	8	24400	23:09:10	Tree fallen , M/T for change over, AB cable faulty
47	MAPUSA	33/11 KV GIS CALANGUTE	11KV Maria Rosa	1S18-1101	RURAL				24:00:00	
48	MAPUSA	33/11 KV GIS CALANGUTE	11KV Weena	1S18-1106	RURAL				24:00:00	
49	PANJIM	33KV Campal	11KV Ideal School	2S03-1106	URBAN				24:00:00	
50	PANJIM	33KV NIO	11KV Odxel	2S08-1102	URBAN				24:00:00	
51	PANJIM	33KV Dharbandora	11KV Sonarbag	2S11-1101	RURAL	1049	85	29400	15:50:00	Transient Fault, Breakdown, Planned Shut down
52	PANJIM	33KV Bethora	11KV Bonbag	2S13-1103	RURAL	1181	1	120	23:58:00	Transient Fault,
53	PANJIM	33KV Kundaim	11KV Industry I	2S14-1103	URBAN	244	4	4440	23:58:46	Breakdown/ transient Fault/Planned Maintenace/
54	MORMUGAO	33KV Harbour	11KV Vasco city	3S01-1105	URBAN	1610	4	10500	23:54:32	Manually tripped for replacement of burnt AB switch outgoing jumper of Khalap Mansion T/C taken by LT staff
55	MORMUGAO	33KV Sancoale	11KV Sicgil	3S03-1104	RURAL	534	1	3780	23:57:58	Feeder triped on E/F

56	MORMUGAO	110/33/11 KV Verna	11KV Quellosim	3S04-1111	RURAL	-	9	10680	23:54:15	Feeder faulty
57	MARGAO	33KV Cuncolim	11KV Balli	4S09-1103	RURAL				24:00:00	
58	MARGAO	33KV Poinguinim	11KV Khotigao	4S12-1103	RURAL				24:00:00	
59	MAPUSA	220/33KV Thivim	11KV Tivim	1S03-1108	RURAL				24:00:00	
60	MAPUSA	33KV Nagoa	11KV Arpora	1S07-1105	RURAL	2209	1	5400	23:57:06	M.T, as for safety purpose, to attend foulty Post Insulator on interlinking AB Switch of 11kv Arpora Feeder and 11kv Agarwado Feeder,11kv Agarwado Feeder partains to S/D-IV,Div-VI,Mapusa.
61	PANJIM	33KV EDC	11KV Kanaka	2S02-1107	URBAN				24:00:00	
62	PANJIM	33KV Bambolim	11KV Santacruz	2S05-1105	RURAL				24:00:00	
63	PANJIM	33KV Nagali hills(IT Park)	11KV MANIPAL	2S07-1106	URBAN				24:00:00	
64	PANJIM	33KV NIO	11KV Alto-Nagali	2S08-1106	URBAN				24:00:00	
65	PANJIM	33KV Colony	11KV Ponda II	2S10-1101	URBAN				24:00:00	
66	PANJIM	33KV Curti	11KV Ponda II	2S10-1101	URBAN				24:00:00	
67	PANJIM	33KV Shiroda	11KV Shiroda Bazar	2S12-1102	RURAL	2131	6	600	23:58:24	transient fault
68	MORMUGAO	33KV Harbour	11KV Harbour	3S01-1101	URBAN				24:00:00	
69	MORMUGAO	110/33/11 KV Verna	11KV Lokmat	3S04-1108	URBAN	131	17	26460	23:45:46	Feeder faulty
70	MORMUGAO	33KV Majorda	11KV Utorda	3S05-1103	RURAL	2079	2	5160	23:58:44	To attend jumper
71	MORMUGAO	33KV Majorda	11KV Arrosim	3S05-1104	RURAL	1563	3	7200	23:58:00	To attend jumper
72	MARGAO	33KV Aquem	11KV KHAREBAND II	4S04-1109	RURAL		3	1260	23:53:00	Incoming supply (Margao Express I) failed from Xeldem.
73	MARGAO	33KV KRC	11KV MES	4S05-1103	RURAL		1	600	23:50:00	Incoming supply (Margao Express I) failed from Xeldem.
74	MARGAO	33KV Carmona	11KV Cavellossim	4S08-1104	RURAL				24:00:00	
75	MARGAO	33KV Cuncolim	11KV Pattem	4S09-1107	RURAL				24:00:00	
76	MARGAO	33KV Canacona	11KV Palolem	4S11-1105	URBAN				24:00:00	
77	MAPUSA	33KV Mapusa	11KV Market	1S04-1108	URBAN				24:00:00	
78	MAPUSA	33KV Bicholim	11KV IDC	1S05-1101	RURAL	268	2	3600	23:30:00	Tree fallen , M/T
79	MAPUSA	33KV Nagoa	11KV Parra	1S07-1103	RURAL				24:00:00	
80	MAPUSA	33KV Porvorim	11KV Torda	1S09-1107	RURAL				24:00:00	
81	MAPUSA	33KV Porvorim	Highland Villa	1S09-1114	URBAN	790	1	2100	23:58:52	Flashed over in Metering Cubicle
82	MAPUSA	220KV Amona	11KV Navelim	1S13-1102	RURAL				24:00:00	
83	MAPUSA	33/11 KV GIS CALANGUTE	11KV Calculo	1S18-1102	RURAL				24:00:00	
84	PANJIM	33KV EDC	11KV Neugi Nagar	2S02-1105	URBAN				24:00:00	
85	PANJIM	33KV Altinho	11KV Lydia Garden	2S04-1110	URBAN				24:00:00	
86	PANJIM	33KV NIO	11KV Taligao	2S08-1108	URBAN				24:00:00	
87	PANJIM	33KV Bethora	11KV Nirankal	2S13-1102	RURAL	2389	5	1680	23:54:24	transient fault
88	MORMUGAO	33KV Kadamba	11KV New Waddem	3S02-1101	URBAN	5071	5	27900	23:45:29	Tripped on OCR. Half feeder charged after patrolling. Line Snapped near PWD water tank near railway overbridge.
89	MORMUGAO	33KV Sancoale	11KV Cortalim	3S03-1105	RURAL	1833	6	7560	23:55:56	To attend snapped jumper, Manual Tripping for testing of relay & CT's behind 11 KV Cortalim feeder as per MRT request, Feeder manually tripped, to remove snapped guarding wire near St. joseph vaz church, Feeder manually tripped, to remove snapped guarding wire near shindolim
90	MARGAO	33KV Monte Hill	11KV Lohia	4S03-1103	URBAN		3	3300	23:41:40	Shutdown taken to take nameplate details of CT/PT in yard, Transformer 3 Manually tripped to attend Red Hot at Transformer 11KV Side
91	MARGAO	33KV KRC	11KV Navelim UG	4S05-1105	URBAN		5	16980	23:03:24	RMU faulty near L&L residency For creeper cutting Shutdown taken by LT staff. LT conductor snapped near Telaulim Conductor snapped near Nagmoddem Tolleband Pin insulator damaged
92	MARGAO	33KV Cuncolim	11KV Chinchinim	4S09-1104	RURAL				24:00:00	

93	MARGAO	33KV Poinguinim	11KV Poinguinim	4S12-1104	RURAL				24:00:00	
94	MAPUSA	33KV Pernem	11KV Dhargal	1S01-1105	RURAL	4015	11	50040	22:45:00	Dry tree branch fallen on line at Virnoda, Jumper open at Oxelbag, Replace AB switch mouth blades in yard, post insulator failure at Arabo DP, Coconut leaf found on line at Virwada, Dhargal
95	MAPUSA	33KV Saligao	11KV Navy	1S10-1107	RURAL				24:00:00	
96	MAPUSA	33KV Valpoi	11KV Thana	1S11-1103	RURAL	1600	7	24420	23:01:52	Tree fallen , M/T for change over, 33KV line fault
97	MAPUSA	33KV Candolim	11KV Ximer	1S12-1101	RURAL	2403	3	2220	23:58:48	Manual trip to attend red hot jumper near 11KV incomer II VCB , Manual trip for maintenace of control panel by M/S Ashida control panels
98	MAPUSA	33 KV Anjuna	11KV Temvi	1S15-1101	URBAN	976	3	14820	22:37:40	1. Feeder tripped on Over current. During test charge the breaker found not operating, breaker ON/OFF indication plate found stuck.and full feeder charged 2. The feeder was manually tripped to carry out maintenance work on the breaker of the 11 kV Tembi feeder. Same was attended and full feeder charged 3. Feeder was manually tripped to open overhead AB Switch to restringe snapped conductor at grand Peddam.
99	MAPUSA	33/11 KV GIS CALANGUTE	11KV Post Office	1S18-1103	RURAL				24:00:00	
100	PANJIM	33KV Corlim	11KV Kadamba	2S01-1110	RURAL				24:00:00	
101	PANJIM	33KV PILAR	11KV Neura	2S06-1101	RURAL				24:00:00	
102	PANJIM	33KV Shiroda	11KV Borim	2S12-1101	RURAL	5514	4	540	23:51:00	Transient Fault, Breakdown, Planned Shut down
103	PANJIM	33KV Shiroda	11KV Torla Paz	2S12-1104	RURAL	2131	6	360	23:54:00	Transient Fault, Breakdown, Planned Shut down
104	MORMUGAO	33KV Kadamba	11KV Airport	3S02-1105	URBAN	2508	4	14400	23:52:30	Manually tripped to cut tree branches near Vidya Mandir.
105	MORMUGAO	33KV Majorda	11KV Majorda	3S05-1102	RURAL				24:00:00	
106	MARGAO	33KV Monte Hill	11KV Lohia-II	4S03-1107	URBAN		2	2220	23:41:30	Shutdown taken to take nameplate details of CT/PT in yard
107	MARGAO	33KV Canacona	11KV Gulem	4S11-1106	RURAL				24:00:00	
108	MARGAO	33KV Pontemol	11KV IDC	4S13-1103	RURAL				24:00:00	
109	MARGAO	33KV Shigao	11KV Collem	4S14-1101	RURAL				24:00:00	
110	MAPUSA	33KV Pernem	11KV Torse	1S01-1102	RURAL	3597	4	2100	23:25:00	Maintenance work
111	MAPUSA	33KV Mapusa	11KV Khorlim	1S04-1107	URBAN				24:00:00	
112	MAPUSA	33KV Porvorim	11KV Salai	1S09-1108	RURAL				24:00:00	
113	MAPUSA	33KV Porvorim	11KV GURUDWARA	1S09-1111	URBAN	1250	3	6900	23:56:17	one number jumper opened, one number cable jumper opened,Jumper opened.
114	MAPUSA	33KV Saligao	11KV PILERNE (UG)	1S10-1110	RURAL	107	3	3780	23:57:58	Manual trip requested by Porvorim SS, Overcurrent Earth fault
115	MAPUSA	33KV Valpoi	11KV Dabose	1S11-1106	RURAL	35	4	22260	22:27:15	Tree fallen , M/T for change over, 33KV line fault
116	MAPUSA	33KV Sal	11KV Ibrampur	1S16-1102	RURAL	375	2	3780	23:28:30	Tree fallen , Planned shutdown
117	PANJIM	33KV Altinho	11KV Tonca Miramar	2S04-1108	URBAN				24:00:00	
118	PANJIM	33KV PILAR	11KV Agasaim	2S06-1102	RURAL				24:00:00	
119	PANJIM	33KV Bethora	11KV Shiroda	2S13-1101	RURAL	715	2	180	23:58:30	transient fault
120	MORMUGAO	33KV Kadamba	11KV Vasco church	3S02-1102	URBAN	3181	6	24300	23:47:21	Manually tripped to attend loose pinbinding near church bus stop. Observed during line patrolling.
121	MORMUGAO	33KV Sancoale	11KV Vasco-II	3S03-1106	RURAL	2463	11	45360	23:35:37	Due to fault on PTR-5 in substation, Tree branch had fallen on line,Feeder manually tripped to shift partial load on TATA / Sesa Goa feeder,Feeder tripped on SE/F., Jumper opened on line at Airport Plaza,Jumper had opened on 4pole structure near Sai service,Manually tripped due to fault on Vasco I feeder,As MRT was carrying out testing of Breaker in the substation, The load was shifted on TATA feeder temporarily.
122	MARGAO	33KV Monte Hill	11KV GVN1	4S03-1102	URBAN		2	3120	23:34:00	Shutdown taken to take nameplate details of CT/PT in yard, Transformer 3 Manually tripped to attend Red Hot at Transformer 11KV Side
123	MARGAO	33KV Cuncolim	11KV IDC II	4S09-1101	RURAL				24:00:00	
124	MARGAO	33KV Poinguinim	11KV Loliem	4S12-1105	RURAL				24:00:00	
125	MAPUSA	33KV Pernem	11KV Sawal	1S01-1104	RURAL	1030	3	16260	22:30:00	Conductor snapped at Sawalwada, Pernem and maintenance work
126	MAPUSA	33KV Tuem	11KV Industry	1S02-1101	URBAN	452	3	6840	23:22:00	Attend open jumper at Simchem Factory AB switch, Industrial area and jumper touch to channel at Industry area

127	MAPUSA	220/33KV Thivim	11KV Colvale	1S03-1104	RURAL	2830	8	28500	23:00:37	1. Feeder was manually tripped to open Bombay tapping AB Switch to carryout tree cutting work same AB Switch was closed and full feeder charged. 2. The feeder was manually tripped to open the Karkyacho Val AB Switch and Railway AB Switch for carrying out a scheduled shutdown for tree-cutting work. During the shutdown, the power supply was back-fedded to maintain continuity of supply to the affected area. Upon completion of the work, the both AB Switch was closed, the back-feed arrangement was withdrawn, and the entire feeder was charged. 3.Planned shutdown taken on Koni Tapping AB Switch on 11KV Colvale feeder for carrying out tree-cutting/treeming work. Upon completion of the work, the AB Switch was closed and the entire feeder was charged. 4.Planned shutdown taken on Telephone Exchange Tapping AB Switch on 11KV Colvale feeder for carrying out tree-cutting/trimming work. Upon completion of the work, the same AB Switch was closed and the full feeder was charged. 5. Planned shutdown taken on Koni section AB Switch on 11KV Colvale feeder for carrying out 1) Tree-cutting/treeming work on HT line 2) DP renovation on High DTC 3) Tree-cutting/treeming work on LT line. 6. Planned shutdown taken on Karkyacho val section AB Switch on 11KV Colvale feeder for carrying out 1) Tree-cutting/treeming work on HT line 2) 11KV jumpering work for commissioning of a new transformer Center at Karkyacho val . 3) Tree-cutting/treeming & maintenance work on LT line. 7. Feeder was manually tripped to open main section AB Switch for 11KV jumpering work of commissioning of a new transformer Center at Karkyacho val Colvale. The rest feeder was restored by back-feeding the supply from Sirsaim Feeder. 8. Planned shutdown taken on Koni section AB Switch on 11KV Colvale feeder for carrying out 1) Tree-cutting/treeming work on HT line 2) Erection of a double feeder for the Highway DTC.
128	MAPUSA	33KV Mapusa	11KV Duler	1S04-1102	URBAN				24:00:00	
129	MAPUSA	33KV Mapusa	11KV City	1S04-1103	RURAL	2350	4	420	23:59:46	Overcurrent R,Y,B phases
130	MAPUSA	33KV Sanquelim	11KV Poriem	1S08-1101	RURAL	3100	1	2400	23:58:50	WRD Plant LA Failed.Same Isolated and Feeder Charge.
131	MAPUSA	33KV Valpoi	11KV Saleli	1S11-1102	RURAL				24:00:00	
132	MAPUSA	33KV Candolim	11KV Highland	1S12-1106	RURAL	2431	3	480	23:59:45	Manually tripped due to moisture in RMU, Manual trip for maintenace of control panel by M/S Ashida control panels
133	MAPUSA	33 KV Anjuna	11KV vagator	1S15-1102	RURAL				24:00:00	
134	PANJIM	33KV EDC	11KV Old bus stand	2S02-1101	URBAN				24:00:00	
135	PANJIM	33KV Curti	11KV Durbhat	2S10-1106	RURAL				24:00:00	
136	PANJIM	33KV Madkai	11KV Karanzal	2S15-1103	RURAL	822	9	5760	23:59:55	Breakdown/ transient Fault/Planned Maintenace/
137	MORMUGAO	33KV Sancoale	11KV Cansualim	3S03-1102	RURAL	2789	21	58920	23:28:19	Feeder tripped on overcurrent,Feeder manually tripped as informed by Majorda Sub-Station staff to attend jumper., to attend snapped LT line at Upasanagar., Due to Tree branch fallen on line in Dando, 5 Nos Jumper snapped on line,Feeder manually tripped to attend jumper on D-Mart line,Manual Tripping for testing of relay & CT's behind 11 KV D mart/Cansaulim feeder as per MRT request, Feeder manually tripped to attend jumper on Cansaulim O/G AB/S., Feeder tripped on sensitive earth fault due to coconut palm fallen on line,Feeder manually tripped to attend jumper on line, The shutdown was taken by Majorda Staff to attend jumper,Feeder manually tripped, shutdown requested by majorda je (Sub-III, Div-XIV), Feeder tripped on O/C a Coconut Palm had falled on line,due to AB/S problem on Cansaulim feeder
138	MORMUGAO	110/33/11 KV Verna	11KV Verna	3S04-1101	RURAL	3	12	2820	23:58:29	Feeder faulty
139	MORMUGAO	110/33/11 KV Verna	11KV Nagoa	3S04-1106	RURAL	1844	6	33660	23:50:39	Feeder faulty, shifting of line, attending jumper, panel testing
140	MARGAO	33KV Raia	11KV Curtorim	4S01-1105	RURAL				24:00:00	
141	MARGAO	33KV Fatorda	11KV Ambaji	4S02-1101	URBAN		1	720	23:48:00	Manually Tripped to attend Red Hot on 33 KV side of Power Transformer - 3

142	MARGAO	33KV Monte Hill	11KV Mutt	4S03-1106	URBAN		4	5220	23:38:15	Transformer II M/T to attend cut jumper, Shutdown taken to take nameplate details of CT/PT in yard
143	MARGAO	33KV Aquem	11KV Margao I	4S04-1107	URBAN		1	600	23:50:00	Incoming supply (Margao Express I) failed from Xeldem.
144	MARGAO	33KV Nessai	11KV Goa Carbon	4S06-1104	URBAN		6	29820	22:37:10	Tripped on EFR. Diana bar HT AB switch jumper cut, Planned shutdown for tree cutting, Tripped on EFR. Took test charge. Patrolling done. Line holding, Tripped manually to attend open jumper on LT T/R near Konkan railway gate
145	MARGAO	33KV Carmona	11KV Janoth Bazar	4S08-1102	URBAN				24:00:00	
146	MARGAO	33KV Cuncolim	11KV Cuncolim	4S09-1105	RURAL				24:00:00	
147	MARGAO	33KV Pontemol	11KV Panchwadi	4S13-1102	RURAL				24:00:00	
148	MARGAO	33KV Xelpem	11KV Malkarne	4S18-1104	RURAL				24:00:00	
149	MAPUSA	33KV Pernem	11KV Nagzar	1S01-1101	RURAL	3676	8	46140	22:24:00	Tree branch fallen on line at Dadachiwadi, Dhargal, Creepers found on line and tree fallen on line at Junatwada, Dhargal
150	MAPUSA	33KV Tuem	11KV Morjim	1S02-1104	RURAL	3121	8	452	23:30:00	Incoming failed from 33KV supply (Electronic city), 33KV Pernem II Income failed. Change over done from Pernem circuit II to Electronic circuit II
151	MAPUSA	220/33KV Thivim	11KV Industrial Estate II (U/G)	1S03-1107	URBAN				24:00:00	
152	MAPUSA	33KV Mapusa	11KV Sodiem	1S04-1111	RURAL	1550	-	-		-
153	MAPUSA	33KV Nagoa	11KV Sanqwadi	1S07-1106	RURAL	1215	1	4080	23:57:48	Declared foulty on OC EF,after sectionizing found flash over between Cusmuser side 2 way RMU & Transformer bushing & charged.
154	MAPUSA	33KV Saligao	11KV Candolim church	1S10-1102	RURAL	968	1	900	23:59:31	Manual trip to attend Red Hot on incoming A.B. switch.
155	MAPUSA	33KV Saligao	11KV Shervani Calangute	1S10-1103	RURAL	3610	2	1380	23:59:15	Manual trip to Red hot attended on AB Switch in yard, C/O made from 33KV Saligao 2 to 33KV Saligao 1 as per tivim S.S
156	MAPUSA	33KV Pale	11KV Nanus	1S14-1101	RURAL	1963	2	300	23:59:50	Supply fail from Ponda Substation
157	MAPUSA	33KV Pale	11KV Kotumbi	1S14-1102	RURAL	607	2	300	23:59:50	Supply fail from Ponda Substation
158	MAPUSA	33/11 KV GIS CALANGUTE	11KV Tivaiwaddo	1S18-1108	RURAL				24:00:00	
159	PANJIM	33KV Corlim	11KV Old Goa	2S01-1102	RURAL				24:00:00	
160	PANJIM	33KV Corlim	11KV Old Industry	2S01-1105	URBAN				24:00:00	
161	PANJIM	33KV Altinho	11KV Circuit House	2S04-1103	URBAN				24:00:00	
162	PANJIM	33KV Bambolim	11KV MES	2S05-1102	RURAL				24:00:00	
163	PANJIM	33KV Nagali hills(IT Park)	11KV OITIYANT	2S07-1103	URBAN				24:00:00	
164	PANJIM	33KV Colony	11KV Rajiv Gandhi Kala Mandir	2S09-1106	URBAN	1367	1	18120	18:58:00	Plan Shut down on 11 KV Feeder to carry out urgent maintenance work at the 33/11 KV Colony Sub Station.
165	PANJIM	33KV Curti	11KV Sarvoiverem	2S10-1104	RURAL	3350	18	8160	21:44:00	manual tripped fuse at keri bazar
166	MORMUGAO	33KV Majorda	11KV Duguem	3S05-1105	RURAL				24:00:00	
167	MORMUGAO	33KV Majorda	11KV Nuvem	3S05-1106	RURAL				24:00:00	
168	MORMUGAO	33KV Bogda	ANTARTICA - Headland II	3S06-1104	URBAN	1668	6	1531	24:00:00	1) Feeder tripped on IDMT on earth fault , feeder charged and stood ok, line patrolling done no fault was traced 2) 33KV Incomer II supply failed, supply failed from Sancoale S/S, 3) 33KV Incomer II supply failed, supply failed from Sancoale S/S, 4) 33KV Incomer II supply failed, supply failed from Sancoale S/S, 5) Feeder tripped on IDMT earth fault. feeder charged and stood ok, line patrolling done no fault was traced 6) 33KV Incomer II supply failed, supply failed shutdown taken by Sancoale S/S due to relay setting.

169	MORMUGAO	33KV Bogda	MASJID	3S06-1105	RURAL	2301	7	9660	24:00:00	1) 33KV Incomer I supply failed, supply failed from Verna substation, 2)Feeder tripped on earth faullt. feeder charged and stood ok, line patrolling done no fault was traced 3) 33KV Incomer I supply failed, supply failed from Verna substation, 4) 33KV Incomer I supply failed, supply failed from Verna substation, 5) Feeder tripped on earth fault, underground cable fault at DTC , faulty section isolated and feeder charged. 6) 33KV Incomer I supply failed, supply failed from Kadamba substation, 7) 33KV Incomer I supply failed, supply failed from Kadamba substation, 8) 33KV Incomer I supply failed, supply failed from Verna substation, 9) 33KV Incomer I supply failed, supply failed from Verna substation, 10) 33KV Incomer I supply failed, due to lightening arrestor failed in sub station yard 11) Feeder manually tripped to replace 33 KV lightening arrestor at sub station yard.
170	MARGAO	33KV KRC	11KV Navelim OH	4S05-1101	RURAL		5	7380	23:35:24	To attend jumper, To remove creepers, For Tree Cutting, FALLING OF TREE BRANCH ON OH LINE
171	MARGAO	33KV KRC	11KV Mandopa	4S05-1102	RURAL		1	720	23:48:00	M/T to put Rosary bakery transformer on underground cable. Only 1 transformer was put off
172	MARGAO	33KV Benaulim	11KV Betal Betim	4S07-1103	RURAL				24:00:00	
173	MARGAO	33KV Velim	11KV Kumbia bhat	4S10-1103	RURAL				24:00:00	
174	MARGAO	33KV Shigao	11KV Mollem	4S14-1102	RURAL				24:00:00	
175	MAPUSA	33KV Pernem	11KV Keri	1S01-1106	RURAL	1869	4	17580	22:47:00	Jamun tree fallen on line at Bhatwadi, LT conductor snapped at Bhalkhajan, Korgao and maintenance work
176	MAPUSA	33KV Tuem	11KV Mandrem	1S02-1102	RURAL	3875	3	378	23:30:00	Incoming failed from 33KV supply (Electronic city)
177	MAPUSA	33KV Mapusa	11KV Industry	1S04-1101	URBAN	-	-	-		-
178	MAPUSA	33KV Mapusa	11KV Karaswada	1S04-1104	URBAN				24:00:00	
179	MAPUSA	33KV Mapusa	11KV Parra	1S04-1113	RURAL				24:00:00	
180	MAPUSA	33KV Bicholim	11KV Lamgao	1S05-1112	RURAL	859	1	2150	23:24:12	Insulator failure
181	MAPUSA	33KV Nachinola	11KV Pomburpa	1S06-1101	RURAL	1451	1	3840	23:57:56	MT Shutdown taken to attend cut jumper on 33kv Porvorim-I & II at Nachinola Substatation & Charged.
182	MAPUSA	33KV Porvorim	11KV Malim	1S09-1104	RURAL	930	3	5700	23:56:56	Flashed over in Metering Cubicle,Jumper opened,Jumper opened
183	PANJIM	33KV EDC	11KV BAL BHARTI	2S02-1108	URBAN				24:00:00	
184	MORMUGAO	33KV Kadamba	11KV Waddem Lake	3S02-1104	URBAN	3152	5	17340	23:50:59	Manually tripped to replace H.G fuse of NAD T/C by LT staff.
185	MORMUGAO	33KV Sancoale	11KV Sesa Goa	3S03-1101	URBAN	1484	2	2400	23:58:43	Feeder manually tripped to shift load of 11kV Vasco-II feeder on TATA feeder, Openeing of jumper on line
186	MORMUGAO	110/33/11 KV Verna	11KV SMARTLINK	3S04-1109	URBAN	133	9	9000	23:55:10	tree cutting
187	MARGAO	33KV Fatorda	11KV Gogol	4S02-1106	RURAL				24:00:00	
188	MARGAO	33KV Aquem	11KV Davorlim	4S04-1106	RURAL				24:00:00	
189	MARGAO	33KV Nessai	11KV Chandor	4S06-1103	RURAL		1	1920	23:28:00	Tripped on OCR. During patrolling found one bird had touched phase to phase on line near New Township area
190	MARGAO	33KV Benaulim	11KV Mobor	4S07-1104	RURAL				24:00:00	
191	MARGAO	33KV Velim	11KV Assolna	4S10-1101	RURAL				24:00:00	
192	MARGAO	33KV Poinguinim	11KV Link line	4S12-1101	RURAL				24:00:00	
193	MARGAO	33KV Xelpem	11KV Dando	4S18-1105	RURAL				24:00:00	
194	MAPUSA	33KV Tuem	11KV Tuem	1S02-1103	RURAL	2145	3	6000	23:27:00	To attend jumper

195	MAPUSA	220/33KV Thivim	11KV Power Grid	1S03-1103	RURAL	2335	4	38880	21:18:00	1. Planned shutdown taken on Colvale IDC Tapping AB Switch on 11KV Powergrid feeder for carrying out tree-cutting/trimming work. Upon completion of the work, the same AB Switch was closed and the full feeder was charged. 2. Feeder tripped on E/F after sectionalizing the feeder Disc Insulator of IDC DTC found faulty, same was attended and full feeder charged 3. Feeder tripped on Earth Fault. After patrolling and sectionalizing the feeder, jumper found in contact with the 4 Pin at Teenmad, same was attended and full feeder charged. 4. Feeder was manually tripped to open Flyover AB Switch to cut creepers on line.
196	MAPUSA	33KV Bicholim	11KV Pilgao	1S05-1104	RURAL	998	6	18700	23:08:06	Tree fallen , M/T for change over, AB cable faulty
197	MAPUSA	33KV Bicholim	11KV Bordem	1S05-1109	URBAN	2655	5	14630	23:11:14	AB cable faulty, Insulator failed
198	MAPUSA	33KV Sanquelim	11KV Honda	1S08-1104	RURAL	188	3	51600	23:32:33	Planned shutdown for line maintenance and Conductor Snapped
199	MAPUSA	33KV Saligao	11KV Saligao	1S10-1104	RURAL	2726	3	7140	23:56:10	Manual trip To attend red/hot jumper near 33 kV Transformer-I , Shutdown taken at Nachinola SS on Porvorim I & II Circuits
200	MAPUSA	33KV Candolim	11KV Sinquerim	1S12-1105	RURAL	2092	3	840	23:59:33	Manual trip for maintenance of VCB of Sinquerim feeder , Manual trip for maintenace of control panel by M/S Ashida control panels
201	MAPUSA	33KV Pale	11KV Barazen	1S14-1103	RURAL	769	2	300	23:59:50	Supply fail from Ponda Substation
202	MAPUSA	33/11 KV GIS CALANGUTE	11KV Kamat	1S18-1107	RURAL				24:00:00	
203	PANJIM	33KV EDC	11KV Ribandar	2S02-1102	URBAN				24:00:00	
204	PANJIM	33KV Campal	11KV Market	2S03-1101	URBAN				24:00:00	
205	PANJIM	33KV Altinho	11KV Inox	2S04-1102	URBAN				24:00:00	
206	PANJIM	33KV Altinho	11KV Campal	2S04-1105	URBAN				24:00:00	
207	PANJIM	33KV Bambolim	11KV Merces	2S05-1104	RURAL				24:00:00	
208	PANJIM	33KV NIO	11KV Models	2S08-1101	URBAN				24:00:00	
209	PANJIM	33KV Curti	11KV Usgao	2S10-1102	RURAL	4641	25	1500	19:50:00	Usgao load shutdown due to 10 MVA tripped (Transferred Curti Feeder load on Farmagudi and Shantinagar directly without tripping) After completing 10 MVA work Usgao RMU charged from 11 KV Controol room also curti feeder normalize.(Usgao load removed from Dharbandora S/S), A fault occurred in the LT cable. To check the cable, the USGOA feeder was manually tripped by L/W Satyam, as the clearance between the LT and HT lines was insufficient, Usgao RMU trip due to tree Cutting work. Khandepar single pole ABS open. (Mr Rajekar) Accepted area garbage HC and Keriya HC and other load given from Sonarbag feeder (backfeed) and Incoming supply failed from 220KV S/S, Instructed to trip main RMU Shantinagar & to charge both Usgao & Farmagudi. Charged ok. 6.3 MVA tripped, Faulty, Bhagwati TC cable fault ,Told to trip RMU Rajangad ABS, closed and backfeed from Kala Mandir feeder, Shutdown from 220KV S/S for panel servicing and also to put lugs at 6.3 MVA transformer and As per instruction 220 KV S/S due to cable work. Shantinagar RMU Tripped and supply restored through backfeed.
210	PANJIM	33KV Madkai	11KV Madkai	2S15-1102	RURAL	2004	14	4440	23:58:46	transient Fault
211	MORMUGAO	110/33/11 KV Verna	11KV Cortalim	3S04-1107	RURAL				24:00:00	
212	MARGAO	33KV Raia	11KV Santamol	4S01-1103	RURAL				24:00:00	
213	MARGAO	33KV Fatorda	11KV Chowgule College	4S02-1103	URBAN		1	720	23:48:00	Manually Tripped to attend Red Hot on 33 KV side of Power Transformer - 3
214	MARGAO	33KV Monte Hill	11KV Hari Mandir-II	4S03-1108	URBAN		6	8280	23:37:00	Transient fault, Mendes Transformer incoming cable moisture, Kerkar Hospital DTC flashover due to moisture build up
215	MARGAO	33KV Aquem	11KV Housing Board O/H	4S04-1103	URBAN				24:00:00	
216	MARGAO	33KV Aquem	11KV Margao III	4S04-1104	URBAN		1	600	23:50:00	Incoming supply (Margao Express I) failed from Xeldem.
217	MARGAO	33KV Velim	11KV Chinchinim	4S10-1104	RURAL				24:00:00	
218	MARGAO	33KV Pontemol	11KV Dabal	4S13-1107	RURAL				24:00:00	
219	MARGAO	220/33/11KV Xeldem	11KV Xelvona	4S15-1101	RURAL				24:00:00	
220	MAPUSA	33KV Pernem	11KV City	1S01-1103	RURAL	1488	4	21900	22:29:00	To attend open jumper, maintenance work
221	MAPUSA	220/33KV Thivim	11KV Industrial Estate	1S03-1101	URBAN				24:00:00	

222	MAPUSA	33KV Nagoa	11KV Calangute	1S07-1101	RURAL				24:00:00	
223	MAPUSA	33KV Porvorim	11KV Sangolda	1S09-1105	RURAL				24:00:00	
224	MAPUSA	33KV Saligao	11KV Gaurawaddo	1S10-1109	URBAN				24:00:00	
225	MAPUSA	33KV Valpoi	11KV City New	1S11-1105	RURAL	1500	4	7560	23:28:30	Tree fallen , M/T for change over, 33KV line fault
226	MAPUSA	33KV Sal	11KV Kasarpal	1S16-1103	RURAL	452	1	1650	23:32:30	Tree fallen , Planned shutdown
227	MAPUSA	33/11 KV GIS CALANGUTE	11KV Mark Memorial	1S18-1105	URBAN				24:00:00	
228	PANJIM	33KV Campal	11KV St. Inez	2S03-1107	URBAN				24:00:00	
229	PANJIM	33KV Altinho	11KV Cabo	2S04-1112	URBAN	796	1	360	23:54:00	Tripped on O/C & E/F
230	PANJIM	33KV PILAR	11KV Batim	2S06-1103	RURAL				24:00:00	
231	PANJIM	33KV NIO	11KV NIO	2S08-1103	URBAN				24:00:00	
232	PANJIM	33KV Colony	11KV Bazaar	2S09-1101	URBAN	2652	7	19140	18:41:00	Plan Shut down on 11 KV Feeder to carry out urgent maintenance work at the 33/11 KV Colony Sub Station and Tripped on Earth Fault relay.
233	PANJIM	33KV Bethora	11KV Industrial	2S13-1104	URBAN	421	4	17760	19:04:00	Transient Fault, Breakdown, Planned Shut down
234	PANJIM	33KV Kundaim	11KV Kundaim	2S14-1104	RURAL	2501	10	1980	23:59:58	transient Fault
235	MORMUGAO	33KV Kadamba	11KV Vasco city	3S02-1103	URBAN	1715	7	45900	23:36:07	Manually tripped to replace red hot nut bolt of R phase incoming AB switch.
236	MORMUGAO	33KV Sancoale	11KV Vasco-I	3S03-1103	URBAN	2369	5	19260	23:49:39	Feeder was manually tripped to attend jumper on Vasco II feeder line,Feeder manually tripped to attend Jumper on line,Feeder tripped on O/C , Line snapped
237	MORMUGAO	110/33/11 KV Verna	11KV Oxynitro	3S04-1110	RURAL	21	17	33600	23:41:56	Feeder faulty
238	MARGAO	33KV Fatorda	11KV Fatorda	4S02-1105	URBAN		2	3300	23:32:30	33 KV side jumper of Power Transformer Opened, Manually Tripped to attend Red Hot on 33 KV side of Power Transformer - 2
239	MARGAO	33KV Monte Hill	11KV GVN2	4S03-1101	URBAN		2	1920	23:44:00	Shutdown taken to take nameplate details of CT/PT in yard
240	MARGAO	33KV Cuncolim	11KV IDC I	4S09-1102	RURAL		1	600	23:50:00	Incoming supply (Margao Express I) failed from Xeldem.
241	MARGAO	33KV Velim	11KV Betul	4S10-1102	RURAL				24:00:00	
242	MARGAO	33KV Poinguinim	11KV Marli Tirval	4S12-1102	RURAL				24:00:00	
243	MARGAO	33KV Pontemol	11KV Town 1	4S13-1101	URBAN				24:00:00	
244	MARGAO	33KV Rivona	11KV Maina	4S16-1101	RURAL				24:00:00	
245	MAPUSA	33KV Nagoa	11KV Baga	1S07-1107	RURAL				24:00:00	
246	MAPUSA	33KV Porvorim	11KV Soccorro	1S09-1101	RURAL				24:00:00	
247	MAPUSA	33KV Saligao	11KV Industry O/H	1S10-1106	URBAN	2285	6	12900	23:24:10	1. Feeder tripped on Sensitive Earth Fault. After patrolling and sectionalizing the feeder, jumper found in contact with the conductor, same was attended and full feeder charged. 2. Feeder manually tripped to permit Line Clearence to Mapusa Substation to carry out tree cutting on 33KV Mapusa-I & II circuit. 3. Feeder tripped on Sensitive Earth Fault. After patrolling and sectionalizing the feeder, jumper found open near Madel Four pole Structure, same was attended and full feeder charged. 4. Feeder tripped on Sensitive Earth Fault. After patrolling and sectionalizing the feeder, found palm leaves on line same was removed and full feeder charged. 5. Feeder tripped on Earth fault. After patrolling and sectionalizing the feeder, a jumper found open of Gotnicho wal Tapping AB Switch . The same was attended and full feeder charged. 6. Feeder was manually tripped to open Crematorium section AB Switch to attend open jumper same was attended and full feeder charged.
248	MAPUSA	33KV Saligao	11KV Nerul	1S10-1108	RURAL	3708	12	5820	23:56:52	Nerul feeder tripped on earth fault, manual trip to check supply to Coco beach Transformer, changeover made from 33KV Saligao 2 to 33KV Saligao 1 as per tivim S.S,Shutdown taken at Nachinola SS on Porvorim I & II Circuits,Manual trip, to put load of Kegdevelim feeder on Nerul feeder,Manual trip to work on RMU of PWD transformer, Shutdown taken to charge RMU of PWD transformer.
249	MAPUSA	220/33KV Amona	11 KV Pissurlem IDC	1S13-1104	RURAL				24:00:00	
250	MAPUSA	33/11 KV GIS CALANGUTE	11KV Shivam	1S18-1104	RURAL	1389	3	1080	23:59:25	Manual trip for safety purpose to replace of fuse of 11KV RMU at Golden suites Transformer, Manual trip due to AVR faulty of silver shell hotel,Manual tripto charge silver shell hotel
251	PANJIM	33KV Corlim	11KV Molar	2S01-1106	RURAL				24:00:00	

252	PANJIM	33KV Campal	11KV City	2S03-1103	RURAL				24:00:00	
253	PANJIM	33KV Nagali hills(IT Park)	11KV STATUS	2S07-1104	URBAN				24:00:00	
254	PANJIM	33KV Colony	11KV Curti	2S09-1105	URBAN	753	4	19740	18:31:00	Plan Shut down on 11 KV Feeder to carry out urgent maintenance work at the 33/11 KV Colony Sub Station,M/T to charge new RMU at Coperwada as per JE's Instruction and Tripped on earth fault relay
255	PANJIM	33KV Dharbandora	11KV Dharbandora	2S11-1104	RURAL	2456	27	36240	13:56:00	Transient Fault, Breakdown, Planned Shut down
256	MORMUGAO	33KV Sancoale	11KV College	3S03-1107	RURAL	1168	2	5760	23:56:54	UG Cable fault between Uptown RMU to Karma-1 RMU, UG Cable fault from RMU Tome Carvalho to Bharat Nagar
257	MARGAO	33KV Benaulim	11KV Colva Exp	4S07-1107	URBAN				24:00:00	
258	MARGAO	220/33/11KV Xeldem	11KV Rivona	4S15-1102	RURAL				24:00:00	
259	MARGAO	33KV Rivona	11KV Colomba	4S16-1103	RURAL				24:00:00	
260	MARGAO	33KV Xelpem	11KV Sanguem	4S18-1101	URBAN				24:00:00	
261	MAPUSA	33KV Tuem	11KV Ashvem Cable	1S02-1105	RURAL	104	3	378	23:30:00	Incoming failed from 33KV supply (Electronic city)
262	MAPUSA	33KV Mapusa	11KV Anjuna	1S04-1106	RURAL				24:00:00	
263	MAPUSA	33KV Mapusa	11KV Assagao	1S04-1110	RURAL	2515	1	1860	23:29:00	1. Feeder tripped on Over Curent Earth fault after sectinalizing the feeder found Tree branch found on line near Assagao residency Same was removed and full feeder charged.
264	MAPUSA	33KV Bicholim	11KV Ladphem	1S05-1103	RURAL	511	0	0	24:00:00	
265	MAPUSA	33KV Bicholim	11KV Narva	1S05-1106	RURAL	585	8	21600	23:15:00	Tree fallen , Planned shutdown, conductor snapped
266	MAPUSA	33KV Nachinola	11KV Moira	1S06-1103	RURAL	3620	8	16200	23:26:15	1. Feeder tripped on Over current master trip relay, also Power Transformer -II pulled due to Monkey touched towards LV side of Power Tr. 2. Feeder tripped on Over Current, Delayed due to Heavy rain & wind, feeder test charged stook ok no fault found. 3. Feeder tripped on Over Current. After patrolling and sectionalizing the feeder, jumper found open on main section AB Switch same was attended but feeder tripped again on Earth fault. 4. After patrolling and sectionalizing the feeder Post Insulator of Isprava DTC found faulty,trasformer RMU outgoing side open and rest feeder charged. Same was attended and full feeder charged 5.Feeder was manually tripped to open Tambadi Mati Section AB Switch to carryout tree cutting work same AB Switch was closed and full feeder charged. 6. Feeder manually trip to open Sateri Temple Section for erection of LT poles for line clearence. Rest full feeder charged by back feeding. 7. Feeder tripped on Over Current. After patrolling and sectionalizing the feeder, Jumper was found open at the Ram Mandir DTC . The same was attended and full feeder charged. 8. Feeder was manually tripped to open Bank Section AB Switch to carryout tree cutting work near Moira Panchayat same AB Switch was closed and full feeder charged.
267	MAPUSA	33KV Nachinola	11KV Bastora	1S06-1104	RURAL	2213	1	3840	23:57:56	MT Shutdown taken to attend cut jumper on 33kv Porvorim-I & II at Nachinola Substatation & Charged.
268	MAPUSA	33KV Sal	11KV Sal	1S16-1101	RURAL	797	5	10360	23:25:30	Tree fallen , Planned shutdown
269	PANJIM	33KV Corlim	11KV Dhulapi	2S01-1101	RURAL				24:00:00	
270	PANJIM	33KV EDC	11KV Vidyut Bhawan	2S02-1104	URBAN				24:00:00	
271	PANJIM	33KV Altinho	11KV Alcon	2S04-1104	URBAN				24:00:00	
272	PANJIM	33KV Bambolim	11KV Donapaula	2S05-1103	RURAL				24:00:00	
273	PANJIM	33KV Curti	11KV OPA	2S10-1103	RURAL				24:00:00	
274	PANJIM	33KV Kundaim	11KV Marcel	2S14-1102	RURAL	7853	22	7800	23:59:54	Breakdown/ transient Fault/Planned Maintenace
275	PANJIM	33KV Madkai	11KV Undir	2S15-1101	RURAL	2015	26	9840	23:59:53	Breakdown/ transient Fault/Planned Maintenace/To servicing braker
276	MORMUGAO	110/33/11 KV Verna	11KV Herald	3S04-1102	URBAN	87	26	34680	23:41:21	Feeder faulty
277	MORMUGAO	110/33/11 KV Verna	11KV Jordan	3S04-1105	URBAN	68	17	31320	23:43:10	Feeder faulty

278	MORMUGAO	33KV Majorda	11KV Ramesh Hotel	3S05-1101	URBAN				24:00:00	
279	MARGAO	33KV Raia	11KV Raia	4S01-1101	RURAL				24:00:00	
280	MARGAO	33KV Raia	11KV Rachol	4S01-1104	RURAL				24:00:00	
281	MARGAO	33KV Fatorda	11KV Old market U/G	4S02-1102	URBAN		2	3300	23:32:30	33 KV side jumper of Power Transformer Opened, Manually Tripped to attend Red Hot on 33 KV side of Power Transformer - 2
282	MARGAO	33KV Aquem	11KV Housing Board U/G	4S04-1102	RURAL		0		24:00:00	
283	MARGAO	33KV Aquem	11KV Malbhat	4S04-1105	URBAN		3	2100	23:48:20	Incoming supply (Margao Express I) failed from Xeldem, Flashover on Ginger Hotel RMU Transformer Side
284	MARGAO	33KV Nessai	11KV MIE	4S06-1101	RURAL				24:00:00	
285	MARGAO	33KV Carmona	11KV XIRO	4S08-1103	RURAL				24:00:00	
286	MARGAO	33KV Canacona	11KV Shristhal	4S11-1102	RURAL				24:00:00	
287	MARGAO	33KV Canacona	11KV Kindlem	4S11-1103	RURAL				24:00:00	
288	MARGAO	33KV Pontemol	11KV Town 2	4S13-1106	URBAN				24:00:00	
289	MARGAO	33KV Pontemol	11KV HODAR	4S13-1109	RURAL				24:00:00	
290	MARGAO	33KV Xelpem	11KV Barazan	4S18-1103	RURAL				24:00:00	
291	MAPUSA	33KV Bicholim	11KV Assnora	1S05-1110	RURAL	1963	3	6250	23:25:17	Tree fallen , Planned shutdown
292	MAPUSA	33KV Nagoa	11KV Sauntawada	1S07-1102	RURAL				24:00:00	
293	MAPUSA	33KV Nagoa	11KV Dharwadkar	1S07-1108	RURAL				24:00:00	
294	MAPUSA	33KV Porvorim	11KV Pundalic Nagar	1S09-1102	RURAL				24:00:00	
295	MAPUSA	220KV Amona	11KV Amona Marcel	1S13-1103	URBAN				24:00:00	
296	PANJIM	33KV Corlim	11KV Khumarjau	2S01-1107	RURAL				24:00:00	
297	PANJIM	33KV Corlim	11KV Diwar	2S01-1109	RURAL				24:00:00	
298	PANJIM	33KV EDC	11KV Ginger	2S02-1106	URBAN				24:00:00	
299	PANJIM	33KV Campal	11KV LA-Campal	2S03-1102	URBAN				24:00:00	
300	PANJIM	33KV Campal	11KV Indoor Stadium	2S03-1104	URBAN				24:00:00	
301	PANJIM	33KV Bambolim	11KV Chimbel	2S05-1106	RURAL				24:00:00	
302	PANJIM	33KV NIO	11KV Rajbhawan	2S08-1104	URBAN				24:00:00	
303	PANJIM	33KV Colony	11KV Ponda-I	2S09-1104	URBAN	3900	1	1200	23:40:00	Feeder was charged twice, but the supply did not hold and cable fault at Daag Ponda Tisk.
304	PANJIM	33KV Dharbandora	11KV Bondla	2S11-1103	RURAL				24:00:00	
305	PANJIM	33KV Kundaim	11KV Industry III	2S14-1105	URBAN	131	1	1800	23:59:58	transient Fault
306	MORMUGAO	33KV Harbour	11KV Vasco-I	3S01-1102	URBAN				24:00:00	The feeder no longer exist; hence, the load was shifted to the bogda sub-station in 2023.
307	MORMUGAO	33KV Sancoale	11KV Industrial	3S03-1108	URBAN				24:00:00	
308	MARGAO	33KV Fatorda	11KV Borda	4S02-1104	URBAN		1	1920	23:28:00	Flashover at RMU Behind Noble Pharmacy
309	MARGAO	33KV Aquem	11KV AQUEM BAIXO	4S04-1108	URBAN		1	600	23:50:00	Incoming supply (Margao Express I) failed from Xeldem.
310	MARGAO	33KV Benaulim	11KV Benaulim	4S07-1101	RURAL				24:00:00	
311	MARGAO	33KV Benaulim	11KV Trinity	4S07-1106	RURAL				24:00:00	
312	MARGAO	220/33/11KV Xeldem	11KV Quepem	4S15-1103	URBAN				24:00:00	
313	MARGAO	33KV Rivona	11KV Sulcorna	4S16-1102	RURAL				24:00:00	
314	MARGAO	33KV Waddem	11KV Netravali	4S17-1102	RURAL				24:00:00	
315	MAPUSA	220/33KV Thivim	11KV Sirsaim	1S03-1106	RURAL	2209	2	4740	23:20:30	1. Feeder tripped on Over current E/F. the cable from Dhanger Waddo Interlink to Forest RMU was suspected to be faulty. The remaining portion of the feeder was restored by back-feeding the supply from Colvale Feeder. 2. 10 MVA Power Transformer tripped at Tivim Substation. Issue on 33KV Incomer Breaker and Bus coupler.

316	MAPUSA	33KV Bicholim	11KV ADVALPAL	1S05-1105	RURAL	558	7	19050	23:14:39	Tree fallen , Planned shutdown
317	MAPUSA	33KV Bicholim	11KV City	1S05-1108	RURAL	0	0	0	24:00:00	
318	MAPUSA	33KV Bicholim	11KV Kudchirem	1S05-1111	RURAL	733	5	12300	23:19:00	Tree fallen , Planned shutdown
319	MAPUSA	33KV Nachinola	11KV Aldona OH	1S06-1102	RURAL	4570	1	3840	23:57:56	MT Shutdown taken to attend cut jumper on 33kv Porvorim-I & II at Nachinola Substatation & Charged.
320	MAPUSA	33KV Sanquelim	11KV Amona	1S08-1103	URBAN	1700	7	93600	23:09:49	Line Maintenance and tree pruning work,Tree fallen on line,resulting in the breakdown of poles.After completion of restoration work,supply was restored.
321	MAPUSA	33KV Porvorim	11KV RND	1S09-1103	RURAL	530	1	1620	23:59:08	Conductor Snapped
322	MAPUSA	33KV Porvorim	11KV Chogum	1S09-1110	RURAL	653	1	3360	23:58:12	Jumper opened
323	PANJIM	33KV Corlim	11KV Carambolim	2S01-1104	RURAL				24:00:00	
324	PANJIM	33KV Campal	11KV Adarsh	2S03-1105	URBAN				24:00:00	
325	PANJIM	33KV Altinho	11KV National	2S04-1101	URBAN				24:00:00	
326	PANJIM	33KV Altinho	11KV Manoshanti	2S04-1106	URBAN				24:00:00	
327	PANJIM	33KV NIO	11KV NIO Colony	2S08-1105	URBAN				24:00:00	
328	PANJIM	33KV Colony	11KV Khadpabandh	2S09-1103	URBAN				24:00:00	
329	PANJIM	33KV Curti	11KV Curti	2S10-1108	URBAN				24:00:00	
330	PANJIM	33KV Kundaim	11KV Industry II	2S14-1106	URBAN	228	1	1140	23:59:41	transient Fault
331	PANJIM	33KV Madkai	11KV Industry II	2S15-1105	URBAN	274	10	43680	23:59:29	Breakdown/ transient Fault/Planned Maintenace/To servicing braker
332	MORMUGAO	33KV Harbour	11KV Mangor	3S01-1104	URBAN	5808	1	1080	23:59:26	Manually tripped to remove creeper from pole near Coast guard. AB switch closed and load normalised.
333	MORMUGAO	33KV Sancoale	11KV Dabolim	3S03-1109	URBAN		2	1920	23:58:58	Due to fault on PTR 5, feeder was manually tripped to ring feed with 11 KV NSD feeder
334	MORMUGAO	110/33/11 KV Verna	11KV Industrial	3S04-1103	URBAN	51	18	35254	23:41:03	Feeder faulty
335	MORMUGAO	33KV Bogda	Brahmasthal - vasco 1	3S06-1102	URBAN	4247	11	1380	23:11:00	1) 33KV Incomer II supply failed, supply failed from Sancoale S/S, 2) 33KV Incomer II supply failed, supply failed from Sancoale S/S, 3) 33KV Incomer II supply failed, supply failed from Sancoale S/S, 4) 33KV Incomer II supply failed, Shutdown taken by Sancoale sub station due to relay setting.
336	MORMUGAO	33KV Bogda	HARBOUR	3S06-1103	URBAN	953	13	7920	22:48:00	1)33KV Incomer I supply failed, supply failed from Verna substation, 2)33KV Incomer I supply failed, supply failed from Verna substation, 3)33KV Incomer I supply failed supply failed from Verna substation, 4) Feeder tripped on earth fault.feeder charged and stood ok, line patrolling done no fault was traced 5) 33KV Incomer I supply failed, supply failed from Kadamba S/S 6) Feeder tripped on IDMT over current due to tree branches that had fallen on the HT line near MPT 1st gate Sada. 7) 33KV Incomer I supply failed, supply failed from Kadamba S/S 8)Feeder tripped on Earth fault due to tree branches fallen on HT line. 9) Feeder tripped on earth fault. On site inspection, it was found that HTC Paradeep phosphate installation AB switch female contact is loosen and was touching to the DP structure, HTC installation isolated and feeder charged. 10) 33KV Incomer I supply failed, supply failed from Verna substation, 10)33KV Incomer I supply failed 11) 33KV Incomer I supply failed, due to lightening arrestor failed in sub station yard 12) 33KV Incomer I supply failed, due to lightening arrestor failed in sub station yard 13) Feeder manually tripped to replace 33 KV lighteniong arrestor at sub station yard.
337	MARGAO	33KV Raia	11KV Loutalim	4S01-1102	RURAL		1	720	23:48:00	Manual tripping To replace HG Fuse at Nirboga RMU
338	MARGAO	33KV Monte Hill	11KV Adarsh	4S03-1104	URBAN		2	4980	23:18:30	Transformer II M/T to attend cut jumper, Shutdown taken to take nameplate details of CT/PT in yard
339	MARGAO	33KV Nessai	11KV Paroda	4S06-1102	RURAL				24:00:00	
340	MARGAO	33KV Benaulim	11KV Varca	4S07-1105	RURAL				24:00:00	
341	MARGAO	33KV Pontemol	11KV Kalay	4S13-1104	RURAL				24:00:00	

342	MARGAO	220/33/11KV Xeldem	11KV Assolda	4S15-1104	RURAL				24:00:00	
343	MARGAO	33KV Waddem	11KV Bhati	4S17-1101	RURAL				24:00:00	
344	MARGAO	33KV Raia	11 Camurlim	4801-1108	RURAL		2	2100	23:25:00	Flash over at Old Gavon and Don Bosco RMU
345	MAPUSA	33KV Pale	11KV Guleli	1S14-1104	RURAL	364	2	300	23:59:50	Supply fail from Ponda Substation
346	MAPUSA	33KV Sanquelim	11 KV Keri	1S08-1106	RURAL	1691	2	2400	23:58:50	Trip on Earth Fault
347	MAPUSA	33KV Valpoi	11 KV Advai	1S11-1101	RURAL	3000	10	25860	23:16:54	O/C, E/F, Tree cutting, Tree fallen , M/T
348	MAPUSA	33KV Valpoi	11 KV Stadium	1S11-1104	RURAL	3000	5	22560	22:44:48	O/C, E/F, Tree cutting, Tree fallen , M/T
349	MAPUSA	33KV Valpoi	11 KV Savarde	1S11-1108	RURAL	1800	10	32040	23:06:36	O/C, E/F, Tree cutting, Tree fallen , M/T
350	MAPUSA	33KV Valpoi	11 KV Ambede	1S11-1107	RURAL	2200	6	22440	22:57:40	O/C, E/F, Tree cutting, Tree fallen , M/T
351	MAPUSA	33KV Saligao	11KV Industry Cable 1		RURAL	31	2	2100	23:58:52	Manual trip to attend red/hot jumper near 33 kV Transformer-I
352	MAPUSA	33KV Saligao	11KV Industry Cable 2		RURAL	23	2	1500	23:59:12	Manual trip to attend red hot near jumper of 11KV Cable industry feeder, Shutdown taken at Nachinola SS on Porvorim I & II Circuits, manually tripped for load shedding
353	MAPUSA	33KV Candolim	11KV Kamat		RURAL	1019	2	240	23:59:52	Manual trip for maintenace of control panel by M/S Ashida control panels
354	MAPUSA	33KV Saligao	11KV Kegdevlim		RURAL	586	10	4260	23:57:43	Kegdevelim Feeder declared faulty,Shutdown taken at Nachinola SS on Porvorim I & II Circuits
355	MAPUSA	33KV Candolim	11KV Marquis waddo		RURAL	567	4	1080	23:59:25	Manually tripped due to moisture in RMU, Manual trip for maintenace of control panel by M/S Ashida control panels,Manual trip for cable jointing near Whispering Palm Hotel
356	MAPUSA	33KV Candolim	11KV Tarcar		RURAL	1079	4	2340	23:58:45	Manual trip to attend red hot jumper near 11KV incomer II VCB, Manual trip for charging Newton DP, Manual trip for maintenace of control panel by M/S Ashida control panels
357	PANJIM	33KV Kundaim	Undergound 4	2S14-1109	URBAN	67	2	1740	23:59:58	transient Fault
358	PANJIM	33KV Kundaim	Kunkolim-Keri	2S14-1107	RURAL	1386	17	8640	23:59:55	Breakdown/ transient Fault/Planned Maintenace/
359	MORMUGAO	110/33/11 KV Verna	11KV Tulip	3S04-1112	URBAN	36	5	19800	23:49:21	tree cutting