

GOVERNMENT OF GOA  
ELECTRICITY DEPARTMENT  
OFFICE OF THE CHIEF ELECTRICAL ENGINEER

Head Office, 3<sup>rd</sup> Floor, Vidyut Bhavan, Tiswadi, GOA 403001 Tel:2234155,2224680/EBAPX:2426421,2422353,2426022|| Fax:2426986,  
2222354|||: Email:::cee-elec.goa@nic.in: website:: http://www.goaelectricity.gov.in/http://59.90.104.90

No.51(3)/CEE/Tech/PLG/2017-18/ 345

Dated: - 27/06/2017


## CIRCULAR

**Sub: Preventive maintenance and arrangement for repair of failed Distribution Transformers to be kept as spare in the event of a distribution transformer failure during the monsoons.**

In view of the onset of the monsoons, prior preparedness for effective and timely restoration of power supply in the event of possible breakdowns and transformer failures, need to be expedited. To tide over the situation and being a critical time, all the Executive Engineers are directed to arrange repairs of at least two each distribution transformers of capacity 200KVA and 100KVA from an outsourced agency, following the codal formalities, so that in the event of failure of running distribution transformer, the repaired ones can be substituted as a temporary measure and power supply restored.

Non-compliance of the above directions would be the responsibility of the Executive Engineer, for which this office shall not be held responsible for the ineffectiveness in maintaining the power supply.

These instructions are with immediate effect.

  
(N N Reddy)  
Chief Electrical Engineer

To,

1. Additional Chief Electrical Engineer I/II, Vidyut Bhavan, Margao/ 5<sup>th</sup> Floor, CEE Office, Panaji
2. Superintending Engineer, Circle I/II/Commercial/Planning, Margao/Panaji/ CEE office , Panaji
3. Executive Engineer(Commercial)/Planning/EHV, Office of CEE, Panaji
4. Executive Engineer, Div I, Panaji/IV, Margao/V, Bicholim/VI, Mapusa/VII, Curcho-rem/X(EHV), Ponda/XI, Vasco/XVI, Margao/ XVII, Mapusa
5. Master file