

### 11 KV Feeder Outage for the Month of April 2026

Sr No	Town Name	Substation	Feeder Name	Feeder Code	Rura / Urban	No. of Consumers	No. of Outages	Duration Of Outage (Sec)	Average Hours of Steady Supply	Reason for power disruptions
1	MAPUSA	220/33KV Thivim	11KV Thivim Village	1S03-1105	RURAL				24:00:00	
2	MAPUSA	33KV Bicholim	11KV MAYEM	1S05-1107	RURAL				24:00:00	
3	MAPUSA	33KV Sanquelim	11KV Sanquelim	1S08-1102	URBAN				24:00:00	
4	MAPUSA	33KV Porvorim	11KV Porvorim Bazar	1S09-1109	RURAL				24:00:00	
5	MAPUSA	33KV Porvorim	Audit bhavan	1S09-1112	URBAN				24:00:00	
6	MAPUSA	33KV Valpoi	11KV Bhironda	1S11-1101	RURAL				24:00:00	
7	MAPUSA	33KV Candolim	11KV Candolim	1S12-1103	RURAL				24:00:00	
8	PANJIM	33KV Nagali hills (IT)	11KV BSNL	2S07-1105	URBAN		2	120	23:59:56	Manuel tripped to check supply on request of JE
9	PANJIM	33KV Madkai	11KV Industry I	2S15-1104	URBAN	71	4	1500	23:59:39	Breakdown/ transient Fault
10	MORMUGAO	33KV Bogda	HEADLAND	3S06-1101	URBAN	1906	9	35400	23:40:20	1) 33 KV incomer supply failed due to annual shutdown taken for maintenance 2)Incomer 1 tripped as 11KV, 2 nos. Feeders tripped on IDMT E/F, 3) 33KV Incomer I supply failed, 4) 33KV Incomer I supply failed, 5) 33KV Incomer I supply failed, Changeover at Verna sub station 6)33KV Incomer I supply failed, 7)Feeder tripped, malfunctioning of RMU, 8) 33KV Incomer I supply failed, 9) 33KV Incomer I supply failed
11	MARGAO	33KV Monte Hill	11KV Hari Mandir	4S03-1105	URBAN				24:00:00	
12	MARGAO	33KV Aquem	11KV Khareband	4S04-1101	URBAN		1	4020	22:53:00	OCR - Due to moisture same was cleaned and transformer charged
13	MARGAO	33KV Carmona	11KV Zalor	4S08-1101	RURAL				24:00:00	
14	MARGAO	33KV Cuncolim	11KV Dharmapur	4S09-1106	RURAL				24:00:00	
15	MARGAO	33KV Pontemol	11KV Bansai	4S13-1105	RURAL				24:00:00	
16	MAPUSA	33KV Mapusa	11KV Althino	1S04-1105	URBAN				24:00:00	
17	MAPUSA	33KV Mapusa	11KV Siolim	1S04-1112	RURAL				24:00:00	
18	MAPUSA	33KV Nachinola	11KV Aldona UG	1S06-1105	RURAL				24:00:00	
19	MAPUSA	33KV Nagoa	11KV AGARWADDO	1S07-1109	RURAL				24:00:00	
20	MAPUSA	33KV Saligao	11KV Betim	1S10-1105	RURAL				24:00:00	
21	MAPUSA	33 KV Anjuna	11KV Starco	1S15-1103	RURAL				24:00:00	
22	PANJIM	33KV Corlim	11KV New Ind.Estate	2S01-1103	URBAN				24:00:00	

23	PANJIM	33KV EDC	11KV Patto-Plaza	2S02-1103	URBAN	91			24:00:00	
24	PANJIM	33KV Bambolim	11KV Siridao	2S05-1101	RURAL				24:00:00	
25	PANJIM	33KV Nagali hills(IT Park)	11KV Adraar	2S07-1101	URBAN				24:00:00	
26	PANJIM	33KV Nagali hills(IT Park)	11KV CARANZALEM	2S07-1102	URBAN				24:00:00	
27	PANJIM	33KV Curti	11KV Shanti Nagar	2S10-1105	URBAN	5124	0	0	24:00:00	-
28	PANJIM	33KV Kundaim	11KV Mardol	2S14-1101	RURAL	4187	3	420	24:00:00	
29	MORMUGAO	110/33/11 KV	11KV IFB	3S04-1104	URBAN	1875	1	2400	23:20:00	E/f. 11kv Cable punctured
30	MARGAO	33KV Benaulim	11KV Colva	4S07-1102	RURAL		4	3840	23:57:56	M/T due to overload on inc 4, M/T to remove load & put on Nerul for load increased on 11KV Incomer 4, E/F
31	MARGAO	33KV Velim	11KV Dramapur	4S10-1105	RURAL				24:00:00	
32	MARGAO	33KV Canacona	11KV Agonda	4S11-1101	RURAL				24:00:00	
33	MARGAO	33KV Canacona	11KV Gaondongri	4S11-1104	RURAL				24:00:00	
34	MARGAO	33KV Pontemol	11KV Kakoda	4S13-1108	URBAN				24:00:00	
35	MARGAO	33KV Shigao	11KV Dhat	4S14-1103	RURAL				24:00:00	
36	MARGAO	33KV Xelpem	11KV Ponsamol	4S18-1102	RURAL				24:00:00	
37	MAPUSA	220/33KV Thivim	11KV Industrial Estate I (U/G)	1S03-1102	RURAL				24:00:00	
38	MAPUSA	33KV Mapusa	11KV Guirim	1S04-1109	RURAL				24:00:00	
39	MAPUSA	33KV Bicholim	11KV Karapur	1S05-1102	RURAL				24:00:00	
40	MAPUSA	33KV Nagoa	11KV Nagoa	1S07-1104	RURAL				24:00:00	
41	MAPUSA	33KV Porvorim	11KV Housing board	1S09-1106	RURAL				24:00:00	
42	MAPUSA	33KV Porvorim	Devashri Feeder	1S09-1113	URBAN				24:00:00	
43	MAPUSA	33KV Valpoi	11KV Nagargao	1S11-1104	RURAL				24:00:00	
44	MAPUSA	220KV Amona	11KV Maina	1S13-1101	RURAL				24:00:00	
45	MAPUSA	33 KV Anjuna	11KV chapora	1S15-1104	URBAN				24:00:00	
46	MAPUSA	33KV Sal	11KV Mencurem	1S16-1104	RURAL				24:00:00	
47	MAPUSA	33/11 KV GIS CALANGUTE	11KV Maria Rosa	1S18-1101	RURAL				24:00:00	
48	MAPUSA	33/11 KV GIS CALANGUTE	11KV Weena	1S18-1106	RURAL	2100	1	3000	23:10:00	E/f. 11kv Cable punctured
49	PANJIM	33KV Campal	11KV Ideal School	2S03-1106	URBAN	0			24:00:00	
50	PANJIM	33KV NIO	11KV Odxel	2S08-1102	URBAN				24:00:00	

51	PANJIM	33KV Dharbandora	11KV Sonarbag	2S11-1101	RURAL	1049	24	9240	21:26:00	1)MT to remove interlink and normalised feeder OK supply upto Sonarbag village DP near Marvaswada 2) EFR charge after open Nestle AB switch 3) MT to interlink with new Tisk trip & charge
52	PANJIM	33KV Bethora	11KV Bonbag	2S13-1103	RURAL	1169	4	720	23:48:00	1) Transient fault, Shutdown
53	PANJIM	33KV Kundaim	11KV Industry I	2S14-1103	URBAN	240	8	1980	23:59:52	Planned maintenance/Breakdown/ transient Fault
54	MORMUGAO	33KV Harbour	11KV Vasco city	3S01-1105	URBAN	3060	2	7800	23:55:40	Manual trip for tree cutting at Maharaj & Vegetable Market. Load normalized.
55	MORMUGAO	33KV Sancoale	11KV Sicgil	3S03-1104	RURAL	534	2	1620	23:59:06	To attend jumper
56	MORMUGAO	110/33/11 KV	11KV Quellosim	3S04-1111	RURAL		2	180	24:00:00	
57	MARGAO	33KV Cuncolim	11KV Balli	4S09-1103	RURAL				24:00:00	
58	MARGAO	33KV Poinguinim	11KV Khotigao	4S12-1103	RURAL				24:00:00	
59	MAPUSA	220/33KV Thivim	11KV Tivim	1S03-1108	RURAL				24:00:00	
60	MAPUSA	33KV Nagoa	11KV Arpora	1S07-1105	RURAL				24:00:00	
61	PANJIM	33KV EDC	11KV Kanaka	2S02-1107	URBAN	593	1	960	23:44:00	Tripped on O/C & E/F
62	PANJIM	33KV Bambolim	11KV Santacruz	2S05-1105	RURAL				24:00:00	
63	PANJIM	33KV Nagali hills(IT Park)	11KV MANIPAL	2S07-1106	URBAN				24:00:00	
64	PANJIM	33KV NIO	11KV Alto-Nagali	2S08-1106	URBAN	1605	1	1920	23:28:00	E/f. 11kv Cable punctured
65	PANJIM	33KV Colony	11KV Ponda II	2S10-1101	URBAN	3426	1	600	23:50:00	Transient fault
66	PANJIM	33KV Curti	11KV Ponda II	2S10-1101	URBAN		5	6240	23:56:32	Manuel tripped,to charge 33kv Candolim-1 circuit, over current,declared faulty (sairaj hotel flash over), Over current and earth fault
67	PANJIM	33KV Shiroda	11KV Shiroda Bazar	2S12-1102	RURAL	713	7	1020	23:43:00	1) Transient fault,Breakdown
68	MORMUGAO	33KV Harbour	11KV Harbour	3S01-1101	URBAN				24:00:00	
69	MORMUGAO	110/33/11 KV	11KV Lokmat	3S04-1108	URBAN		6	1320	23:38:00	
70	MORMUGAO	33KV Majorda	11KV Utorda	3S05-1103	RURAL			----	24:00:00	----
71	MORMUGAO	33KV Majorda	11KV Arrosim	3S05-1104	RURAL	1562	4	3360	23:59:26	11 KV Arossim Feeder tripped onOCR/EFR Line patrolling found dead cat hanging to H.T Line on pole after removing feeder charged holding (Behind Utorda Ground in Field)
72	MARGAO	33KV Aquem	11KV KHAREBAND	4S04-1109	RURAL				24:00:00	
73	MARGAO	33KV KRC	11KV MES	4S05-1103	RURAL				24:00:00	
74	MARGAO	33KV Carmona	11KV Cavellossim	4S08-1104	RURAL				24:00:00	
75	MARGAO	33KV Cuncolim	11KV Patten	4S09-1107	RURAL				24:00:00	
76	MARGAO	33KV Canacona	11KV Palolem	4S11-1105	URBAN				24:00:00	
77	MAPUSA	33KV Mapusa	11KV Market	1S04-1108	URBAN				24:00:00	

78	MAPUSA	33KV Bicholim	11KV IDC	1S05-1101	RURAL				24:00:00	
79	MAPUSA	33KV Nagoa	11KV Parra	1S07-1103	RURAL				24:00:00	
80	MAPUSA	33KV Porvorim	11KV Torda	1S09-1107	RURAL				24:00:00	
81	MAPUSA	33KV Porvorim	Highland Villa	1S09-1114	URBAN				24:00:00	
82	MAPUSA	220KV Amona	11KV Navelim	1S13-1102	RURAL				24:00:00	
83	MAPUSA	33/11 KV GIS CALANGUTE	11KV Calculo	1S18-1102	RURAL	2097	1	180	23:59:54	M/T for testing of Ammeter
84	PANJIM	33KV EDC	11KV Neugi Nagar	2S02-1105	URBAN	2019			24:00:00	
85	PANJIM	33KV Altinho	11KV Lydia Garden	2S04-1110	URBAN	1440			24:00:00	
86	PANJIM	33KV NIO	11KV Taligao	2S08-1108	URBAN				24:00:00	
87	PANJIM	33KV Bethora	11KV Nirankal	2S13-1102	RURAL	2384	21	3840	22:56:00	1) Transient fault,Shutdown
88	MORMUGAO	33KV Kadamba	11KV New Waddem	3S02-1101	URBAN	5854	2	4740	23:57:22	Manual trip for LT work near Sai Baba temple.
89	MORMUGAO	33KV Sancoale	11KV Cortalim	3S03-1105	RURAL	1833	1	4140	23:57:46	Over-current LT Transformer LA fault
90	MARGAO	33KV Monte Hill	11KV Lohia	4S03-1103	URBAN		1	1200	23:40:00	OCR & EFR
91	MARGAO	33KV KRC	11KV Navelim UG	4S05-1105	URBAN		4	6540	23:32:45	M/T for tree cutting
92	MARGAO	33KV Cuncolim	11KV Chinchinim	4S09-1104	RURAL				24:00:00	
93	MARGAO	33KV Poinguinim	11KV Poinguinim	4S12-1104	RURAL				24:00:00	
94	MAPUSA	33KV Pernem	11KV Dhargal	1S01-1105	RURAL				24:00:00	
95	MAPUSA	33KV Saligao	11KV Navy	1S10-1107	RURAL	2403	7	2460	23:59:39	M/T to interchange wiring of meter 'digimaster meter', O/C E/F ,M/T half load put on highland, M/T for planned shutdown, M/T on request of JE and Staff from GIS A/L to put AG fuse of Hotel Villa Alina centre, M/T on request of A/L
96	MAPUSA	33KV Valpoi	11KV Thana	1S11-1103	RURAL				24:00:00	
97	MAPUSA	33KV Candolim	11KV Ximer	1S12-1101	RURAL		4	4800	23:57:20	Manuel tripped for safety purpose, Manuel tripped to charge Candolim -1 circuit, Manuel tripped ,to put load on feeder
98	MAPUSA	33 KV Anjuna	11KV Temvi	1S15-1101	URBAN				24:00:00	
99	MAPUSA	33/11 KV GIS CALANGUTE	11KV Post Office	1S18-1103	RURAL				24:00:00	
100	PANJIM	33KV Corlim	11KV Kadamba	2S01-1110	RURAL				24:00:00	
101	PANJIM	33KV PILAR	11KV Neura	2S06-1101	RURAL				24:00:00	
102	PANJIM	33KV Shiroda	11KV Borim	2S12-1101	RURAL	5498	4	660	23:49:00	1) Transient fault,Breakdown
103	PANJIM	33KV Shiroda	11KV Torla Paz/ Vazangal	2S12-1104	RURAL	1755	7	120	23:58:00	1) Transient fault,Breakdown
104	MORMUGAO	33KV Kadamba	11KV Airport	3S02-1105	URBAN	2510	3	7680	23:55:44	EFR, Manual trip to attend 3 nos. of cut jumpers at Vidhya Mandir AB switch.
105	MORMUGAO	33KV Majorda	11KV Majorda	3S05-1102	RURAL			----	24:00:00	----
106	MARGAO	33KV Monte Hill	11KV Lohia-II	4S03-1107	URBAN				24:00:00	

107	MARGAO	33KV Canacona	11KV Gulem	4S11-1106	RURAL				24:00:00	
108	MARGAO	33KV Pontemol	11KV IDC	4S13-1103	RURAL				24:00:00	
109	MARGAO	33KV Shigao	11KV Collem	4S14-1101	RURAL				24:00:00	
110	MAPUSA	33KV Pernem	11KV Torse	1S01-1102	RURAL				24:00:00	
111	MAPUSA	33KV Mapusa	11KV Khorlim	1S04-1107	URBAN				24:00:00	
112	MAPUSA	33KV Porvorim	11KV Salai	1S09-1108	RURAL				24:00:00	
113	MAPUSA	33KV Porvorim	11KV GURUDWARA	1S09-1111	URBAN				24:00:00	
114	MAPUSA	33KV Saligao	11KV PILERNE (UG)	1S10-1110	RURAL				24:00:00	
115	MAPUSA	33KV Valpoi	11KV Dabose	1S11-1106	RURAL	2331	7	2040	23:58:52	O/C E/F
116	MAPUSA	33KV Sal	11KV Ibrampur	1S16-1102	RURAL				24:00:00	
117	PANJIM	33KV Altinho	11KV Tonca Miramar	2S04-1108	URBAN	1333			24:00:00	
118	PANJIM	33KV PILAR	11KV Agasaim	2S06-1102	RURAL				24:00:00	
119	PANJIM	33KV Bethora	11KV Shiroda/ dattagad	2S13-1101	RURAL	713	13	660	23:49:00	1)OCR after opening RMU at Neutrain and charge its hold
120	MORMUGAO	33KV Kadamba	11KV Vasco church	3S02-1102	URBAN	4483	1	2400	23:58:40	Manual trip, Shivam theatre's 1 no. AB switch belt replaced.
121	MORMUGAO	33KV Sancoale	11KV Vasco-II	3S03-1106	RURAL	2463	4	9180	23:55:04	Attended jumper on 4poles Chicalim,Feeder manually tripped due to Road Accident,Feeder manually tipped due to vehicle accident,HT conductor snap at assai dongri
122	MARGAO	33KV Monte Hill	11KV GVN1	4S03-1102	URBAN				24:00:00	
123	MARGAO	33KV Cuncolim	11KV IDC II	4S09-1101	RURAL				24:00:00	
124	MARGAO	33KV Poinguinim	11KV Loliem	4S12-1105	RURAL				24:00:00	
125	MAPUSA	33KV Pernem	11KV Sawal	1S01-1104	RURAL				24:00:00	
126	MAPUSA	33KV Tuem	11KV Industry	1S02-1101	URBAN				24:00:00	
127	MAPUSA	220/33KV Thivim	11KV Colvale	1S03-1104	RURAL				24:00:00	
128	MAPUSA	33KV Mapusa	11KV Duler	1S04-1102	URBAN				24:00:00	
129	MAPUSA	33KV Mapusa	11KV City	1S04-1103	RURAL				24:00:00	
130	MAPUSA	33KV Sanquelim	11KV Poriem	1S08-1101	RURAL				24:00:00	
131	MAPUSA	33KV Valpoi	11KV Saleli	1S11-1102	RURAL				24:00:00	
132	MAPUSA	33KV Candolim	11KV Highland	1S12-1106	RURAL				24:00:00	
133	MAPUSA	33 KV Anjuna	11KV vagator	1S15-1102	RURAL				24:00:00	
134	PANJIM	33KV EDC	11KV Old bus stand	2S02-1101	URBAN	741			24:00:00	
135	PANJIM	33KV Curti	11KV Durbhat	2S10-1106	RURAL	3300	3	240	23:56:00	Transient fault
136	PANJIM	33KV Madkai	11KV Karanzal	2S15-1103	RURAL	821	7	6720	23:59:52	Breakdown/ transient Fault
137	MORMUGAO	33KV Sancoale	11KV Cansualim	3S03-1102	RURAL	2789	3	7740	23:55:50	FeederTripped on Earth Fault,Feeder Manually tripped due to snapping of LT conductor at zuari nagar,To attend jumper
138	MORMUGAO	110/33/11 KV	11KV Verna	3S04-1101	RURAL		15	3960	24:00:00	

139	MORMUGAO	110/33/11 KV	11KV Nagoa	3S04-1106	RURAL		4	2220	24:00:00	
140	MARGAO	33KV Raia	11KV Curtorim	4S01-1105	RURAL				24:00:00	
141	MARGAO	33KV Fatorda	11KV Ambaji	4S02-1101	URBAN				24:00:00	
142	MARGAO	33KV Monte Hill	11KV Mutt	4S03-1106	URBAN		1	900	23:45:00	OCR & EFR - Cable puncture at Raghavendra load of 5 T/c put shift on 11kv Harimandir-2
143	MARGAO	33KV Aquem	11KV Margao I	4S04-1107	URBAN		10	7440	23:56:00	Manuel tripped, L/T staff on request of JE Anthony,work on DP,work done, Manuel tripped, L/T staff on request of JE Anthony,work on DP, Manuel tripped,to charge 33kv Candolim-1 circuit, Over current and earth fault. M/T - Pristine
144	MARGAO	33KV Nessai	11KV Goa Carbon	4S06-1104	URBAN		3	23460	21:49:40	Tripped on EFR. Full feeder patrolling done. No fault found
145	MARGAO	33KV Carmona	11KV Janoth Bazar	4S08-1102	URBAN				24:00:00	
146	MARGAO	33KV Cuncolim	11KV Cuncolim	4S09-1105	RURAL				24:00:00	
147	MARGAO	33KV Pontemol	11KV Panchwadi	4S13-1102	RURAL				24:00:00	
148	MARGAO	33KV Xelpem	11KV Malkarne	4S18-1104	RURAL				24:00:00	
149	MAPUSA	33KV Pernem	11KV Nagzar	1S01-1101	RURAL				24:00:00	
150	MAPUSA	33KV Tuem	11KV Morjim	1S02-1104	RURAL				24:00:00	
151	MAPUSA	220/33KV Thivim	11KV Industrial Estate	1S03-1107	URBAN				24:00:00	
152	MAPUSA	33KV Mapusa	11KV Sodiem	1S04-1111	RURAL				24:00:00	
153	MAPUSA	33KV Nagoa	11KV Sanqwadi	1S07-1106	RURAL				24:00:00	
154	MAPUSA	33KV Saligao	11KV Candolim church	1S10-1102	RURAL				24:00:00	
155	MAPUSA	33KV Saligao	11KV Shervani Calangute	1S10-1103	RURAL				24:00:00	
156	MAPUSA	33KV Pale	11KV Nanus	1S14-1101	RURAL				24:00:00	
157	MAPUSA	33KV Pale	11KV Kotumbi	1S14-1102	RURAL				24:00:00	
158	MAPUSA	33/11 KV GIS CALANGUTE	11KV Tivaiwaddo	1S18-1108	RURAL	3218	3	2340	23:58:45	Declared Steady, M/T RMU opened , O/C E/F
159	PANJIM	33KV Corlim	11KV Old Goa	2S01-1102	RURAL				24:00:00	
160	PANJIM	33KV Corlim	11KV Old Industry	2S01-1105	URBAN				24:00:00	
161	PANJIM	33KV Altinho	11KV Circuit House	2S04-1103	URBAN	569	2	2280	23:22:00	Tripped on O/C & E/F
162	PANJIM	33KV Bambolim	11KV MES	2S05-1102	RURAL				24:00:00	
163	PANJIM	33KV Nagali hills(IT Park)	11KV OITIYANT	2S07-1103	URBAN				24:00:00	
164	PANJIM	33KV Colony	11KV Rajiv Gandhi Kala Mandir	2S09-1106	URBAN	1352	5	1440	23:36:00	4-Transient fault,1-Break down
165	PANJIM	33KV Curti	11KV Sarvoiverem	2S10-1104	RURAL	3336	0	0	24:00:00	-

166	MORMUGAO	33KV Majorda	11KV Duguem	3S05-1105	RURAL			----	24:00:00	----
167	MORMUGAO	33KV Majorda	11KV Nuvem	3S05-1106	RURAL			----	24:00:00	----
168	MORMUGAO	33KV Bogda	ANTARTICA - Headland II	3S06-1104	URBAN	1661	8	33900	23:41:10	1) Feeder tripped on IDMT E/F, 2)33 KV incomer supply failed due to annual shutdown taken for maintenance, 3)33KV Incomer II supply failed, supply failed from Verna sub station, 4)33KV Incomer II supply failed, Changeover at Verna sub station, 5) 33KV Incomer II supply failed, 6) 33KV Incomer II supply failed, shutdown taken by Kadamba sub station due to incomer jumper loose contact/sparking, 7) 33 KV incomer II shutdown taken by sancoale sub station for tree cutting, 8)33KV Incomer II supply failed
169	MORMUGAO	33KV Bogda	MASJID	3S06-1105	RURAL	2220	11	38280	23:38:44	1) 33 KV incomer supply failed due to annual shutdown taken for maintenance 2)Feeder tripped on IDMT E/F, on checking found 11 KV breaker loose contact 3) 33KV Incomer I supply failed, 4) 33KV Incomer I supply failed, 5) 33KV Incomer I supply failed, Changeover at Verna sub station 6)33KV Incomer I supply 7)Feeder tripped on IDMT E/F, 8)33KV Incomer I supply failed, 9) Feeder tripped , fault at sewerage plant Baina, 10)33KV Incomer I supply failed, 11)Feeder tripped on IDMT EFR , reason: disc faulty at HT GRB sewerage Baina, section isolated and fault attended
170	MARGAO	33KV KRC	11KV Navelim	4S05-1101	RURAL		3	18180	22:19:00	Manually tripped to attend LT jumper near Navelim Bazaar
171	MARGAO	33KV KRC	11KV Mandopa	4S05-1102	RURAL		5	26100	22:33:00	Jumper cut near Mahalasa bakery
172	MARGAO	33KV Benaulim	11KV Betal Betim	4S07-1103	RURAL				24:00:00	
173	MARGAO	33KV Velim	11KV Kumbia bhat	4S10-1103	RURAL				24:00:00	
174	MARGAO	33KV Shigao	11KV Mollem	4S14-1102	RURAL				24:00:00	

175	MAPUSA	33KV Pernem	11KV Keri	1S01-1106	RURAL				24:00:00	
176	MAPUSA	33KV Tuem	11KV Mandrem	1S02-1102	RURAL				24:00:00	
177	MAPUSA	33KV Mapusa	11KV Industry	1S04-1101	URBAN				24:00:00	
178	MAPUSA	33KV Mapusa	11KV Karaswada	1S04-1104	URBAN				24:00:00	
179	MAPUSA	33KV Mapusa	11KV Parra	1S04-1113	RURAL				24:00:00	
180	MAPUSA	33KV Bicholim	11KV Lamgao	1S05-1112	RURAL	2726	1	120	23:59:56	O/C E/F
181	MAPUSA	33KV Nachinola	11KV Pomburpa	1S06-1101	RURAL	1892	3	480	23:59:45	M/T to normalize load, O/C E/F
182	MAPUSA	33KV Porvorim	11KV Malim	1S09-1104	RURAL				24:00:00	
183	PANJIM	33KV EDC	11KV BAL BHARTI	2S02-1108	URBAN		23	9600	23:54:50	Manuel tripped to charge Candolim -1 circuit, Manuel tripped as told by Thivim substation due to increase of load, Manuel tripped,for safety purpose ,requested by JE Agnelo, Manuel tripped,same closed and opened casa ventures and closed stood okay, Over current and earth fault,open main section stood ok, Manuel tripped,same closed and openedat saldhana stood ok,full feeder charged(fault not found)
184	MORMUGAO	33KV Kadamba	11KV Waddem Lake	3S02-1104	URBAN	2885	4	11340	23:53:42	OCR/EFR thrice charged declared faulty conductor snapped near Pai Hospital.
185	MORMUGAO	33KV Sancoale	11KV Sesa Goa	3S03-1101	URBAN	1484	3	7320	23:56:04	Feeder tripped on over-current relay, Feeder manually tripped to attend jumper, Cable punched at Dabolim damaged by P.W.D
186	MORMUGAO	110/33/11 KV	11KV SMARTLINK	3S04-1109	URBAN		3	3780	23:59:59	Earth fault & Manual tripping
187	MARGAO	33KV Fatorda	11KV Gogol	4S02-1106	RURAL		2	2280	23:41:00	M/T - Pristine servicing
188	MARGAO	33KV Aquem	11KV Davorlim	4S04-1106	RURAL				24:00:00	
189	MARGAO	33KV Nessai	11KV Chandor	4S06-1103	RURAL		2	2040	23:43:00	Manually tripped to open jumper on HT pole at Fatramoll area
190	MARGAO	33KV Benaulim	11KV Mobor	4S07-1104	RURAL				24:00:00	
191	MARGAO	33KV Velim	11KV Assolna	4S10-1101	RURAL				24:00:00	
192	MARGAO	33KV Poinguinim	11KV Link line	4S12-1101	RURAL				24:00:00	
193	MARGAO	33KV Xelpem	11KV Dando	4S18-1105	RURAL				24:00:00	
194	MAPUSA	33KV Tuem	11KV Tuem	1S02-1103	RURAL				24:00:00	
195	MAPUSA	220/33KV Thivim	11KV Power Grid	1S03-1103	RURAL				24:00:00	
196	MAPUSA	33KV Bicholim	11KV Pilgao	1S05-1104	RURAL				24:00:00	
197	MAPUSA	33KV Bicholim	11KV Bordem	1S05-1109	URBAN				24:00:00	
198	MAPUSA	33KV Sanquelim	11KV Honda	1S08-1104	RURAL				24:00:00	
199	MAPUSA	33KV Saligao	11KV Saligao	1S10-1104	RURAL				24:00:00	
200	MAPUSA	33KV Candolim	11KV Sinquerim	1S12-1105	RURAL				24:00:00	

201	MAPUSA	33KV Pale	11KV Barazen	1S14-1103	RURAL				24:00:00	
202	MAPUSA	33/11 KV GIS CALANGUTE	11KV Kamat	1S18-1107	RURAL				24:00:00	
203	PANJIM	33KV EDC	11KV Ribandar	2S02-1102	URBAN	1538	1	1020	23:43:00	Tripped on O/C & E/F
204	PANJIM	33KV Campal	11KV Market	2S03-1101	URBAN	1762			24:00:00	
205	PANJIM	33KV Altinho	11KV Inox	2S04-1102	URBAN	86			24:00:00	
206	PANJIM	33KV Altinho	11KV Campal	2S04-1105	URBAN	2086			24:00:00	
207	PANJIM	33KV Bambolim	11KV Mercedes	2S05-1104	RURAL				24:00:00	
208	PANJIM	33KV NIO	11KV Models	2S08-1101	URBAN				24:00:00	
209	PANJIM	33KV Curti	11KV Usgao	2S10-1102	RURAL	6106	12	16020	19:33:00	1) Transient fault,Breakdown
210	PANJIM	33KV Madkai	11KV Madkai	2S15-1102	RURAL	2001	13	3120	23:59:58	Transient Fault
211	MORMUGAO	110/33/11 KV	11KV Cortalim	3S04-1107	RURAL		17	3900	23:59:59	Earth fault & Manual tripping
212	MARGAO	33KV Raia	11KV Santamol	4S01-1103	RURAL				24:00:00	
213	MARGAO	33KV Fatorda	11KV Chowgule College	4S02-1103	URBAN		1	1140	23:41:00	Tripped on OCR & EFR ( Sasa t/c Faulty )
214	MARGAO	33KV Monte Hill	11KV Hari Mandir-II	4S03-1108	URBAN				24:00:00	
215	MARGAO	33KV Aquem	11KV Housing Board O/H	4S04-1103	URBAN				24:00:00	
216	MARGAO	33KV Aquem	11KV Margao III	4S04-1104	URBAN				24:00:00	
217	MARGAO	33KV Velim	11KV Chinchinim	4S10-1104	RURAL				24:00:00	
218	MARGAO	33KV Pontemol	11KV Dabal	4S13-1107	RURAL				24:00:00	
219	MARGAO	220/33/11KV Xeldem	11KV Xelvona	4S15-1101	RURAL	2221	4	10080	23:54:00	Due to 10 nos AB kit failed and one jumper cut and tree fallen on line
220	MAPUSA	33KV Pernem	11KV City	1S01-1103	RURAL				24:00:00	
221	MAPUSA	220/33KV Thivim	11KV Industrial	1S03-1101	URBAN				24:00:00	
222	MAPUSA	33KV Nagoa	11KV Calangute	1S07-1101	RURAL				24:00:00	
223	MAPUSA	33KV Porvorim	11KV Sangolda	1S09-1105	RURAL				24:00:00	
224	MAPUSA	33KV Saligao	11KV Gaurawaddo	1S10-1109	URBAN				24:00:00	
225	MAPUSA	33KV Valpoi	11KV City New	1S11-1105	RURAL				24:00:00	
226	MAPUSA	33KV Sal	11KV Kasarpal	1S16-1103	RURAL				24:00:00	
227	MAPUSA	33/11 KV GIS CALANGUTE	11KV Mark Memorial	1S18-1105	URBAN				24:00:00	
228	PANJIM	33KV Campal	11KV St. Inez	2S03-1107	URBAN	551			24:00:00	
229	PANJIM	33KV Altinho	11KV Cabo	2S04-1112	URBAN	796	1	600	23:50:00	Tripped on O/C
230	PANJIM	33KV PILAR	11KV Batim	2S06-1103	RURAL				24:00:00	
231	PANJIM	33KV NIO	11KV NIO	2S08-1103	URBAN				24:00:00	
232	PANJIM	33KV Colony	11KV Bazaar	2S09-1101	URBAN	2652	1	600	23:50:00	Transient fault
233	PANJIM	33KV Bethora	11KV Industrial	2S13-1104	URBAN	420	8	4320	22:48:00	Transient fault, Breakdown, Planned shutdown
234	PANJIM	33KV Kundaim	11KV Kundaim	2S14-1104	RURAL	2501	1	60	24:00:00	

235	MORMUGAO	33KV Kadamba	11KV Vasco city	3S02-1103	URBAN	1857	0	0	24:00:00	
236	MORMUGAO	33KV Sancoale	11KV Vasco-I	3S03-1103	URBAN	2369	7	18180	23:50:14	To attend jumper at Ranghavi estate, Planned shutdown for tree cutting, Feeder tripped on sensitive earth fault due to opening of AB switch jumper, Heavy rain Hollant beach side section faulty, To attend jumper on field AB swaitch
237	MORMUGAO	110/33/11 KV	11KV Oxynitro	3S04-1110	RURAL		3	4160	23:59:59	Earth fault & Manual tripping
238	MARGAO	33KV Fatorda	11KV Fatorda	4S02-1105	URBAN				24:00:00	
239	MARGAO	33KV Monte Hill	11KV GVN2	4S03-1101	URBAN				24:00:00	
240	MARGAO	33KV Cuncolim	11KV IDC I	4S09-1102	RURAL				24:00:00	
241	MARGAO	33KV Velim	11KV Betul	4S10-1102	RURAL				24:00:00	
242	MARGAO	33KV Poinguinim	11KV Marli Tirval	4S12-1102	RURAL				24:00:00	
243	MARGAO	33KV Pontemol	11KV Town 1	4S13-1101	URBAN				24:00:00	
244	MARGAO	33KV Rivona	11KV Maina	4S16-1101	RURAL				24:00:00	
245	MAPUSA	33KV Nagoa	11KV Baga	1S07-1107	RURAL				24:00:00	
246	MAPUSA	33KV Porvorim	11KV Soccorro	1S09-1101	RURAL				24:00:00	
247	MAPUSA	33KV Saligao	11KV Industry O/H	1S10-1106	URBAN				24:00:00	
248	MAPUSA	33KV Saligao	11KV Nerul	1S10-1108	RURAL				24:00:00	
249	MAPUSA	220/33KV Amona	11 KV Pissurlem IDC	1S13-1104	RURAL				24:00:00	
250	MAPUSA	33/11 KV GIS CALANGUTE	11KV Shivam	1S18-1104	RURAL				24:00:00	
251	PANJIM	33KV Corlim	11KV Molar	2S01-1106	RURAL				24:00:00	
252	PANJIM	33KV Campal	11KV City	2S03-1103	RURAL	4			24:00:00	
253	PANJIM	33KV Nagali hills(IT Park)	11KV STATUS	2S07-1104	URBAN				24:00:00	
254	PANJIM	33KV Colony	11KV Curti	2S09-1105	URBAN	707	29	4980	22:37:00	27-Transient fault,2-Break down
255	PANJIM	33KV Dharbandora	11KV Dharbandora	2S11-1104	RURAL	2453	33	6240	22:16:00	1)EFR 1 section open and charge its hold 2) MT service connection wire touch HT line near PKB DP 3) EFR open Dharbandora AB switch and charge OK
256	MORMUGAO	33KV Sancoale	11KV College	3S03-1107	RURAL	1168	2	4200	23:57:45	Cable Damaged, Cable faulty Damaged by MVR
257	MARGAO	33KV Benaulim	11KV Colva Exp	4S07-1107	URBAN				24:00:00	
258	MARGAO	220/33/11KV Xeldem	11KV Rivona	4S15-1102	RURAL	2528	11	21600	23:47:06	Because of birds and monkey activity in Rivona area and failure of AB cable termination kit
259	MARGAO	33KV Rivona	11KV Colomba	4S16-1103	RURAL				24:00:00	
260	MARGAO	33KV Xelpem	11KV Sanguem	4S18-1101	URBAN				24:00:00	
261	MAPUSA	33KV Tuem	11KV Ashvem Cable	1S02-1105	RURAL				24:00:00	

262	MAPUSA	33KV Mapusa	11KV Anjuna	1S04-1106	RURAL				24:00:00	
263	MAPUSA	33KV Mapusa	11KV Assagao	1S04-1110	RURAL				24:00:00	
264	MAPUSA	33KV Bicholim	11KV Ladphem	1S05-1103	RURAL				24:00:00	
265	MAPUSA	33KV Bicholim	11KV Narva	1S05-1106	RURAL				24:00:00	
266	MAPUSA	33KV Nachinola	11KV Moira	1S06-1103	RURAL				24:00:00	
267	MAPUSA	33KV Nachinola	11KV Bastora	1S06-1104	RURAL				24:00:00	
268	MAPUSA	33KV Sal	11KV Sal	1S16-1101	RURAL				24:00:00	
269	PANJIM	33KV Corlim	11KV Dhulapi	2S01-1101	RURAL				24:00:00	
270	PANJIM	33KV EDC	11KV Vidyut Bhawan	2S02-1104	URBAN	825			24:00:00	
271	PANJIM	33KV Altinho	11KV Alcon	2S04-1104	URBAN	1398			24:00:00	
272	PANJIM	33KV Bambolim	11KV Donapaula	2S05-1103	RURAL				24:00:00	
273	PANJIM	33KV Curti	11KV OPA	2S10-1103	RURAL				24:00:00	
274	PANJIM	33KV Kundaim	11KV Marcel	2S14-1102	RURAL	7814	8	780	24:00:00	
275	PANJIM	33KV Madkai	11KV Umdir	2S15-1101	RURAL	2014	11	3600	23:59:58	Breakdown/ transient Fault
276	MORMUGAO	110/33/11 KV	11KV Herald	3S04-1102	URBAN		8	3600	23:59:58	overcurrent , manual tripping
277	MORMUGAO	110/33/11 KV	11KV Jordan	3S04-1105	URBAN		7	1320	23:59:59	earth fault , overcurrent , manual tripping
278	MORMUGAO	33KV Majorda	11KV Ramesh Hotel	3S05-1101	URBAN			----	24:00:00	----
279	MARGAO	33KV Raia	11KV Raia	4S01-1101	RURAL				24:00:00	
280	MARGAO	33KV Raia	11KV Rachol	4S01-1104	RURAL				24:00:00	
281	MARGAO	33KV Fatorda	11KV Old market	4S02-1102	URBAN				24:00:00	
282	MARGAO	33KV Aquem	11KV Housing Board U/G	4S04-1102	RURAL				24:00:00	
283	MARGAO	33KV Aquem	11KV Malbhat	4S04-1105	URBAN				24:00:00	
284	MARGAO	33KV Nessai	11KV MIE	4S06-1101	RURAL				24:00:00	
285	MARGAO	33KV Carmona	11KV XIRO	4S08-1103	RURAL				24:00:00	
286	MARGAO	33KV Canacona	11KV Shristhal	4S11-1102	RURAL				24:00:00	
287	MARGAO	33KV Canacona	11KV Kindlem	4S11-1103	RURAL				24:00:00	
288	MARGAO	33KV Pontemol	11KV Town 2	4S13-1106	URBAN				24:00:00	
289	MARGAO	33KV Pontemol	11KV HODAR	4S13-1109	RURAL				24:00:00	
290	MARGAO	33KV Xelpem	11KV Barazan	4S18-1103	RURAL				24:00:00	
291	MAPUSA	33KV Bicholim	11KV Assnora	1S05-1110	RURAL				24:00:00	
292	MAPUSA	33KV Nagoa	11KV Sauntawada	1S07-1102	RURAL				24:00:00	
293	MAPUSA	33KV Nagoa	11KV Dharwadkar	1S07-1108	RURAL				24:00:00	
294	MAPUSA	33KV Porvorim	11KV Pundalic Nagar	1S09-1102	RURAL				24:00:00	
295	MAPUSA	220KV Amona	11KV Amona Marcel	1S13-1103	URBAN				24:00:00	
296	PANJIM	33KV Corlim	11KV Khumarjau	2S01-1107	RURAL				24:00:00	
297	PANJIM	33KV Corlim	11KV Diwar	2S01-1109	RURAL				24:00:00	
298	PANJIM	33KV EDC	11KV Ginger	2S02-1106	URBAN	405			24:00:00	
299	PANJIM	33KV Campal	11KV LA-Campal	2S03-1102	URBAN	3001			24:00:00	

300	PANJIM	33KV Campal	11KV Indoor Stadium	2S03-1104	URBAN	1023			24:00:00	
301	PANJIM	33KV Bambolim	11KV Chimbhel	2S05-1106	RURAL				24:00:00	
302	PANJIM	33KV NIO	11KV Rajbhawan	2S08-1104	URBAN				24:00:00	
303	PANJIM	33KV Colony	11KV Ponda-I	2S09-1104	URBAN	3873	8	8520	21:38:00	6-Transient fault,2-Break down
304	PANJIM	33KV Dharbandora	11KV Bondla	2S11-1103	RURAL	3137	14	5940	22:21:00	1)MT shutdown taken for cable work at Bondla 2)MT to remove interlink normalized feeder OK 3) MT to loop the Dabal Feeder supply upto
305	PANJIM	33KV Kundaim	11KV Industry III	2S14-1105	URBAN	131	1	67	23:59:59	Breakdown/ transient Fault/planned maintenace
306	MORMUGAO	33KV Harbour	11KV Vasco-I	3S01-1102	URBAN				24:00:00	
307	MORMUGAO	33KV Sancoale	11KV Industrial	3S03-1108	URBAN	585	0	0	24:00:00	Nil
308	MARGAO	33KV Fatorda	11KV Borda	4S02-1104	URBAN	2610	1	120	23:59:56	S/E/F & MT to attend redhot jumper at Swimming poll T/C
309	MARGAO	33KV Aquem	11KV AQUEM	4S04-1108	URBAN				24:00:00	
310	MARGAO	33KV Benaulim	11KV Benaulim	4S07-1101	RURAL				24:00:00	
311	MARGAO	33KV Benaulim	11KV Trinity	4S07-1106	RURAL		12	3720	23:58:00	Manuel tripped, due to load shedding, Over current ,declared faulty(Alphonso DtC,RMU, Over current,to take test charge
312	MARGAO	220/33/11KV Xeldem	11KV Quepem	4S15-1103	URBAN	4866	1	660	23:56:00	Because of conductor snapped and birds and monkey activity in Ambaulim area
313	MARGAO	33KV Rivona	11KV Sulcorna	4S16-1102	RURAL				24:00:00	
314	MARGAO	33KV Waddem	11KV Netravali	4S17-1102	RURAL				24:00:00	
315	MAPUSA	220/33KV Thivim	11KV Sirsaim	1S03-1106	RURAL				24:00:00	
316	MAPUSA	33KV Bicholim	11KV ADVALPAL	1S05-1105	RURAL				24:00:00	
317	MAPUSA	33KV Bicholim	11KV City	1S05-1108	RURAL				24:00:00	
318	MAPUSA	33KV Bicholim	11KV Kudchirem	1S05-1111	RURAL				24:00:00	
319	MAPUSA	33KV Nachinola	11KV Aldona OH	1S06-1102	RURAL				24:00:00	
320	MAPUSA	33KV Sanquelim	11KV Amona	1S08-1103	URBAN				24:00:00	
321	MAPUSA	33KV Porvorim	11KV RND	1S09-1103	RURAL				24:00:00	
322	MAPUSA	33KV Porvorim	11KV Chogum	1S09-1110	RURAL				24:00:00	
323	PANJIM	33KV Corlim	11KV Carambolim	2S01-1104	RURAL				24:00:00	
324	PANJIM	33KV Campal	11KV Adarsh	2S03-1105	URBAN	193			24:00:00	
325	PANJIM	33KV Altinho	11KV National	2S04-1101	URBAN	1244			24:00:00	
326	PANJIM	33KV Altinho	11KV Manoshanti	2S04-1106	URBAN	861			24:00:00	
327	PANJIM	33KV NIO	11KV NIO Colony	2S08-1105	URBAN	125			24:00:00	
328	PANJIM	33KV Colony	11KV Khadpabandh	2S09-1103	URBAN	4655	0	0	24:00:00	-
329	PANJIM	33KV Curti	Farmagudi	2S10-1108	URBAN	58			24:00:00	

330	PANJIM	33KV Kundaim	11KV Industry II	2S14-1106	URBAN	386	15	3840	23:57:56	M/T to open and close tata motors RMU, M/T to open Amit Capacitor stood Ok, M/T to close tata motors RMU, M/T to close Amit Capacitor stood Ok, C/O made at Tivim S/S, O/C E/F
331	PANJIM	33KV Madkai	11KV Industry II	2S15-1105	URBAN	274	9	16560	23:59:00	Breakdown/ transient Fault/planned maintenance
332	MORMUGAO	33KV Harbour	11KV Mangor	3S01-1104	URBAN	3901	5	30240	23:43:12	Manual trip, 1) Outgoing AB Switch open. 2)Mata school AB Switch open and full load shifted on Bramhastal feeder Bogda S/S. 3)Load Normalized.
333	MORMUGAO	33KV Sancoale	11KV Dabolim	3S03-1109	URBAN		5	2940	23:58:25	Over current and earth fault,Over current,to shift the load but over current,declared faulty
334	MORMUGAO	110/33/11 KV	11KV Industrial	3S04-1103	URBAN		4	3420	24:00:00	
335	MORMUGAO	33KV Bogda	Brahmasthal - vasco 1	3S06-1102	URBAN	4235	7	33780	23:41:14	1)33 KV incomer supply failed due to annual shutdown taken for maintenance, 2)33KV Incomer II supply failed, supply failed from Verna sub station, 3)33KV Incomer II supply failed, Changeover at Verna sub station, 4)33KV Incomer II supply failed, 5)33KV Incomer II supply failed, shutdown taken by Kadamba sub station due to incomer jumper loose contact/sparking, 6) 33 KV incomer II shutdown taken by sancoale sub station for tree cutting, 7)33KV Incomer II supply failed
336	MORMUGAO	33KV Bogda	HARBOUR	3S06-1103	URBAN	953	8	33600	23:41:20	1) 33 KV incomer supply failed due to annual shutdown taken for maintenance 2)Feeder tripped on IDMT E/F, on checking found 11 KV breaker loose contact, 3) 33KV Incomer I supply failed, 4) 33KV Incomer I supply failed, 5) 33KV Incomer I supply failed, Changeover at Verna sub station 6)33KV Incomer I supply failed, 7)33KV Incomer I supply failed, 8)33KV Incomer I supply failed
337	MARGAO	33KV Raia	11KV Loutalim	4S01-1102	RURAL		1	1800 sec	23:45:00	Monkey fallen on transformer at Gaoncho marg
338	MARGAO	33KV Monte Hill	11KV Adarsh	4S03-1104	URBAN				24:00:00	

339	MARGAO	33KV Nessai	11KV Paroda	4S06-1102	RURAL		4	30300	21:53:45	M/T to open jumper near Canara Bank in Menezes Bhat area for contractor's work purpose
340	MARGAO	33KV Benaulim	11KV Varca	4S07-1105	RURAL				24:00:00	
341	MARGAO	33KV Pontemol	11KV Kalay	4S13-1104	RURAL				24:00:00	
342	MARGAO	220/33/11KV Xeldem	11KV Assolda	4S15-1104	RURAL	1695	2	1920	23:58:54	11KV GOAB switch unit failed at Baag transformer
343	MARGAO	33KV Waddem	11KV Bhati	4S17-1101	RURAL				24:00:00	