

11 KV Feeder Outage for the Month of May 2026

Sr No	Town Name	Substation	Feeder Name	Feeder Code	Rural / Urban	Number of Consumers	Number of Outages	Duration Of Outage (Sec)	Average Hours of Steady Supply	Reason for power disruptions
1	MAPUSA	220/33KV Thivim	11KV Thivim Village	1S03-1105	RURAL	2158	2	2880	23:12:00	1) Tripped on O/C 2) Tripped on O/C, E/F
2	MAPUSA	33KV Bicholim	11KV MAYEM	1S05-1107	RURAL	756	4	6620	23:56:26	MANUAL TRIP to open jumper work at 3top mining sesa on narva feeder
3	MAPUSA	33KV Sanquelim	11KV Sanquelim	1S08-1102	URBAN	12788	3	61200	23:26:00	Interruption due to failure of power transformer at 220kv amona substation
4	MAPUSA	33KV Porvorim	11KV Porvorim Bazar	1S09-1109	RURAL				24:00:00	
5	MAPUSA	33KV Porvorim	Audit bhavan	1S09-1112	URBAN				24:00:00	
6	MAPUSA	33KV Valpoi	11KV Bhironda	1S11-1101	RURAL	680	6	55860	21:24:50	Tree cutting, Major Fault at Amona SS
7	MAPUSA	33KV Candolim	11KV Candolim	1S12-1103	RURAL	2730	7	56040	21:46:34	Tree cutting, Major Fault at Amona SS
8	PANJIM	33KV Nagali hills (IT Park)	11KV BSNL	2S07-1105	URBAN	1580	7	61200	21:34:17	Tree cutting, Major Fault at Amona SS
9	PANJIM	33KV Madkai	11KV Industry I	2S15-1104	URBAN	2	2	55320	16:19:00	Tree cutting, Major Fault at Amona SS

10	MORMUGAO	33KV Bogda	HEADLAND	3S06-1101	URBAN	1906	21	20640	23:49:00	1)33KV Incomer I supply failed, supply failed from Verna S/S, 2)33KV Incomer I supply failed, supply failed from Verna S/S, 3) 33KV Incomer I supply failed, supply failed from Verna S/S, 4)33KV Incomer I supply failed, supply failed from Verna S/S, 5) 33KV Incomer I supply failed, supply failed from Verna S/S, 6) 33KV Incomer I supply failed, supply failed from Verna S/S, 7) 33KV Incomer I supply failed, supply failed from Verna S/S, 8) 33KV Incomer I supply failed, supply failed from Verna S/S, 9) 33KV Incomer I supply failed, supply failed from Verna S/S, 110 disc failed; 10) 33KV Incomer I supply failed, supply failed from Verna S/S, 11)33KV Incomer I supply failed, supply failed from Verna S/S, 12) Feeder tripped on IDMT E/F, 13) 33KV Incomer I supply failed, supply failed from Verna S/S, 14) 33KV Incomer I supply failed, supply failed from Verna S/S, 15) 33KV Incomer I supply failed, supply failed from Verna S/S, 16) Feeder tripped on IDMT E/F,cable feeding from RMU to transformer caught fire and cable was damaged, the faulty section was isolated and feeder charged 17) 33KV Incomer I supply failed, supply failed from Verna S/S, 18) 33KV Incomer I supply failed, supply failed from Verna S/S, 19)33KV Incomer I supply failed, supply failed from Verna S/S, 20) Feeder manually tripped, shutdown was taken to replace HG fuse of garbage treatment plant, 21) 33KV Incomer I supply failed, reason: due to snake found on PT
11	MARGAO	33KV Monte Hill	11KV Hari Mandir	4S03-1105	URBAN	6380	7	56580	21:45:17	Tree cutting, Major Fault at Amona SS
12	MARGAO	33KV Aquem	11KV Khareband	4S04-1101	URBAN		0	0	24:00:00	
13	MARGAO	33KV Carmona	11KV Zalor	4S08-1101	RURAL				24:00:00	
14	MARGAO	33KV Cuncolim	11KV Dharmapur	4S09-1106	RURAL				24:00:00	
15	MARGAO	33KV Pontemol	11KV Bansai	4S13-1105	RURAL	4480	1	2100	23:58:50	Emergency Shutdown taken to attend Red HoT at Pontemol Sub-station 11 KV Yard.
16	MAPUSA	33KV Mapusa	11KV Althino	1S04-1105	URBAN				24:00:00	
17	MAPUSA	33KV Mapusa	11KV Siolim	1S04-1112	RURAL	4915	14	231	23:30:00	Load Shedding, 33KV Mapusa II Circuit over load
18	MAPUSA	33KV Nachinola	11KV Aldona UG	1S06-1105	RURAL				24:00:00	
19	MAPUSA	33KV Nagoa	11KV AGARWADDO	1S07-1109	RURAL				24:00:00	
20	MAPUSA	33KV Saligao	11KV Betim	1S10-1105	RURAL				24:00:00	
21	MAPUSA	33 KV Anjuna	11KV Starco	1S15-1103	RURAL				24:00:00	
22	PANJIM	33KV Corlim	11KV New Ind.Estate	2S01-1103	URBAN				24:00:00	
23	PANJIM	33KV EDC	11KV Patto-Plaza	2S02-1103	URBAN	91			24:00:00	
24	PANJIM	33KV Bambolim	11KV Siridao	2S05-1101	RURAL	2192	1	1500	23:35:00	Tripped on E/F relay,Cable joint failure
25	PANJIM	33KV Nagali hills(IT Park)	11KV Adraar	2S07-1101	URBAN				24:00:00	

26	PANJIM	33KV Nagali hills(IT Park)	11KV CARANZALEM	2S07-1102	URBAN				24:00:00	
27	PANJIM	33KV Curti	11KV Shanti Nagar	2S10-1105	URBAN	5143	4	10380	21:07:00	1-Transient faults 3-Breakdown
28	PANJIM	33KV Kundaim	11KV Mardol	2S14-1101	RURAL	4198	43	48240	10:36:00	Breakdown/ transient Fault/Planned Maintenace/To servicing braker
29	MORMUGAO	110/33/11 KV Verna	11KV IFB	3S04-1104	URBAN		4	342.00	23:59:48	Feeder declared Faulty, hence Changeover initiated.
30	MARGAO	33KV Benaulim	11KV Colva	4S07-1102	RURAL				24:00:00	
31	MARGAO	33KV Velim	11KV Dramapur	4S10-1105	RURAL				24:00:00	
32	MARGAO	33KV Canacona	11KV Agonda	4S11-1101	RURAL				24:00:00	
33	MARGAO	33KV Canacona	11KV Gaondongri	4S11-1104	RURAL				24:00:00	
34	MARGAO	33KV Pontemol	11KV Kakoda	4S13-1108	URBAN	1568	1	2100	23:58:50	Emergency Shutdown taken to attend Bansai Feeder Red Hot 2 Nos at Pontemol Sub-station.
35	MARGAO	33KV Shigao	11KV Dhat	4S14-1103	RURAL	861	13	50580	23:31:54	
36	MARGAO	33KV Xelpem	11KV Ponsamol	4S18-1102	RURAL	2179	8	13080	23:59:01	Due to frequent failure of AB Cable terminations kit, AB Cable puncture, tree fallen fallen on line, pole damaged due to tree fallen
37	MAPUSA	220/33KV Thivim	11KV Industrial Estate I (U/G)	1S03-1102	RURAL				24:00:00	
38	MAPUSA	33KV Mapusa	11KV Guirim	1S04-1109	RURAL				24:00:00	
39	MAPUSA	33KV Bicholim	11KV Karapur	1S05-1102	RURAL	2950	3	61200	23:26:00	Interruption due to failure of power transformer at 220kv amona substation
40	MAPUSA	33KV Nagoa	11KV Nagoa	1S07-1104	RURAL				24:00:00	
41	MAPUSA	33KV Porvorim	11KV Housing board	1S09-1106	RURAL				24:00:00	
42	MAPUSA	33KV Porvorim	Devashri Feeder	1S09-1113	URBAN				24:00:00	
43	MAPUSA	33KV Valpoi	11KV Nagargao (New)	1S11-1104	RURAL	2730	7	56040	21:46:34	Tree cutting, Major Fault at Amona SS
44	MAPUSA	220KV Amona	11KV Maina	1S13-1101	RURAL				24:00:00	
45	MAPUSA	33 KV Anjuna	11KV chapora	1S15-1104	URBAN				24:00:00	
46	MAPUSA	33KV Sal	11KV Mencurem	1S16-1104	RURAL	644	2	5452	23:57:04	To attend jumper cut on pole.
47	MAPUSA	33/11 KV GIS CALANGUTE	11KV Maria Rosa	1S18-1101	RURAL		7	14940	23:51:58	Manuel tripped for safety purpose,Manuel tripped,inter linked RMU with Post office feeder and VCB servicing,Manuel tripped ,to attend red hot, Manuel tripped due to load shedding
48	MAPUSA	33/11 KV GIS CALANGUTE	11KV Weena	1S18-1106	RURAL				24:00:00	
49	PANJIM	33KV Campal	11KV Ideal School	2S03-1106	URBAN	0			24:00:00	
50	PANJIM	33KV NIO	11KV Odxel	2S08-1102	URBAN				24:00:00	
51	PANJIM	33KV Dharbandora	11KV Sonarbag	2S11-1101	RURAL	1050	89	24360	17:14:00	Transient Fault, Breakdown
52	PANJIM	33KV Bethora	11KV Bonbag	2S13-1103	RURAL	1171	2	7140	22:01:00	Transient Fault, Breakdown, Planned Shut down
53	PANJIM	33KV Kundaim	11KV Industry I	2S14-1103	URBAN	241	18	48300	10:35:00	Breakdown/ transient Fault/Planned Maintenace/To servicing braker
54	MORMUGAO	33KV Harbour	11KV Vasco city	3S01-1105	URBAN	3060	5	30180	23:44:18	Manual trip, outgoing and incoming AB switch closed and feeder charged.

55	MORMUGAO	33KV Sancoale	11KV Sicgil	3S03-1104	RURAL	534	1	9000	23:55:00	Cable Faulty From Nalux RMU to Zenith RMU
56	MORMUGAO	110/33/11 KV Verna	11KV Quellosim	3S04-1111	RURAL		2	3948.00	23:57:48	Feeder found faulty, hence manually tripped.
57	MARGAO	33KV Cuncolim	11KV Balli	4S09-1103	RURAL				24:00:00	
58	MARGAO	33KV Poinguinim	11KV Khotigao	4S12-1103	RURAL				24:00:00	
59	MAPUSA	220/33KV Thivim	11KV Tivim	1S03-1108	RURAL				24:00:00	
60	MAPUSA	33KV Nagoa	11KV Arpora	1S07-1105	RURAL				24:00:00	
61	PANJIM	33KV EDC	11KV Kanaka	2S02-1107	URBAN	593			24:00:00	
62	PANJIM	33KV Bambolim	11KV Santacruz	2S05-1105	RURAL				24:00:00	
63	PANJIM	33KV Nagali hills(IT Park)	11KV MANIPAL	2S07-1106	URBAN				24:00:00	
64	PANJIM	33KV NIO	11KV Alto-Nagali	2S08-1106	URBAN				24:00:00	
65	PANJIM	33KV Colony	11KV Ponda II	2S10-1101	URBAN	3431	0	0	24:00:00	-
66	PANJIM	33KV Curti	11KV Ponda II	2S10-1101	URBAN				24:00:00	
67	PANJIM	33KV Shiroda	11KV Shiroda Bazar	2S12-1102	RURAL	1759	14	4020	22:53:00	Transient Fault, Breakdown, Planned Shut down
68	MORMUGAO	33KV Harbour	11KV Harbour	3S01-1101	URBAN				24:00:00	
69	MORMUGAO	110/33/11 KV Verna	11KV Lokmat	3S04-1108	URBAN		21	2787.00	23:58:27	Feeder found faulty, hence manually tripped.
70	MORMUGAO	33KV Majorda	11KV Utorda	3S05-1103	RURAL		-	-	24:00:00	-
71	MORMUGAO	33KV Majorda	11KV Arrosim	3S05-1104	RURAL	1563	4	2100	23:59:39	Feeder tripped upon triggering of OCR. Hence, Cansaulim Bazar AB Switch was opened, following which feeder was charged and it stood OK. As a preventive measure, overall line patrolling was carried out by line staff, and it was found that the reason behind OCR trigger was mango tree branch that had fallen on the line. Therefore, the said branch was cleared from the line. Thereafter, the opened AB switch was closed and entire feeder was charged, that stood OK.
72	MARGAO	33KV Aquem	11KV KHAREBAND II	4S04-1109	RURAL		4	4140	23:42:45	Tripped on Earth Fault Relay
73	MARGAO	33KV KRC	11KV MES	4S05-1103	RURAL		1	26280	16:42:00	Half feeder was on. Pin insulator faulty and jumper attended.
74	MARGAO	33KV Carmona	11KV Cavellossim	4S08-1104	RURAL				24:00:00	
75	MARGAO	33KV Cuncolim	11KV Patten	4S09-1107	RURAL				24:00:00	
76	MARGAO	33KV Canacona	11KV Palolem	4S11-1105	URBAN				24:00:00	
77	MAPUSA	33KV Mapusa	11KV Market	1S04-1108	URBAN				24:00:00	
78	MAPUSA	33KV Bicholim	11KV IDC	1S05-1101	RURAL	325	0	0	24:00:00	N.A
79	MAPUSA	33KV Nagoa	11KV Parra	1S07-1103	RURAL				24:00:00	
80	MAPUSA	33KV Porvorim	11KV Torda	1S09-1107	RURAL				24:00:00	
81	MAPUSA	33KV Porvorim	Highland Villa	1S09-1114	URBAN				24:00:00	
82	MAPUSA	220KV Amona	11KV Navelim	1S13-1102	RURAL				24:00:00	
83	MAPUSA	33/11 KV GIS CALANGUTE	11KV Calculo	1S18-1102	RURAL				24:00:00	
84	PANJIM	33KV EDC	11KV Neugi Nagar	2S02-1105	URBAN	2019	2	1110	23:01:00	1.Tripped on O/C and E/F 2. Tripped on O/C & E/F, flashover at Jairam Complex Transformer side.
85	PANJIM	33KV Altinho	11KV Lydia Garden	2S04-1110	URBAN	1440			24:00:00	

86	PANJIM	33KV NIO	11KV Taligao	2S08-1108	URBAN				24:00:00	
87	PANJIM	33KV Bethora	11KV Nirankal	2S13-1102	RURAL	2388	2	2340	23:21:00	Transient Fault, Breakdown, Planned Shut down
88	MORMUGAO	33KV Kadamba	11KV New Waddem	3S02-1101	URBAN	5854	2	16260	23:51:30	Manual trip to attend cut jumper near Gazi Abs.
89	MORMUGAO	33KV Sancoale	11KV Cortalim	3S03-1105	RURAL	1833	7	35460	23:40:56	Coconut palm leave fallen on on line at Kudwa, Metal part of Disc Faulty, Pin Insulator fail, conductor snap at sub-station outside, Planned shutdown, Petrolling, Disc replaced at Sancoale Panchayat
90	MARGAO	33KV Monte Hill	11KV Lohia	4S03-1103	URBAN		0	0	24:00:00	
91	MARGAO	33KV KRC	11KV Navelim UG	4S05-1105	URBAN		21	46920	23:22:46	M/T for tree cutting
92	MARGAO	33KV Cuncolim	11KV Chinchinim	4S09-1104	RURAL				24:00:00	
93	MARGAO	33KV Poinguinim	11KV Poinguinim	4S12-1104	RURAL				24:00:00	
94	MAPUSA	33KV Pernem	11KV Dhargal	1S01-1105	RURAL	4015	2	3645	23:08:00	Tree fallen on line
95	MAPUSA	33KV Saligao	11KV Navy	1S10-1107	RURAL				24:00:00	
96	MAPUSA	33KV Valpoi	11KV Thana	1S11-1103	RURAL	1580	7	61200	21:34:17	Tree cutting, Major Fault at Amona SS
97	MAPUSA	33KV Candolim	11KV Ximer	1S12-1101	RURAL				24:00:00	
98	MAPUSA	33 KV Anjuna	11KV Temvi	1S15-1101	URBAN	-	-	-	24:00:00	
99	MAPUSA	33/11 KV GIS CALANGUTE	11KV Post Office	1S18-1103	RURAL				24:00:00	
100	PANJIM	33KV Corlim	11KV Kadamba	2S01-1110	RURAL				24:00:00	
101	PANJIM	33KV PILAR	11KV Neura	2S06-1101	RURAL	2230	1	720	23:48:00	Tripped on O/C relay
102	PANJIM	33KV Shiroda	11KV Borim	2S12-1101	RURAL	5514	8	1620	23:33:00	Transient Fault, Planned Shut down
103	PANJIM	33KV Shiroda	11KV Torla Paz/ Vazangal	2S12-1104	RURAL	2132	2	540	23:51:00	Transient Fault, Planned Shut down
104	MORMUGAO	33KV Kadamba	11KV Airport	3S02-1105	URBAN	2510	3	25620	23:46:42	Declared faulty on EFR/OCR, jumper was touching to stay wire of Vidya Mandir section AB switch and provided gap between jumper and stay wire.
105	MORMUGAO	33KV Majorda	11KV Majorda	3S05-1102	RURAL		-	-	24:00:00	-
106	MARGAO	33KV Monte Hill	11KV Lohia-II	4S03-1107	URBAN		0	0	24:00:00	
107	MARGAO	33KV Canacona	11KV Gulem	4S11-1106	RURAL				24:00:00	
108	MARGAO	33KV Pontemol	11KV IDC	4S13-1103	RURAL	136	0	0	24:00:00	
109	MARGAO	33KV Shigao	11KV Collem	4S14-1101	RURAL	1244	7	37860	23:39:00	Transient Fault, Planned Shut down
110	MAPUSA	33KV Pernem	11KV Torse	1S01-1102	RURAL	3597	8	32436	22:48:00	Tree branch fallen on line, insulator failure, jumper open
111	MAPUSA	33KV Mapusa	11KV Khorlim	1S04-1107	URBAN				24:00:00	
112	MAPUSA	33KV Porvorim	11KV Salai	1S09-1108	RURAL				24:00:00	
113	MAPUSA	33KV Porvorim	11KV GURUDWARA	1S09-1111	URBAN				24:00:00	
114	MAPUSA	33KV Saligao	11KV PILERNE (UG)	1S10-1110	RURAL		7	7260	23:56:06	O/C E/F,M/T RMU opened at primary school,M/T for safety purpose to work on 11KV Saligao Feeder
115	MAPUSA	33KV Valpoi	11KV Dabose	1S11-1106	RURAL	2	2	55320	16:19:00	Tree cutting, Major Fault at Amona SS
116	MAPUSA	33KV Sal	11KV Ibrampur	1S16-1102	RURAL	375	2	6800	23:56:21	MANUAL TRIP for tree cutting purpose
117	PANJIM	33KV Altinho	11KV Tonca Miramar	2S04-1108	URBAN	1333			24:00:00	
118	PANJIM	33KV PILAR	11KV Agasaim	2S06-1102	RURAL	3305	2	780	23:47:00	M/T, replacement of HG fuse
119	PANJIM	33KV Bethora	11KV Shiroda detanged	2S13-1101	RURAL	714	10	5520	22:28:00	Planned Shut down
120	MORMUGAO	33KV Kadamba	11KV Vasco church	3S02-1102	URBAN	4483	4	28620	23:45:06	Manual trip due to Verenkar AB switch twice charged and opened.

121	MORMUGAO	33KV Sancoale	11KV Vasco-II	3S03-1106	RURAL	2463	6	35400	23:40:58	Tree branch fallen on line and attended jumper, Tree branches tochiing double circuit at vales, Jumper attended on Chicalim 4 pole structure, Conductor snap at MES college, Petrolling was done but no fault was found, Planned shutdown
122	MARGAO	33KV Monte Hill	11KV GVN1	4S03-1102	URBAN		1	1140	23:41:00	M/T - Due to overload at Verna S/s
123	MARGAO	33KV Cuncolim	11KV IDC II	4S09-1101	RURAL				24:00:00	
124	MARGAO	33KV Poinguinim	11KV Loliem	4S12-1105	RURAL				24:00:00	
125	MAPUSA	33KV Pernem	11KV Sawal	1S01-1104	RURAL	1030	3	3607	23:38:00	To attend jumper, conductor snapped
126	MAPUSA	33KV Tuem	11KV Industry	1S02-1101	URBAN	452	7	18025	23:14:00	MT
127	MAPUSA	220/33KV Thivim	11KV Colvale	1S03-1104	RURAL	2862	1	1740	23:31:00	1)E/F D/Faulty informed Nachinola Substation S.O Majil. Charged after opening Railway ABS. Stood ok.
128	MAPUSA	33KV Mapusa	11KV Duler	1S04-1102	URBAN				24:00:00	
129	MAPUSA	33KV Mapusa	11KV City	1S04-1103	RURAL				24:00:00	
130	MAPUSA	33KV Sanquelim	11KV Poriem	1S08-1101	RURAL	9314	3	61200	23:26:00	Interruption due to failure of power transformer at 220kv amona substation
131	MAPUSA	33KV Valpoi	11KV Saleli	1S11-1102	RURAL	3205	4	57120	20:02:00	Tree cutting, Major Fault at Amona SS
132	MAPUSA	33KV Candolim	11KV Highland	1S12-1106	RURAL				24:00:00	
133	MAPUSA	33 KV Anjuna	11KV vagator	1S15-1102	RURAL	-	-	-	24:00:00	
134	PANJIM	33KV EDC	11KV Old bus stand	2S02-1101	URBAN	741			24:00:00	
135	PANJIM	33KV Curti	11KV Durbhat	2S10-1106	RURAL	3302	5	1200	23:40:00	Transient Faults
136	PANJIM	33KV Madkai	11KV Karanzal	2S15-1103	RURAL	822	12	4500	22:45:00	Breakdown/ transient Fault/Planned Maintenace/To servicing braker
137	MORMUGAO	33KV Sancoale	11KV Cansualim	3S03-1102	RURAL	2789	5	42900	23:36:56	Shutdown taken by Majorda Staff, Attended jumper in yard, Petrolling , Casaulim Church Section Faulty due to conductor snap, Goa Section side tree branches touching
138	MORMUGAO	110/33/11 KV Verna	11KV Verna	3S04-1101	RURAL		4	4297.00	23:57:37	Feeder found faulty, hence manually tripped.
139	MORMUGAO	110/33/11 KV Verna	11KV Nagoa	3S04-1106	RURAL		9	4761.00	23:57:21	Feeder declared Faulty, hence Changeover initiated.
140	MARGAO	33KV Raia	11KV Curtorim	4S01-1105	RURAL				24:00:00	
141	MARGAO	33KV Fatorda	11KV Ambaji	4S02-1101	URBAN		1	2100	23:25:00	M/T for load shading purpose
142	MARGAO	33KV Monte Hill	11KV Mutt	4S03-1106	URBAN		1	1680	23:32:00	M/T - Due to overload at Verna S/s
143	MARGAO	33KV Aquem	11KV Margao I	4S04-1107	URBAN		0	0	24:00:00	
144	MARGAO	33KV Nessai	11KV Goa Carbon	4S06-1104	URBAN		7	9780	23:36:43	Heavy rain and wind
145	MARGAO	33KV Carmona	11KV Janoth Bazar	4S08-1102	URBAN				24:00:00	
146	MARGAO	33KV Cuncolim	11KV Cuncolim	4S09-1105	RURAL				24:00:00	
147	MARGAO	33KV Pontemol	11KV Panchwadi	4S13-1102	RURAL	3115	3	5220	23:57:06	Manual trippings, I/C supply failure , transient faults
148	MARGAO	33KV Xelpem	11KV Malkarne	4S18-1104	RURAL				24:00:00	
149	MAPUSA	33KV Pernem	11KV Nagzar	1S01-1101	RURAL	3676	12	43232	22:58:00	Tree branch fallen on line, insulator failure, jumper open,
150	MAPUSA	33KV Tuem	11KV Morjim	1S02-1104	RURAL	3077	6	269	23:30:00	OCR phase tripped on 252 Amps charge after opening HT Consumer, Outgoing E/F open DTC & test charge between tembwada to khennir but tripped, Planned Shutdown
151	MAPUSA	220/33KV Thivim	11KV Industrial Estate II (U/G)	1S03-1107	URBAN				24:00:00	
152	MAPUSA	33KV Mapusa	11KV Sodiem	1S04-1111	RURAL	1494	5	148	23:30:00	AB Switch repair, Block bet found on line, Load shedding

153	MAPUSA	33KV Nagoa	11KV Sanqwadi	1S07-1106	RURAL				24:00:00	
154	MAPUSA	33KV Saligao	11KV Candolim oburob	1S10-1102	RURAL				24:00:00	
155	MAPUSA	33KV Saligao	11KV Shervani Calangute	1S10-1103	RURAL				24:00:00	
156	MAPUSA	33KV Pale	11KV Nanus	1S14-1101	RURAL	1964	1	120	23:59:56	Sparking observed on tale matha
157	MAPUSA	33KV Pale	11KV Kotumbi	1S14-1102	RURAL	607	1	60	23:59:58	Changeover of load
158	MAPUSA	33/11 KV GIS CALANGUTE	11KV Tivaiwaddo	1S18-1108	RURAL				24:00:00	
159	PANJIM	33KV Corlim	11KV Old Goa	2S01-1102	RURAL				24:00:00	
160	PANJIM	33KV Corlim	11KV Old Industry	2S01-1105	URBAN				24:00:00	
161	PANJIM	33KV Altinho	11KV Circuit House	2S04-1103	URBAN	569			24:00:00	
162	PANJIM	33KV Bambolim	11KV MES	2S05-1102	RURAL	2583	1	1260	23:39:00	Tripped on E/F relay,Faulty Straight joint
163	PANJIM	33KV Nagali hills(IT Park)	11KV OITIYANT	2S07-1103	URBAN				24:00:00	
164	PANJIM	33KV Colony	11KV Rajiv Gandhi Kala Mandir	2S09-1106	URBAN	1353	5	1020	23:43:00	Transient Faults
165	PANJIM	33KV Curti	11KV Sarvoiverem	2S10-1104	RURAL	3348	0	0	24:00:00	-
166	MORMUGAO	33KV Majorda	11KV Duguem	3S05-1105	RURAL		-	-	24:00:00	-
167	MORMUGAO	33KV Majorda	11KV Nuvem	3S05-1106	RURAL		-	-	24:00:00	-
168	MORMUGAO	33KV Bogda	ANTARTICA - Headland II	3S06-1104	URBAN	1661	9	15540	23:52:00	1) 33KV Incomer II supply failed, supply failed from Verna S/S, 2)33KV Incomer II supply failed, supply failed from Sancoale S/S 3)33KV Incomer II supply failed, supply failed from Sancoale S/S 4)33KV Incomer II supply failed, supply failed from Sancoale S/S 5) 33KV Incomer II supply failed, supply failed from Verna S/S, 110 disc failed, 6) 33KV Incomer II supply failed, cable found faulty and section isolated and load shifted on 33 KV Incomer 1, 7) 33KV Incomer II supply failed, due to heavy rain and wind, 8) 33KV Incomer II supply failed, supply failed from Sancoale S/S 9) Feeder tripped on IDMT E/F

169	MORMUGAO	33KV Bogda	MASJID	3S06-1105	RURAL	2220	20	19320	23:50:00	1) Feeder tripped on IDMT E/F, 2)33KV Incomer I supply failed, supply failed from Verna S/S, 3)33KV Incomer I supply failed, supply failed from Verna S/S, 4)33KV Incomer I supply failed, supply failed from Verna S/S, 5)33KV Incomer I supply failed, supply failed from Verna S/S, 6) 33KV Incomer I supply failed, supply failed from Verna S/S, 7)33KV Incomer I supply failed, supply failed from Verna S/S, 8)33KV Incomer I supply failed, supply failed from Verna S/S, 9) 33KV Incomer I supply failed, supply failed from Verna S/S, 10) 33KV Incomer I supply failed, supply failed from Verna S/S, 110 disc failed, 11) 33KV Incomer I supply failed, supply failed from Verna S/S, 12) 33KV Incomer I supply failed, supply failed from Verna S/S, 13) 33KV Incomer I supply failed, supply failed from Verna S/S, 14) 33KV Incomer I supply failed, supply failed from Verna S/S, 15) 33KV Incomer I supply failed, supply failed from Verna S/S, 16) 33KV Incomer I supply failed, supply failed from Verna S/S, 17) 33KV Incomer I supply failed, supply failed from Verna S/S, 18) 33KV Incomer I supply failed, supply failed from Verna S/S, 19) feeder tripped indicating OCR, 20) 33KV Incomer I supply failed, reason: due to snake found on PT
170	MARGAO	33KV KRC	11KV Navelim	4S05-1101	RURAL		12	63480	22:31:50	Manually tripped to attend LT jumper near Navelim Bazaar
171	MARGAO	33KV KRC	11KV Mandopa	4S05-1102	RURAL		8	45600	22:25:00	Jumper cut near Mahalasa bakery
172	MARGAO	33KV Benaulim	11KV Betal Betim	4S07-1103	RURAL				24:00:00	
173	MARGAO	33KV Velim	11KV Kumbia bhat	4S10-1103	RURAL				24:00:00	
174	MARGAO	33KV Shigao	11KV Mollem	4S14-1102	RURAL	961	5	21660	23:48:00	Transient fault
175	MAPUSA	33KV Pernem	11KV Keri	1S01-1106	RURAL	1869	4	32448	21:40:00	Coconut leaf on line, to attend open jumper
176	MAPUSA	33KV Tuem	11KV Mandrem	1S02-1102	RURAL	3785	2	25	23:30:00	Flash over on LBS Transformer LT wire was hanging
177	MAPUSA	33KV Mapusa	11KV Industry	1S04-1101	URBAN				24:00:00	
178	MAPUSA	33KV Mapusa	11KV Karaswada	1S04-1104	URBAN				24:00:00	
179	MAPUSA	33KV Mapusa	11KV Parra	1S04-1113	RURAL				24:00:00	
180	MAPUSA	33KV Bicholim	11KV Lamgao	1S05-1112	RURAL	859	0	0	24:00:00	N.A
181	MAPUSA	33KV Nachinola	11KV Pomburpa	1S06-1101	RURAL				24:00:00	
182	MAPUSA	33KV Porvorim	11KV Malim	1S09-1104	RURAL				24:00:00	
183	PANJIM	33KV EDC	11KV BAL BHARTI	2S02-1108	URBAN	531	4	4560	22:40:00	1. Tripped on O/C and E/F, Load extended by Corlim SS and was faulty from their side. 2. Corlim ss delayed removing of load, 3. Flash over at Karekar Residency RMU.
184	MORMUGAO	33KV Kadamba	11KV Waddem Lake	3S02-1104	URBAN	2885	4	28860	23:45:00	Declared faulty on EFR/OCR, charged late due to heavy wind and rain.
185	MORMUGAO	33KV Sancoale	11KV Sesa Goa	3S03-1101	URBAN	1484	6	5400	23:57:06	Manually Tripped to cut damaged Sesa Goa cable, To attend Jumper in yard, Shutdown taken from Birla Section Office, To attend jumper in yard 3Nos, Taken Shut-down by Birla Staff, Attended Jumper

186	MORMUGAO	110/33/11 KV Verna	11KV SMARTLINK	3S04-1109	URBAN		3	2497.00	23:58:37	Feeder found faulty, hence manually tripped.
187	MARGAO	33KV Fatorda	11KV Gogol	4S02-1106	RURAL		1	1260	23:39:00	M/T for load shading purpose
188	MARGAO	33KV Aquem	11KV Davorlim	4S04-1106	RURAL		2	2820	23:36:30	To open RMU
189	MARGAO	33KV Nessai	11KV Chandor	4S06-1103	RURAL		12	38340	23:06:45	Heavy rain and wind
190	MARGAO	33KV Benaulim	11KV Mobor	4S07-1104	RURAL				24:00:00	
191	MARGAO	33KV Velim	11KV Assolna	4S10-1101	RURAL				24:00:00	
192	MARGAO	33KV Poinguinim	11KV Link line	4S12-1101	RURAL				24:00:00	
193	MARGAO	33KV Xelpem	11KV Dando	4S18-1105	RURAL	659	1	540	24:00:00	Shutdown taken for R&I Works of DTC
194	MAPUSA	33KV Tuem	11KV Tuem	1S02-1103	RURAL	2145	2	32408	19:26:00	To attend jumper
195	MAPUSA	220/33KV Thivim	11KV Power Grid	1S03-1103	RURAL	1856	6	35940	14:01:00	1)E/F D/F inform to Nachinola Substation S.O Sunil. Test charge taken by request from Chandrakant HT staff. 2)E/F informed to Chandrakant HT staff, charged after opening main section. Feeder stood ok. 3)Sen E/F D/Faulty informed to Nachinola S/S Khambal on duty. Charged after opening Cococola ABS. Stood ok. 4)E/F D/Faulty informed to Nachinola Substation S.O Majik, charged after opening New Cococola ABS. Stood ok. 5)M/T to open new Khadpani ABS to cut off load back feed from sodiem feeder L.Cissued to S.O Khambal for planned shutdown. Charged after returning L.C. 6)E/F, D/F informed to Nachinola substation, charged after opening Main section ABS. Stood ok.
196	MAPUSA	33KV Bicholim	11KV Pilgao	1S05-1104	RURAL	1159	3	9200	23:55:03	MANUAL TRIP to attend sparking AB cable of dhabdhaba
197	MAPUSA	33KV Bicholim	11KV Bordem	1S05-1109	URBAN	2873	0	0	24:00:00	N.A
198	MAPUSA	33KV Sanquelim	11KV Honda	1S08-1104	RURAL	564	3	61200	23:26:00	Interruption due to failure of power transformer at 220kv amona substation
199	MAPUSA	33KV Saligao	11KV Saligao	1S10-1104	RURAL				24:00:00	
200	MAPUSA	33KV Candolim	11KV Siquerim	1S12-1105	RURAL				24:00:00	
201	MAPUSA	33KV Pale	11KV Barazen	1S14-1103	RURAL	727	1	60	23:59:58	Changeover of load
202	MAPUSA	33/11 KV GIS CALANGUTE	11KV Kamat	1S18-1107	RURAL		50	25800	23:46:08	Manuel tripped, due to shut down taken by Nachinola substationy, Over current and earth fault,over current earth fault,open main section stood ok,Manuel tripped,same closed,full feeders charged ,stood okay(no fault),over current earth fault,main section of RMU open ,no fault found,Manuel tripped ,open one side(main section RMU)
203	PANJIM	33KV EDC	11KV Ribandar	2S02-1102	URBAN	1538			24:00:00	
204	PANJIM	33KV Campal	11KV Market	2S03-1101	URBAN	1762			24:00:00	
205	PANJIM	33KV Altinho	11KV Inox	2S04-1102	URBAN	86			24:00:00	
206	PANJIM	33KV Altinho	11KV Campal	2S04-1105	URBAN	2086	2	1740	23:31:00	Tripped on O/C & E/F
207	PANJIM	33KV Bambolim	11KV Mercedes	2S05-1104	RURAL				24:00:00	
208	PANJIM	33KV NIO	11KV Models	2S08-1101	URBAN				24:00:00	
209	PANJIM	33KV Curti	11KV Usgao	2S10-1102	RURAL	4640	0	0	24:00:00	-

210	PANJIM	33KV Madkai	11KV Madkai	2S15-1102	RURAL	2002	16	8700	21:35:00	Breakdown/ transient Fault/Planned Maintenace/To servicing braker
211	MORMUGAO	110/33/11 KV Verna	11KV Cortalim	3S04-1107	RURAL		15	2903.00	23:58:23	Manual Tripping initiated by Verna SS & Sancoale SS, Line Fault
212	MARGAO	33KV Raia	11KV Santamol	4S01-1103	RURAL		0	0	24:00:00	
213	MARGAO	33KV Fatorda	11KV Chowgute College	4S02-1103	URBAN		1	2340	23:21:00	M/T for load shading purpose
214	MARGAO	33KV Monte Hill	11KV Hari Mandir-II	4S03-1108	URBAN		0	0	24:00:00	
215	MARGAO	33KV Aquem	11KV Housing Board O/H	4S04-1103	URBAN		0	0	24:00:00	
216	MARGAO	33KV Aquem	11KV Margao III	4S04-1104	URBAN		0	0	24:00:00	
217	MARGAO	33KV Velim	11KV Chinchinim	4S10-1104	RURAL				24:00:00	
218	MARGAO	33KV Pontemol	11KV Dabal	4S13-1107	RURAL	13	12	17160	19:14:00	Transient Fault, Breakdown
219	MARGAO	220/33/11KV Xeldem	11KV Xelvona	4S15-1101	RURAL	2221	3	7260	23:55:42	For maintenec work of RMU
220	MAPUSA	33KV Pernem	11KV City	1S01-1103	RURAL	1488	1	2700	23:15:00	Tree branch fallen on line
221	MAPUSA	220/33KV Thivim	11KV Industrial Estate	1S03-1101	URBAN				24:00:00	
222	MAPUSA	33KV Nagoa	11KV Calangute	1S07-1101	RURAL				24:00:00	
223	MAPUSA	33KV Porvorim	11KV Sangolda	1S09-1105	RURAL				24:00:00	
224	MAPUSA	33KV Saligao	11KV Gaurawaddo	1S10-1109	URBAN				24:00:00	
225	MAPUSA	33KV Valpoi	11KV City New	1S11-1105	RURAL	6380	7	56580	21:45:17	Tree cutting, Major Fault at Amona SS
226	MAPUSA	33KV Sal	11KV Kasarpal	1S16-1103	RURAL	452	4	5266	23:57:10	To attend jumper cut on pole.
227	MAPUSA	33/11 KV GIS CALANGUTE	11KV Mark Memorial	1S18-1105	URBAN		9	12420	23:53:06	Manuel tripped,due to load sheeding, Manuel tripped for safety purpose,Manuel tripped,VCB servicing by Pristine,Over current and earth fault,Manuel tripped ,to attend red hot
228	PANJIM	33KV Campal	11KV St. Inez	2S03-1107	URBAN	551			24:00:00	
229	PANJIM	33KV Altinho	11KV Cabo	2S04-1112	URBAN	796			24:00:00	
230	PANJIM	33KV PILAR	11KV Batim	2S06-1103	RURAL	4475	2	300	23:55:00	Tripped on O/C relay
231	PANJIM	33KV NIO	11KV NIO	2S08-1103	URBAN				24:00:00	
232	PANJIM	33KV Colony	11KV Bazaar	2S09-1101	URBAN	2652	20	6960	22:04:00	18-Transient faults 2-Breakdown
233	PANJIM	33KV Bethora	11KV Industrial	2S13-1104	URBAN	420	5	1620	23:33:00	Transient Fault, Breakdown, Planned Shut down
234	PANJIM	33KV Kundaim	11KV Kundaim	2S14-1104	RURAL	2501	29	14940	19:51:00	Breakdown/ transient Fault/Planned Maintenace/To servicing braker
235	MORMUGAO	33KV Kadamba	11KV Vasco city	3S02-1103	URBAN	1857	3	37500	23:40:30	OC, EFR, Conductor snapped near Leena Hotel.

236	MORMUGAO	33KV Sancoale	11KV Vasco-I	3S03-1103	URBAN	2369	7	23640	23:47:17	LA faulty of Hollant slope DTC, Hollant slope DTC AB switch was open and ull feeder ws charged, LT staff taken shutdown for fire near DTC Dabral Raghavi Estate Dabolim, Attended jumper on line, Due to Vasco-II Tree cutting (double circuit), Taken shutdown by Vasco-2 line, Planned shutdown
237	MORMUGAO	110/33/11 KV Verna	11KV Oxynitro	3S04-1110	RURAL		7	1394.00	23:59:14	Feeder found faulty, hence manually tripped.
238	MARGAO	33KV Fatorda	11KV Fatorda	4S02-1105	URBAN		1	1860	23:29:00	M/T for load shading purpose
239	MARGAO	33KV Monte Hill	11KV GVN2	4S03-1101	URBAN		0	0	24:00:00	
240	MARGAO	33KV Cuncolim	11KV IDC I	4S09-1102	RURAL				24:00:00	
241	MARGAO	33KV Velim	11KV Betul	4S10-1102	RURAL				24:00:00	
242	MARGAO	33KV Poinguinim	11KV Marli Tirval	4S12-1102	RURAL				24:00:00	
243	MARGAO	33KV Pontemol	11KV Town 1	4S13-1101	URBAN	4338	0	0	24:00:00	
244	MARGAO	33KV Rivona	11KV Maina	4S16-1101	RURAL	726	11	41760	23:35:06	Due to frequent failure of AB cable termination kit and planned shutdown taken for tree cutting
245	MAPUSA	33KV Nagoa	11KV Baga	1S07-1107	RURAL				24:00:00	
246	MAPUSA	33KV Porvorim	11KV Soccorro	1S09-1101	RURAL				24:00:00	
247	MAPUSA	33KV Saligao	11KV Industry O/H	1S10-1106	URBAN	1258	4	17880	19:02:00	1)M/T to open old interlink ABS for planned shutdown work. From old inetrlink ABS upto Chaitanya ABS. Charged after opening the same. 2)O/C RY phase D/Faulty informed to Nachinola Substation. Charged after opening 4 pole ABS, but trip on RYB phase. 3)E/F D/Faulty informed to Nachinola Substation after opening Main section ABS. Stood ok. 4)E/F D/F informed to Nachinola Substation & HT staff. Charged after opening Dhamade ABS
248	MAPUSA	33KV Saligao	11KV Nerul	1S10-1108	RURAL				24:00:00	
249	MAPUSA	220/33KV Amona	11 KV Pissurlem IDC	1S13-1104	RURAL				24:00:00	
250	MAPUSA	33/11 KV GIS CALANGUTE	11KV Shivam	1S18-1104	RURAL		12	13740	23:52:37	Over current and earth fault,Manuel tripped,VCB servicing by Pristine,Over current and earth fault,pulled by Mark Memorial feeder,Manuel tripped, due to load shedding,Manuel tripped for load shedding as informed by Thivim substation,
251	PANJIM	33KV Corlim	11KV Molar	2S01-1106	RURAL				24:00:00	
252	PANJIM	33KV Campal	11KV City	2S03-1103	RURAL	4			24:00:00	
253	PANJIM	33KV Nagali hills(IT Park)	11KV STATUS	2S07-1104	URBAN				24:00:00	
254	PANJIM	33KV Colony	11KV Curti	2S09-1105	URBAN	729	31	6060	22:19:00	29-Transient faults 2-Breakdown
255	PANJIM	33KV Dharbandora	11KV Dharbandora	2S11-1104	RURAL	2455	63	33480	14:42:00	Transient Fault, Breakdown
256	MORMUGAO	33KV Sancoale	11KV College	3S03-1107	RURAL	1168	2	2400	23:58:43	Due to cable isolate Tomy Carvallo to Bharat Nagar, Cable damaged MVR
257	MARGAO	33KV Benaulim	11KV Colva Exp	4S07-1107	URBAN				24:00:00	
258	MARGAO	220/33/11KV Xeldem	11KV Rivona	4S15-1102	RURAL	2528	11	15360	23:50:54	Because of birds and monkey activity in Rivona area and Failure of AB Cable termination kit.
259	MARGAO	33KV Rivona	11KV Colomba	4S16-1103	RURAL	316	12	24720	23:45:18	Ab Cbale kit failed At Shivsorem And Talsai Section

260	MARGAO	33KV Xelpem	11KV Sanguem	4S18-1101	URBAN	2670	5	6960	23:59:00	Shut taken for underground cabling work,, LT line stringing work, DTC Renovation work
261	MAPUSA	33KV Tuem	11KV Ashvem Cable	1S02-1105	RURAL	71	-	-	24:00:00	-
262	MAPUSA	33KV Mapusa	11KV Anjuna	1S04-1106	RURAL	4952	3	25020	17:03:00	1)Test charged. Close Val and open Palloti, tripped on E/F. 2)11KV conductor snapped near Maruti Temple. 3)E/F, O/C charged after opening Badem ABS. Stood ok.
263	MAPUSA	33KV Mapusa	11KV Assagao	1S04-1110	RURAL	2825	7	18480	18:52:00	1)Idal feeder charged after Main section open Relay setting close by JE Siddesh and feeder charged at 16:00 hrs. Stood ok. Khargali VCB installed on Assagao feeder, all 3 phase showing ok. RYB 121,125,125. 2) O/C Relay on high alarm of temperature 3)Broken conductor relay tripped feeder faulty. 4)E/F, Overhead, open HT consumer 5)M/T to open ABS by HT staff 6)M/T to open ABS by HT staff Sandeep L/W 7)Charged after removing tree branch but tripped on O/C
264	MAPUSA	33KV Bicholim	11KV Ladphem	1S05-1103	RURAL	2232	3	5420	23:57:05	Interruption due to failure of power transformer at 220kv amona substation
265	MAPUSA	33KV Bicholim	11KV Narva	1S05-1106	RURAL	2189	4	17080	23:50:49	Interruption due to failure of power transformer at 220kv amona substation
266	MAPUSA	33KV Nachinola	11KV Moira	1S06-1103	RURAL	3569	2	4380	22:47:00	1)E/F, D/F informed Nachinola Substation , Main section open.Stood ok. 2)E/F, D/F informed to HT staff Sakharam
267	MAPUSA	33KV Nachinola	11KV Bastora	1S06-1104	RURAL	2213	2	1335600	11:38:00	Planned Shutdown and load Shedding
268	MAPUSA	33KV Sal	11KV Sal	1S16-1101	RURAL	797	4	11860	23:53:37	MANUAL TRIP For UG cable connection .
269	PANJIM	33KV Corlim	11KV Dhulapi	2S01-1101	RURAL				24:00:00	
270	PANJIM	33KV EDC	11KV Vidyut Bhawan	2S02-1104	URBAN	825			24:00:00	
271	PANJIM	33KV Altinho	11KV Alcon	2S04-1104	URBAN	1398			24:00:00	
272	PANJIM	33KV Bambolim	11KV Donapaula	2S05-1103	RURAL				24:00:00	
273	PANJIM	33KV Curti	11KV OPA	2S10-1103	RURAL	1470	0	0	24:00:00	-
274	PANJIM	33KV Kundaim	11KV Marcel	2S14-1102	RURAL	7822	17	5460	22:29:00	Breakdown/ transient Fault/Planned Maintenace/To servicing braker
275	PANJIM	33KV Madkai	11KV Undir	2S15-1101	RURAL	2015	11	6900	22:05:00	Breakdown/ transient Fault/Planned Maintenace/To servicing braker
276	MORMUGAO	110/33/11 KV Verna	11KV Herald	3S04-1102	URBAN		13	3716.00	23:57:56	Feeder found faulty, hence manually tripped and changeover initiated.
277	MORMUGAO	110/33/11 KV Verna	11KV Jordan	3S04-1105	URBAN		13	2613.00	23:58:33	Feeder found faulty, hence manually tripped.
278	MORMUGAO	33KV Majorda	11KV Ramesh Hotel	3S05-1101	URBAN		-	-	24:00:00	-

279	MARGAO	33KV Raia	11KV Raia	4S01-1101	RURAL		0	0	24:00:00	
280	MARGAO	33KV Raia	11KV Rachol	4S01-1104	RURAL		2	4680	23:21:00	M/T - to attend opened jumper at veterinary Tr.
281	MARGAO	33KV Fatorda	11KV Old market U/G	4S02-1102	URBAN		2	4500	23:22:30	M/T for load shading purpose
282	MARGAO	33KV Aquem	11KV Housing Board U/G	4S04-1102	RURAL		0	0	24:00:00	
283	MARGAO	33KV Aquem	11KV Malbhat	4S04-1105	URBAN		0	0	24:00:00	
284	MARGAO	33KV Nessai	11KV MIE	4S06-1101	RURAL		0	0	24:00:00	
285	MARGAO	33KV Carmona	11KV XIRO	4S08-1103	RURAL				24:00:00	
286	MARGAO	33KV Canacona	11KV Shristhal	4S11-1102	RURAL				24:00:00	
287	MARGAO	33KV Canacona	11KV Kindlem	4S11-1103	RURAL				24:00:00	
288	MARGAO	33KV Pontemol	11KV Town 2	4S13-1106	URBAN	1264	1	2100	23:58:50	Emergency Shutdown taken to attend Bansai Feeder Red Hot 2 Nos at Pontemol Sub-station.
289	MARGAO	33KV Pontemol	11KV HODAR	4S13-1109	RURAL		2	3300	23:58:10	Due to Heavy rainfall, strong winds and Lightning, feeder tripped on EFR and was declared Faulty Feeder Sectionized and supply restored through Ring Feed arrangement
290	MARGAO	33KV Xelpem	11KV Barazan	4S18-1103	RURAL	1247	11	37020	23:59:01	Due to frequent failure of AB Cable terminations kit, AB Cable puncture, AB Cable insulation failure,
291	MAPUSA	33KV Bicholim	11KV Assnora	1S05-1110	RURAL	3786	4	3780	23:57:58	MANUALTRIP catch fire at tip assnora and also removed dry coconut leaf on line
292	MAPUSA	33KV Nagoa	11KV Sauntawada	1S07-1102	RURAL				24:00:00	
293	MAPUSA	33KV Nagoa	11KV Dharwadkar	1S07-1108	RURAL				24:00:00	
294	MAPUSA	33KV Porvorim	11KV Pundalic Nagar	1S09-1102	RURAL				24:00:00	
295	MAPUSA	220KV Amona	11KV Amona Marcel	1S13-1103	URBAN				24:00:00	
296	PANJIM	33KV Corlim	11KV Khumarjau	2S01-1107	RURAL				24:00:00	
297	PANJIM	33KV Corlim	11KV Diwar	2S01-1109	RURAL				24:00:00	
298	PANJIM	33KV EDC	11KV Ginger	2S02-1106	URBAN	405			24:00:00	
299	PANJIM	33KV Campal	11KV LA-Campal	2S03-1102	URBAN	3001			24:00:00	
300	PANJIM	33KV Campal	11KV Indoor Stadium	2S03-1104	URBAN	1023	1	60	23:59:00	Tripped on O/C & E/F
301	PANJIM	33KV Bambolim	11KV Chimbhel	2S05-1106	RURAL				24:00:00	
302	PANJIM	33KV NIO	11KV Rajbhawan	2S08-1104	URBAN				24:00:00	
303	PANJIM	33KV Colony	11KV Ponda-I	2S09-1104	URBAN	3885	5	2220	23:23:00	3-Transient faults 2-Breakdown
304	PANJIM	33KV Dharbandora	11KV Bondla	2S11-1103	RURAL	3144	24	9540	21:21:00	Transient Fault, Breakdown
305	PANJIM	33KV Kundaim	11KV Industry III	2S14-1105	URBAN	131	11	26460	16:39:00	Breakdown/ transient Fault/Planned Maintenance/To servicing braker
306	MORMUGAO	33KV Harbour	11KV Vasco-I	3S01-1102	URBAN				24:00:00	
307	MORMUGAO	33KV Sancoale	11KV Industrial	3S03-1108	URBAN	585	0	0	24:00:00	Nil
308	MARGAO	33KV Fatorda	11KV Borda	4S02-1104	URBAN		0	0	24:00:00	
309	MARGAO	33KV Aquem	11KV AQUEM BAIXO	4S04-1108	URBAN		1	1320	23:38:00	M/T - feeder put off and charged after changing incoming cable of Sapna Gandeur.
310	MARGAO	33KV Benaulim	11KV Benaulim	4S07-1101	RURAL				24:00:00	
311	MARGAO	33KV Benaulim	11KV Trinity	4S07-1106	RURAL				24:00:00	
312	MARGAO	220/33/11KV Xeldem	11KV Quepem	4S15-1103	URBAN	4866	3	5340	23:56:48	Because of Conductor snapped and birds and monkey activity in ambaulim area

313	MARGAO	33KV Rivona	11KV Sulcorna	4S16-1102	RURAL	388	9	24540	23:45:24	Due to frequent failure of AB cable termination kit and planned shutdown taken for tree cutting
314	MARGAO	33KV Waddem	11KV Netravali	4S17-1102	RURAL	365	0	0	24:00:00	
315	MAPUSA	220/33KV Thivim	11KV Sirsaim	1S03-1106	RURAL	2358	5	31080	15:22:00	1)SEN/E/F D/F informed Nachinola S/S S.O charegd as per request of L/W Saideep to open railway ABS. Stood ok. 2)M/T L.C issued to Nachinola Substation to attend jumper at Main section & Madani supply upto Forest RMU. 3)M/T to open Tale ABS & back feed supply from Assonore to Tale ABS L.C issued for contractor work. 4)E/F D/F informed to Nachinola Substation. Main section open. Stood ok. 5)E/F informed to Nachinola Substation. Charged after opening Tale ABS but feeder tripped on E/F
316	MAPUSA	33KV Bicholim	11KV ADVALPAL	1S05-1105	RURAL	1247	4	11660	23:53:44	MANUAL TRIP for tree cutting work at mulgao vinayank nagar.
317	MAPUSA	33KV Bicholim	11KV City	1S05-1108	RURAL	3526	0	0	24:00:00	N.A
318	MAPUSA	33KV Bicholim	11KV Kudchirem	1S05-1111	RURAL	1209	3	8580	23:55:23	For change over purpose
319	MAPUSA	33KV Nachinola	11KV Aldona OH	1S06-1102	RURAL				24:00:00	
320	MAPUSA	33KV Sanquelim	11KV Amona	1S08-1103	URBAN	5368	5	68400	23:22:00	Interruption due to failure of power transformer at 220kv amona substation, and shutdown for line maintainence
321	MAPUSA	33KV Porvorim	11KV RND	1S09-1103	RURAL				24:00:00	
322	MAPUSA	33KV Porvorim	11KV Chogum	1S09-1110	RURAL				24:00:00	
323	PANJIM	33KV Corlim	11KV Carambolim	2S01-1104	RURAL				24:00:00	
324	PANJIM	33KV Campal	11KV Adarsh	2S03-1105	URBAN	193			24:00:00	
325	PANJIM	33KV Altinho	11KV National	2S04-1101	URBAN	1244			24:00:00	
326	PANJIM	33KV Altinho	11KV Manoshanti	2S04-1106	URBAN	861			24:00:00	
327	PANJIM	33KV NIO	11KV NIO Colony	2S08-1105	URBAN	125			24:00:00	
328	PANJIM	33KV Colony	11KV Khadpabandh	2S09-1103	URBAN	4662	8	1800	23:30:00	7-Transient faults 1-Breakdown
329	PANJIM	33KV Curti	Farmagudi	2S10-1108	URBAN	3402	1	14700	19:55:00	Transient Fault
330	PANJIM	33KV Kundaim	11KV Industry II	2S14-1106	URBAN	228	12	26100	16:45:00	Breakdown/ transient Fault/Planned Maintenace/To servicing braker
331	PANJIM	33KV Madkai	11KV Industry II	2S15-1105	URBAN	274	15	15660	19:39:00	Breakdown/ transient Fault/Planned Maintenace/To servicing braker
332	MORMUGAO	33KV Harbour	11KV Mangor	3S01-1104	URBAN	3901	4	39540	23:39:24	Manual trip to shift load on Bramhastal feeder and feeder charged.
333	MORMUGAO	33KV Sancoale	11KV Dabolim	3S03-1109	URBAN		0	0	24:00:00	Nil
334	MORMUGAO	110/33/11 KV Verna	11KV Industrial	3S04-1103	URBAN		5	1161.00	23:59:21	Feeder found faulty, hence manually tripped.

335	MORMUGAO	33KV Bogda	Brahmasthal - vasco 1	3S06-1102	URBAN	4235	9	15540	23:52:00	1) 33KV Incomer II supply failed, supply failed from Verna S/S, 2)33KV Incomer II supply failed, supply failed from Sancoale S/S 3)33KV Incomer II supply failed, supply failed from Sancoale S/S 4) 33KV Incomer II supply failed, supply failed from Sancoale S/S 5)33KV Incomer II supply failed, supply failed from Verna S/S, 110 disc failed, 6) 33KV Incomer II supply failed, cable found faulty and section isolated and load shifted on 33 KV Incomer I; 7)feeder tripped indicating OCR, 8) 33KV Incomer II supply failed, due to heavy rain and wind, 9) 33KV Incomer II supply failed, supply failed from Sancoale S/S
336	MORMUGAO	33KV Bogda	HARBOUR	3S06-1103	URBAN	953	19	24480	23:47:00	1)33KV Incomer I supply failed, supply failed from Verna S/S, 2)33KV Incomer I supply failed, supply failed from Verna S/S, 3) Feeder tripped on sensitive E/F, Chowgule transformer side internal fault, 4)33KV Incomer I supply failed, supply failed from Verna S/S, 5) 33KV Incomer I supply failed, supply failed from Verna S/S, 6) 33KV Incomer I supply failed, supply failed from Verna S/S 7) 33KV Incomer I supply failed, supply failed from Verna S/S, 8)33KV Incomer I supply failed, supply failed from Verna S/S, 9) 33KV Incomer I supply failed, supply failed from Verna S/S, 10)33KV Incomer I supply failed, supply failed from Verna S/S, 110 disc failed, 11) 33KV Incomer I supply failed, supply failed from Verna S/S, 12) 33KV Incomer I supply failed, supply failed from Verna S/S, 13) 33KV Incomer I supply failed, supply failed from Verna S/S, 14) 33KV Incomer I supply failed, supply failed from Verna S/S, 15) 33KV Incomer I supply failed, supply failed from Verna S/S, 16) 33KV Incomer I supply failed, supply failed from Verna S/S, 17) 33KV Incomer I supply failed, supply failed from Verna S/S, 18)33KV Incomer I supply failed, supply failed from Verna S/S, 19) 33KV Incomer I supply failed, reason: due to snake found on PT
337	MARGAO	33KV Raia	11KV Loutalim	4S01-1102	RURAL		0	0	24:00:00	
338	MARGAO	33KV Monte Hill	11KV Adarsh	4S03-1104	URBAN		0	0	24:00:00	
339	MARGAO	33KV Nessai	11KV Paroda	4S06-1102	RURAL		8	12720	23:33:30	AB switch opened at Canal. Feeder holding
340	MARGAO	33KV Benaulim	11KV Varca	4S07-1105	RURAL				24:00:00	
341	MARGAO	33KV Pontemol	11KV Kalay	4S13-1104	RURAL	177	5	34680	23:40:42	Transient trippings , Manual trippings , jumper opening , I/C conductor snapping ,supply failure
342	MARGAO	220/33/11KV Xeldem	11KV Assolda	4S15-1104	RURAL	1695	7	6660	23:56:00	Tree Banch Fallen On line at Avedwm Pump
343	MARGAO	33KV Waddem	11KV Bhati	4S17-1101	RURAL	635	5	8340	23:59:00	Due to frequent failure of AB Cable terminations kit, AB Cable puncture, AB Cable insulation failure,
344	PANJIM		11KV Tisk Bazar		URBAN				24:00:00	

345	PANJIM		11KV Baldai		RURAL				24:00:00	
346	PANJIM	33KV Kundaim	Kundai Rural	2S14-1108	RURAL				24:00:00	
347	PANJIM	33KV Kundaim	Undergound 4	2S14-1109	URBAN	2895	7	11400	20:50:00	Transient Fault, Breakdown
348	PANJIM	33KV Kundaim	Kunkolim-Keri	2S14-1107	RURAL	1182	1	900	23:45:00	Transient Fault, Breakdown, Planned Shut down