

11 KV Feeder Outage for the Month of June 2026										
Sr. No	Town Name	Substation	Feeder Name	Feeder Code	Rural / Urban	Number of Consumers	Number Outages	Duration Of Outage (Sec)	Average Hours of Steady Supply	Reason for power disruptions
1	MAPUSA	220/33KV Thivim	11KV Thivim Village	1S03-1105	RURAL	2158	1	61	23:58:59	1. O/C, D/F, informed to Nachinola Substation, one jumper open near Poder Palni. Charged after attending, but tripped.
2	MAPUSA	33KV Bicholim	11KV MAYEM	1S05-1107	RURAL	2471	7	15000	23:24:17	Tree cutting
3	MAPUSA	33KV Sanquelim	11KV Sanquelim	1S08-1102	URBAN	0	3	10800	23:54:00	O/C, E/F, Breaker maintenance
4	MAPUSA	33KV Porvorim	11KV Porvorim Bazar	1S09-1109	RURAL				24:00:00	
5	MAPUSA	33KV Porvorim	Audit bhavan	1S09-1112	URBAN	1680	1	4500	22:45:00	Unknown vehicle dashed on DP
6	MAPUSA	33KV Valpoi	11KV Bhironda	1S11-1101	RURAL	375	4	7680	23:28:00	Tree cutting
7	MAPUSA	33KV Candolim	11KV Candolim	1S12-1103	RURAL				24:00:00	
8	PANJIM	33KV Nagali hills(IT Park)	11KV BSNL	2S07-1105	URBAN				24:00:00	
9	PANJIM	33KV Madkai	11KV Industry I	2S15-1104	URBAN	71	3	5400	22:30:00	Breakdown/ transient Fault/Planned Maintenace

10	MORMUGAO	33KV Bogda	HEADLAND	3S06-1101	URBAN	1906	14	8700	23:55:00	1) 33 KV Incomer I manually tripped due to meter testing at substation by MRT, 2) 33KV Incomer I supply failed, supply failed from Verna substation, 3) 33KV Incomer I supply failed, supply failed from Verna substation, 4) 33KV Incomer I supply failed, supply failed from Verna substation, 5) 33KV Incomer I supply failed, supply failed from Verna substation, 6) 33KV Incomer I supply failed, supply failed from Verna substation, 7) 33KV Incomer I supply failed, shutdown taken by Kadamba sub station to replace jumper, 8) 33KV Incomer I supply manually tripped to replace 33 KV PT in the yard, 9) 33KV Incomer I supply failed, supply failed from Verna substation, 10) 33KV Incomer I supply failed, supply failed from Verna substation, 11) 33KV Incomer I supply failed, supply failed from Verna substation, 12) 33KV Incomer I supply failed, supply failed from Verna substation, 13) 33KV Incomer I supply failed, change over done 14) 33KV Incomer I supply failed, supply failed from Verna substation,
11	MARGAO	33KV Monte Hill	11KV Hari Mandir	4S03-1105	URBAN		0		24:00:00	
12	MARGAO	33KV Aquem	11KV Khareband	4S04-1101	URBAN		1	1200	23:40:00	To attend red hot nut bolt of 10mva -tr-II VCB outgoing side 'R' phase
13	MARGAO	33KV Carmona	11KV Zalor	4S08-1101	RURAL				24:00:00	
14	MARGAO	33KV Cuncolim	11KV Dharmapur	4S09-1106	RURAL				24:00:00	
15	MARGAO	33KV Pontemol	11KV Bansai	4S13-1105	RURAL				24:00:00	
16	MAPUSA	33KV Mapusa	11KV Althino	1S04-1105	URBAN				24:00:00	
17	MAPUSA	33KV Mapusa	11KV Siolim	1S04-1112	RURAL	4945	1	52	23:30:00	Tree cutting work done
18	MAPUSA	33KV Nachinola	11KV Aldona UG	1S06-1105	RURAL				24:00:00	
19	MAPUSA	33KV Nagoa	11KV AGARWADDO	1S07-1109	RURAL				24:00:00	
20	MAPUSA	33KV Saligao	11KV Betim	1S10-1105	RURAL				24:00:00	
21	MAPUSA	33 KV Anjuna	11KV Starco	1S15-1103	RURAL				24:00:00	
22	PANJIM	33KV Corlim	11KV New Ind.Estate	2S01-1103	URBAN				24:00:00	
23	PANJIM	33KV EDC	11KV Patto-Plaza	2S02-1103	URBAN	91			24:00:00	
24	PANJIM	33KV Bambolim	11KV Siridao	2S05-1101	RURAL				24:00:00	

25	PANJIM	33KV Nagali hills(IT Park)	11KV Adraar	2S07-1101	URBAN				24:00:00	
26	PANJIM	33KV Nagali hills(IT Park)	11KV CARANZALEM	2S07-1102	URBAN				24:00:00	
27	PANJIM	33KV Curti	11KV Shanti Nagar	2S10-1105	URBAN	5147	4	27000	16:30:00	1-Transient fault 3-Breakdown
28	PANJIM	33KV Kundaim	11KV Mardol	2S14-1101	RURAL	4212	11	1620	23:33:00	Breakdown/ transient Fault/Planned Maintenace/
29	MORMUGAO	110/33/11 KV Verna	11KV IFB	3S04-1104	URBAN		2	120	23:59:56	Manual tripping by S/D-III
30	MARGAO	33KV Benaulim	11KV Colva	4S07-1102	RURAL				24:00:00	
31	MARGAO	33KV Velim	11KV Dramapur	4S10-1105	RURAL				24:00:00	
32	MARGAO	33KV Canacona	11KV Agonda	4S11-1101	RURAL				24:00:00	
33	MARGAO	33KV Canacona	11KV Gaondongri	4S11-1104	RURAL				24:00:00	
34	MARGAO	33KV Pontemol	11KV Kakoda	4S13-1108	URBAN				24:00:00	
35	MARGAO	33KV Shigao	11KV Dhat	4S14-1103	RURAL				24:00:00	
36	MARGAO	33KV Xelpem	11KV Ponsamol	4S18-1102	RURAL	2179	2	5940	23:59:00	Due to frequent failure of AB Cable terminations kit, AB Cable puncture, tree fallen fallen on line, pole damaged due to tree fallen
37	MAPUSA	220/33KV Thivim	11KV Industrial Estate I (U/G)	1S03-1102	RURAL				24:00:00	
38	MAPUSA	33KV Mapusa	11KV Guirim	1S04-1109	RURAL				24:00:00	
39	MAPUSA	33KV Bicholim	11KV Karapur	1S05-1102	RURAL	0	0	0	24:00:00	
40	MAPUSA	33KV Nagoa	11KV Nagoa	1S07-1104	RURAL				24:00:00	
41	MAPUSA	33KV Porvorim	11KV Housing board	1S09-1106	RURAL				24:00:00	
42	MAPUSA	33KV Porvorim	Devashri Feeder	1S09-1113	URBAN				24:00:00	
43	MAPUSA	33KV Valpoi	11KV Nagargao (New)	1S11-1104	RURAL	2730	8	3540	23:52:37	Tree cutting
44	MAPUSA	220KV Amona	11KV Maina	1S13-1101	RURAL	375	4	2100	23:51:15	E/F, O/C, M/T for AB switch maintenance
45	MAPUSA	33 KV Anjuna	11KV chapora	1S15-1104	URBAN				24:00:00	
46	MAPUSA	33KV Sal	11KV Mencurem	1S16-1104	RURAL	372	8	5100	23:49:21	1-Transient fault 2-Breakdown
47	MAPUSA	33/11 KV GIS CALANGUTE	11KV Maria Rosa	1S18-1101	RURAL				24:00:00	
48	MAPUSA	33/11 KV GIS CALANGUTE	11KV Weena	1S18-1106	RURAL	567	11	11100	23:53:50	Manual tripped due to cable damage,Manual tripped/to put load on 33kv Transformer-2 through bus coupler, Manual tripped,red hot attended at Candolim substation yard,Manual tripped,to put load on Transformer-1, over current and earth fault, Declared faulty, over current and earth fault, Manuel tripped,main section incoming open, Manual tripped,to normalise the load.Over current and earth fault, Manual tripped for safety purpose
49	PANJIM	33KV Campal	11KV Ideal School	2S03-1106	URBAN	0			24:00:00	
50	PANJIM	33KV NIO	11KV Odxel	2S08-1102	URBAN				24:00:00	

51	PANJIM	33KV Dharbandora	11KV Sonarbag	2S11-1101	RURAL	1050	52	31140	15:21:00	Transient Fault,Breakdown,Planed shutdown
52	PANJIM	33KV Bethora	11KV Bonbag	2S13-1103	RURAL	1178	2	1560	23:34:00	Transient Fault,Breakdown
53	PANJIM	33KV Kundaim	11KV Industry I	2S14-1103	URBAN	242	3	1800	23:30:00	Breakdown/ transient Fault/Planned Maintenace/
54	MORMUGAO	33KV Harbour	11KV Vasco city	3S01-1105	URBAN	3060	5	14400	23:55:54	Manual trip, large tree fallen and same has been informed to HT staff and load upto 11KV AB Switch open.
55	MORMUGAO	33KV Sancoale	11KV Sicgil	3S03-1104	RURAL	534	1	2700	23:58:30	VCB servicing
56	MORMUGAO	110/33/11 KV Verna	11KV Quellosim	3S04-1111	RURAL		9	14400	23:52:00	1. Tripped on E/F On " Y" Phase,2. Tripped on B Phase Charged after two Minutes, 3.Tripped on B Phase Charged after two Minutes, 4.Shutdown taken by Sancoale HT staff to remove load Yellappa A/LW)
57	MARGAO	33KV Cuncolim	11KV Balli	4S09-1103	RURAL				24:00:00	
58	MARGAO	33KV Poinguinim	11KV Khotigao	4S12-1103	RURAL				24:00:00	
59	MAPUSA	220/33KV Thivim	11KV Tivim	1S03-1108	RURAL				24:00:00	
60	MAPUSA	33KV Nagoa	11KV Arpora	1S07-1105	RURAL				24:00:00	
61	PANJIM	33KV EDC	11KV Kanaka	2S02-1107	URBAN	593			24:00:00	
62	PANJIM	33KV Bambolim	11KV Santacruz	2S05-1105	RURAL				24:00:00	
63	PANJIM	33KV Nagali hills(IT Park)	11KV MANIPAL	2S07-1106	URBAN				24:00:00	
64	PANJIM	33KV NIO	11KV Alto-Nagali	2S08-1106	URBAN				24:00:00	
65	PANJIM	33KV Colony	11KV Ponda II	2S10-1101	URBAN	3432	3	360	23:54:00	3-Breakdown
66	PANJIM	33KV Curti	11KV Ponda II	2S10-1101	URBAN	3432	3	360	23:54:00	Transient Fault
67	PANJIM	33KV Shiroda	11KV Shiroda Bazar	2S12-1102	RURAL	1759	13	4920	22:38:00	Transient Fault
68	MORMUGAO	33KV Harbour	11KV Harbour	3S01-1101	URBAN	2390	5	720	23:48:00	Transient Fault
69	MORMUGAO	110/33/11 KV Verna	11KV Lokmat	3S04-1108	URBAN		15	52080	23:31:04	1. Manually Tripped for Tree Cutting, 2. To open section ABS near hp godown for fault isolation, 3. Tripped on E/F, 4. M/T for Load Restrictions from SLDC
70	MORMUGAO	33KV Majorda	11KV Utorda	3S05-1103	RURAL	----	----	----	24:00:00	----

71	MORMUGAO	33KV Majorda	11KV Arrosim	3S05-1104	RURAL	1563	7	18504	23:55:16	Trip on OCR & EFR. After open at cansaulim Bazar Feeder stood ok upto Cansaulim Bazar conductor snapped at St. Laurence Chapel , Delayed due to staff on 11KV Verna feeder . feeder M/T for safety purpose , Line staff working on 11 KV Majorda Feeder. Open Cansaulim gate ABS's stood ok at fault:- Pin Insulator punctured near cansaulim , full feeder charged. Shutdown taken for tree cutting near Adu Bar behind Cansaulim Section Office. After patrolling and sectionalising ABS , found coconut palm fallen on line near field ABS Arossim after removing feeder charged. after opening konkan railway ABS(outside) feeder charged stood ok & line patrolling tree fall on line nearPWD Tank & removed , full feeder charged at 13.26 stood ok. open konkan railway ABS in field and taken work 5 nos Disc insulators replaced
72	MARGAO	33KV Aquem	11KV KHAREBAND II	4S04-1109	RURAL		2	4020	23:26:30	33KV Margao Express I failed from Xeldem Sub Station, O.C.R - reset and feeder charged, tripped again at 04:02 after opening sewerage plant feeder charged stood Ok
73	MARGAO	33KV KRC	11KV MES	4S05-1103	RURAL		3	14520	22:39:20	M/T. RMU opened, To attend red hot at 33KV Nessai-II at KRC S/S yard and load was shifted to KRC S/S
74	MARGAO	33KV Carmona	11KV Cavellossim	4S08-1104	RURAL				24:00:00	
75	MARGAO	33KV Cuncolim	11KV Patten	4S09-1107	RURAL				24:00:00	
76	MARGAO	33KV Canacona	11KV Palolem	4S11-1105	URBAN				24:00:00	
77	MAPUSA	33KV Mapusa	11KV Market	1S04-1108	URBAN				24:00:00	
78	MAPUSA	33KV Bicholim	11KV IDC	1S05-1101	RURAL	163	6	7440	23:39:24	M/T for change over
79	MAPUSA	33KV Nagoa	11KV Parra	1S07-1103	RURAL				24:00:00	
80	MAPUSA	33KV Porvorim	11KV Torda	1S09-1107	RURAL				24:00:00	
81	MAPUSA	33KV Porvorim	Highland Villa	1S09-1114	URBAN				24:00:00	
82	MAPUSA	220KV Amona	11KV Navelim	1S13-1102	RURAL	538	6	10920	23:29:40	M/T for change over , Tree cutting
83	MAPUSA	33/11 KV GIS CALANGUTE	11KV Calculo	1S18-1102	RURAL				24:00:00	
84	PANJIM	33KV EDC	11KV Neugi Nagar	2S02-1105	URBAN	2019			24:00:00	
85	PANJIM	33KV Altinho	11KV Lydia Garden	2S04-1110	URBAN	1440			24:00:00	
86	PANJIM	33KV NIO	11KV Taligao	2S08-1108	URBAN				24:00:00	
87	PANJIM	33KV Bethora	11KV Nirankal	2S13-1102	RURAL	2390	5	720	23:48:00	Transient Fault
88	MORMUGAO	33KV Kadamba	11KV New Waddem	3S02-1101	URBAN	5854	4	3600	23:37:00	Tree had fallen on the line. Manual tripped to normalize New Waddem feeder.
89	MORMUGAO	33KV Sancoale	11KV Cortalim	3S03-1105	RURAL	1833	3	5580	23:57:00	Tree branch fallen on line,Crow touching metal part on pole

90	MARGAO	33KV Monte Hill	11KV Lohia	4S03-1103	URBAN		2	5700	23:12:30	Incoming supply was Faulty
91	MARGAO	33KV KRC	11KV Navelim UG	4S05-1105	URBAN		2	5700	23:12:30	Incoming supply was Faulty
92	MARGAO	33KV Cuncolim	11KV Chinchinim	4S09-1104	RURAL		16	45780	23:12:19	To attend jumper, CT overload, Tree branch fallen on line at Nagmoddem, Shutdown taken for LT work
93	MARGAO	33KV Poinguinim	11KV Poinguinim	4S12-1104	RURAL				24:00:00	
94	MAPUSA	33KV Pernem	11KV Dhargal	1S01-1105	RURAL	4015	5	7800	22:00:00	Maintenance work
95	MAPUSA	33KV Saligao	11KV Navy	1S10-1107	RURAL				24:00:00	
96	MAPUSA	33KV Valpoi	11KV Thana	1S11-1103	RURAL	1580	7	4920	23:48:17	Tree cutting
97	MAPUSA	33KV Candolim	11KV Ximer	1S12-1101	RURAL				24:00:00	
98	MAPUSA	33 KV Anjuna	11KV Temvi	1S15-1101	URBAN				24:00:00	
99	MAPUSA	33/11 KV GIS CALANGUTE	11KV Post Office	1S18-1103	RURAL				24:00:00	
100	PANJIM	33KV Corlim	11KV Kadamba	2S01-1110	RURAL				24:00:00	
101	PANJIM	33KV PILAR	11KV Neura	2S06-1101	RURAL	2230	2	9540	21:21:00	Tripped on O/C,E/F and 86 relay, Snapped jumper at Dhakte-Bhat DTC, Tripped on E/F and 86 relay, Corlim Side was faulty
102	PANJIM	33KV Shiroda	11KV Borim	2S12-1101	RURAL	5515	3	540	23:51:00	Transient Fault
103	PANJIM	33KV Shiroda	11KV Torla Paz	2S12-1104	RURAL	2133	2	240	23:56:00	Transient Fault
104	MORMUGAO	33KV Kadamba	11KV Airport	3S02-1105	URBAN	2510	3	13800	23:58:06	Manual trip, Declared Shutdown.
105	MORMUGAO	33KV Majorda	11KV Majorda	3S05-1102	RURAL	----	----	----	24:00:00	----
106	MARGAO	33KV Monte Hill	11KV Lohia-II	4S03-1107	URBAN		2	5400	23:15:00	Incoming supply was Faulty, Transformer I Oil Filtration work
107	MARGAO	33KV Canacona	11KV Gulem	4S11-1106	RURAL				24:00:00	
108	MARGAO	33KV Pontemol	11KV IDC	4S13-1103	RURAL				24:00:00	
109	MARGAO	33KV Shigao	11KV Collem	4S14-1101	RURAL				24:00:00	
110	MAPUSA	33KV Pernem	11KV Torse	1S01-1102	RURAL	3597	9	38640	22:48:51	To attend open jumper at Porascadem Railway bridge. Coconut leaf found on line at Ugveem and jumper touching the pole. Tree branch found on line at Tamboxe. Monkey found on line at Tamboxe. To attend jumper and mouth blade in sub station yard. Tree branch found on line at Duskir near Petrol Pump. Tree fallen on line at Mopa Bagayat
111	MAPUSA	33KV Mapusa	11KV Khorlim	1S04-1107	URBAN				24:00:00	
112	MAPUSA	33KV Porvorim	11KV Salai	1S09-1108	RURAL				24:00:00	
113	MAPUSA	33KV Porvorim	11KV GURUDWARA	1S09-1111	URBAN	1220	1	1260	23:39:00	one number jumper opened
114	MAPUSA	33KV Saligao	11KV PILERNE (UG)	1S10-1110	RURAL				24:00:00	
115	MAPUSA	33KV Valpoi	11KV Dabose	1S11-1106	RURAL	2	1	420	23:53:00	Tree cutting
116	MAPUSA	33KV Sal	11KV Ibrampur	1S16-1102	RURAL	375	9	10800	23:40:00	Incoming supply was Faulty
117	PANJIM	33KV Altinho	11KV Tonca Miramar	2S04-1108	URBAN	1333			24:00:00	
118	PANJIM	33KV PILAR	11KV Agasaim	2S06-1102	RURAL				24:00:00	
119	PANJIM	33KV Bethora	11KV Shiroda	2S13-1101	RURAL	715	6	1920	23:28:00	Transient Fault

120	MORMUGAO	33KV Kadamba	11KV Vasco church	3S02-1102	URBAN	4483	2	10320	23:58:30	O/C, E/F near PWD pumping station & incoming cable jumper disconnected at Taniya hotel & line charged.
121	MORMUGAO	33KV Sancoale	11KV Vasco-II	3S03-1106	RURAL	2463	6	10740	23:54:14	VCB Servicing,Jumper attended inyard,To close ABS of smart Bazar,Serviced VCB refitting,Breaker repair by Pristine Engineering, L/A faulty of htc Zudio (consumer side), ABS kept open and also guarding touch the line.
122	MARGAO	33KV Monte Hill	11KV GVN1	4S03-1102	URBAN		2	6300	23:07:30	Incoming supply was Faulty
123	MARGAO	33KV Cuncolim	11KV IDC II	4S09-1101	RURAL				24:00:00	
124	MARGAO	33KV Poinguinim	11KV Loliem	4S12-1105	RURAL				24:00:00	
125	MAPUSA	33KV Pernem	11KV Sawal	1S01-1104	RURAL	1030	2	16380	23:59:54	Pin insulator faulty at Sangale DP
126	MAPUSA	33KV Tuem	11KV Industry	1S02-1101	URBAN	452	2	8520	22:59:53	Tree fallen on line. Lizard found on line
127	MAPUSA	220/33KV Thivim	11KV Colvale	1S03-1104	RURAL	2862	2	86	23:58:34	1. M/T request from Dhaku A/L L.C issued to Nachinola substation to repair Main section ABS 2. O/C, E/F open railway ABS and charged but feeder tripped on O/C, E/F.
128	MAPUSA	33KV Mapusa	11KV Duler	1S04-1102	URBAN				24:00:00	
129	MAPUSA	33KV Mapusa	11KV City	1S04-1103	RURAL				24:00:00	
130	MAPUSA	33KV Sanquelim	11KV Poriem	1S08-1101	RURAL	7560	4	9000	23:55:00	Breaker maintenance, tree cutting
131	MAPUSA	33KV Valpoi	11KV Saleli	1S11-1102	RURAL	3205	7	4740	23:48:43	Tree cutting
132	MAPUSA	33KV Candolim	11KV Highland	1S12-1106	RURAL				24:00:00	
133	MAPUSA	33 KV Anjuna	11KV vagator	1S15-1102	RURAL				24:00:00	
134	PANJIM	33KV EDC	11KV Old bus stand	2S02-1101	URBAN	741			24:00:00	
135	PANJIM	33KV Curti	11KV Durbhat	2S10-1106	RURAL	1560	5		24:00:00	
136	PANJIM	33KV Madkai	11KV Karanzal	2S15-1103	RURAL	822	14	3600	23:00:00	Breakdown/ transient Fault/Planned Maintenace/
137	MORMUGAO	33KV Sancoale	11KV Cansualim	3S03-1102	RURAL	2789	4	11700	23:53:43	Dando side faulty,guarding snap, shutdown requested by Majorda staff
138	MORMUGAO	110/33/11 KV Verna	11KV Verna	3S04-1101	RURAL		9	12960	23:52:48	1. Tripped on E/F, 2. Tripped on O/C, 3. Manual Tripping by Verna SS for urgent maintenance, 4. M/T by Majorda S/S for Opening RMU of faulty Section, 5. M/T as per Majorda S/S to Close RMU Section
139	MORMUGAO	110/33/11 KV Verna	11KV Nagoa	3S04-1106	RURAL		8	16260	23:50:58	1. Manual Tripping by Verna SS for maintenance, 2. M/T as per request L/W from Majorda SS, 3. Tripped on O/C Charged after Opening Section at Pirni RMU holding, 4. Tripped on O/C and E/F, Charged after Opening faulty Section at pirni, 5. O/C trip, Charged after Opening Section at Cansaulim bypass road Nagao, 5. Tripped on E/F
140	MARGAO	33KV Raia	11KV Curtorim	4S01-1105	RURAL		0		24:00:00	
141	MARGAO	33KV Fatorda	11KV Ambaji	4S02-1101	URBAN		0		24:00:00	
142	MARGAO	33KV Monte Hill	11KV Mutt	4S03-1106	URBAN		2	3840	23:28:00	Incoming supply was Faulty
143	MARGAO	33KV Aquem	11KV Margao I	4S04-1107	URBAN		1	4140	22:51:00	Flashover at roofmaker RMU, To attend red hot nut bolt of 10mva -tr-II VCB outgoing side 'R' phase

144	MARGAO	33KV Nessai	11KV Goa Carbon	4S06-1104	URBAN		3	6840	23:22:00	AB switch opened at Dyna. Line holding, TREE BRANCHES FALLEN ON LINE AND CONDUCTOR SNAPPED
145	MARGAO	33KV Carmona	11KV Janoth Bazar	4S08-1102	URBAN				24:00:00	
146	MARGAO	33KV Cuncolim	11KV Cuncolim	4S09-1105	RURAL				24:00:00	
147	MARGAO	33KV Pontemol	11KV Panchwadi	4S13-1102	RURAL	3115	0	2520	23:58:36	Manual trippings, I/C supply failure , transient faults
148	MARGAO	33KV Xelpem	11KV Malkarne	4S18-1104	RURAL				24:00:00	
149	MAPUSA	33KV Pernem	11KV Nagzar	1S01-1101	RURAL	3676	15	51660	23:02:46	To attend open jumper at Amaiwada main section AB switch. Coconut tree fallen on line at Chandel near 3 staf bar. Guarding touching to line at Chichule, Dhargal. Tree branch touching HT line near Kapni DP. Coconut leaf found on line at Chandel
150	MAPUSA	33KV Tuem	11KV Morjim	1S02-1104	RURAL	3096	4	272	23:30:00	OCRYB phase outgoing ABS open & charged feeder holding, Jumper open in Sub Station yard
151	MAPUSA	220/33KV Thivim	11KV Industrial Estate II (U/G)	1S03-1107	URBAN				24:00:00	
152	MAPUSA	33KV Mapusa	11KV Sodiem	1S04-1111	RURAL	1515	7	179	23:30:00	M/T to erect LT pole at Housing board, OC RY phase on Alba ABS heavy flash over
153	MAPUSA	33KV Nagoa	11KV Sanqwadi	1S07-1106	RURAL				24:00:00	
154	MAPUSA	33KV Saligao	11KV Candolim church	1S10-1102	RURAL				24:00:00	
155	MAPUSA	33KV Saligao	11KV Shervani Calangute	1S10-1103	RURAL				24:00:00	
156	MAPUSA	33KV Pale	11KV Nanus	1S14-1101	RURAL	1671	4	1440	23:59:00	O/c, E/F,
157	MAPUSA	33KV Pale	11KV Kotumbi	1S14-1102	RURAL	615	5	300	23:59:00	O/c, E/F due to heavy wind & Planned Shutdown for maintenance
158	MAPUSA	33/11 KV GIS CALANGUTE	11KV Tivaiwaddo	1S18-1108	RURAL	483	5	14940	23:51:58	Over current ,shivam load put on Tivai waddo feeder, Over current and earth fault
159	PANJIM	33KV Corlim	11KV Old Goa	2S01-1102	RURAL				24:00:00	
160	PANJIM	33KV Corlim	11KV Old Industry	2S01-1105	URBAN				24:00:00	
161	PANJIM	33KV Altinho	11KV Circuit House	2S04-1103	URBAN	569			24:00:00	
162	PANJIM	33KV Bambolim	11KV MES	2S05-1102	RURAL				24:00:00	
163	PANJIM	33KV Nagali hills(IT Park)	11KV OITIYANT	2S07-1103	URBAN				24:00:00	
164	PANJIM	33KV Colony	11KV Rajiv Gandhi Kala Mandir	2S09-1106	URBAN	1364	0	0	24:00:00	-
165	PANJIM	33KV Curti	11KV Sarvoiverem	2S10-1104	RURAL	3348	0	0	24:00:00	-
166	MORMUGAO	33KV Majorda	11KV Duguem	3S05-1105	RURAL	----	----	----	24:00:00	----
167	MORMUGAO	33KV Majorda	11KV Nuvem	3S05-1106	RURAL	----	----	----	24:00:00	----

168	MORMUGAO	33KV Bogda	ANTARTICA - Headland II	3S06-1104	URBAN	1661	10	12060	23:53:00	1) 33KV Incomer II supply failed, shutdown taken by Sancoale sub station to replace jumper in the yard, 2) 33 KV Incomer II manually tripped due to meter testing at sub station by MRT, 3) 33KV Incomer II supply failed, supply failed from Sancoale S/S, 4) 33KV Incomer II supply failed, supply failed from Sancoale S/S, 5) 33KV Incomer II supply failed, supply failed from Sancoale S/S, 6)33KV Incomer II supply failed, supply failed from Sancoale S/S, 7) 33KV Incomer II supply failed, supply failed from Xeldem sub station 8) 33KV Incomer II supply failed, supply failed from Sancoale S/S, 9) 33KV Incomer II supply failed, supply failed from Sancoale S/S, 10) 33KV Incomer II supply failed, shutdown taken by Kadamba substation for tree cutting
169	MORMUGAO	33KV Bogda	MASJID	3S06-1105	RURAL	2220	16	9540	23:55:00	1) 33 KV Incomer I manually tripped due to meter testing at sub station by MRT, 2) Feeder faulty on EFR, 3) 33KV Incomer I supply failed, supply failed from Verna sub station, 4) 33KV Incomer I supply failed, supply failed from Verna sub station, 5) 33KV Incomer I supply failed, supply failed from Verna sub station, 6) 33KV Incomer I supply failed, supply failed from Verna sub station, 7) Feeder tripped on earth fault, 8) 33KV Incomer I supply failed, supply failed from Verna sub station, 9) 33KV Incomer I supply failed, shutdown taken by Kadamba sub station to replace jumper, 10) 33KV Incomer I supply manually tripped to replace 33 KV PT in the yard, 11) 33KV Incomer I supply failed, supply failed from Verna sub station, 12) 33KV Incomer I supply failed, supply failed from Verna sub station, 13) 33KV Incomer I supply failed, supply failed from Verna sub station, 14) 33KV Incomer I supply failed, supply failed from Verna sub station, 15) 33KV Incomer I supply failed, change over done

170	MARGAO	33KV KRC	11KV Navelim	4S05-1101	RURAL		7	19260	23:14:09	M/T for tree cutting, Conductor snapped, Coconut leaves fallen on line near woods residency
171	MARGAO	33KV KRC	11KV Mandopa	4S05-1102	RURAL		0		24:00:00	
172	MARGAO	33KV Benaulim	11KV Betal Betim	4S07-1103	RURAL				24:00:00	
173	MARGAO	33KV Velim	11KV Kumbia bhat	4S10-1103	RURAL				24:00:00	
174	MARGAO	33KV Shigao	11KV Mollem	4S14-1102	RURAL				24:00:00	
175	MAPUSA	33KV Pernem	11KV Keri	1S01-1106	RURAL	1869	7	24120	23:03:00	Sparrow found on line at Bhatwadi, Korgao. Coconut leaf found on line at Bagayat, Parashte. Coconut leaf found on line near Kharebandh, Pernem. Coconut tree fallen on line at Konadi and to attend cut jumper at Kaloba AB Switch at Konadi. Pin insulator punctured at Kharebandh, Pernem
176	MAPUSA	33KV Tuem	11KV Mandrem	1S02-1102	RURAL	3830	13	1740	23:30:00	Declare shutdown, E/F D/F fault found , Cable faulty,
177	MAPUSA	33KV Mapusa	11KV Industry	1S04-1101	URBAN	-	-	-	24:00:00	-
178	MAPUSA	33KV Mapusa	11KV Karaswada	1S04-1104	URBAN				24:00:00	
179	MAPUSA	33KV Mapusa	11KV Parra	1S04-1113	RURAL				24:00:00	
180	MAPUSA	33KV Bicholim	11KV Lamgao	1S05-1112	RURAL	859	14	12300	23:45:22	
181	MAPUSA	33KV Nachinola	11KV Pomburpa	1S06-1101	RURAL				24:00:00	
182	MAPUSA	33KV Porvorim	11KV Malim	1S09-1104	RURAL				24:00:00	
183	PANJIM	33KV EDC	11KV BAL BHARTI	2S02-1108	URBAN	531			24:00:00	
184	MORMUGAO	33KV Kadamba	11KV Waddem Lake	3S02-1104	URBAN	2885	5	14460	23:55:30	Manual trip, Double circuit creeper cutting & tree cutting done.
185	MORMUGAO	33KV Sancoale	11KV Sesa Goa	3S03-1101	URBAN	1484	4	12000	23:53:33	04 Nos. Jumper attended in yard, Sesa Goa Qtr. Side faulty, feeder faulty,Birla Temple to Palm estateside faulty after section found faulty
186	MORMUGAO	110/33/11 KV Verna	11KV SMARTLINK	3S04-1109	URBAN		6	4980	23:57:14	1. Tripped on E/F, 2. Manual Tripping by Verna SS for urgent maintenance, 3. Manual tripping for feeder data incorporation in SCADA, 4. M/T for Load Restrictions from SLDC
187	MARGAO	33KV Fatorda	11KV Gogol	4S02-1106	RURAL		0		24:00:00	
188	MARGAO	33KV Aquem	11KV Davorlim	4S04-1106	RURAL		1	15660	19:39:00	Feeder tripped on EFR and load was shifted to Aquem-Margao S/S
189	MARGAO	33KV Nessai	11KV Chandor	4S06-1103	RURAL		3	2760	23:44:40	AB switch opened at Guirdolim. Tripped on EFR, AB switch opened at Laxmi temple. Feeder holding, M/T. Coconut leaf had fallen on HT line near Jio tower at Guirdolim
190	MARGAO	33KV Benaulim	11KV Mobor	4S07-1104	RURAL				24:00:00	
191	MARGAO	33KV Velim	11KV Assolna	4S10-1101	RURAL				24:00:00	
192	MARGAO	33KV Poinguinim	11KV Link line	4S12-1101	RURAL				24:00:00	
193	MARGAO	33KV Xelpem	11KV Dando	4S18-1105	RURAL	659	0	0	24:00:00	NIL
194	MAPUSA	33KV Tuem	11KV Tuem	1S02-1103	RURAL	2145	7	22440	23:06:44	Conductor snapped. To attend open jumper. Tree fallen on line
195	MAPUSA	220/33KV Thivim	11KV Power Grid	1S03-1103	RURAL				24:00:00	
196	MAPUSA	33KV Bicholim	11KV Pilgao	1S05-1104	RURAL	998	9	8300	23:44:38	E/F

197	MAPUSA	33KV Bicholim	11KV Bordem	1S05-1109	URBAN	2655	7	6800	23:43:49	O/c, E/F due to heavy wind & Planned Shutdown for maintenance
198	MAPUSA	33KV Sanquelim	11KV Honda	1S08-1104	RURAL	564	6	18000	23:50:00	O/c, E/F due to heavy wind & Planned Shutdown for maintenance
199	MAPUSA	33KV Saligao	11KV Saligao	1S10-1104	RURAL				24:00:00	
200	MAPUSA	33KV Candolim	11KV Siquerim	1S12-1105	RURAL				24:00:00	
201	MAPUSA	33KV Pale	11KV Barazen	1S14-1103	RURAL	732	2	900	23:59:00	O/c, E/F due to heavy wind & Planned Shutdown for maintenance
202	MAPUSA	33/11 KV GIS CALANGUTE	11KV Kamat	1S18-1107	RURAL				24:00:00	
203	PANJIM	33KV EDC	11KV Ribandar	2S02-1102	URBAN	1538			24:00:00	
204	PANJIM	33KV Campal	11KV Market	2S03-1101	URBAN	1762	1	1020	23:43:00	Tripped on O/C & E/F, Flashover at Greenland LBS
205	PANJIM	33KV Altinho	11KV Inox	2S04-1102	URBAN	86			24:00:00	
206	PANJIM	33KV Altinho	11KV Campal	2S04-1105	URBAN	2086			24:00:00	
207	PANJIM	33KV Bambolim	11KV Mercedes	2S05-1104	RURAL				24:00:00	
208	PANJIM	33KV NIO	11KV Models	2S08-1101	URBAN				24:00:00	
209	PANJIM	33KV Curti	11KV Usgao	2S10-1102	RURAL	4641	0	0	24:00:00	-
210	PANJIM	33KV Madkai	11KV Madkai	2S15-1102	RURAL	2003	5	1980	23:27:00	Breakdown/ transient Fault/Planned Maintenace/To servicing braker
211	MORMUGAO	110/33/11 KV Verna	11KV Cortalim	3S04-1107	RURAL		19	21120	23:48:16	1. Manual tripping by Sancoale staff, 2. M/T as per request Viraj kadam (L/W) for tree cutting and declare shutdown, 3. M/T to Close AB Switch opposite Chikita L/W Viraj Sancoal HT Staff, 4. Manual Tripping by Verna SS for maintenance, 5. M/T as per Sancoale HT staff to open AB Switch at meeting point, 6. M/T as per request Sancoal S/S HT L/W Nelish to close AB Switch at meeting Point, 7. Tripped on E/F Charged after opening section AB switch.
212	MARGAO	33KV Raia	11KV Santamol	4S01-1103	RURAL		3	2460	23:46:20	Tripped on OCR, M/T to check Colleadongar RMU
213	MARGAO	33KV Fatorda	11KV Chowgule College	4S02-1103	URBAN		0		24:00:00	
214	MARGAO	33KV Monte Hill	11KV Hari Mandir-II	4S03-1108	URBAN		6	12000	23:26:40	Manually Tripped, Incoming supply was Faulty, LT Side cable fault
215	MARGAO	33KV Aquem	11KV Housing Board O/H	4S04-1103	URBAN		0		24:00:00	
216	MARGAO	33KV Aquem	11KV Margao III	4S04-1104	URBAN		0		24:00:00	
217	MARGAO	33KV Velim	11KV Chinchinim	4S10-1104	RURAL				24:00:00	
218	MARGAO	33KV Pontemol	11KV Dabal	4S13-1107	RURAL	2873	11	54480	23:29:42	Trasient trippings , Manual trippings , snapping of conductor , jumper opening , tree branches fell on line , I/C supply failure , broken of poles
219	MARGAO	220/33/11KV Xeldem	11KV Xelvona	4S15-1101	RURAL	2221	2	3600	23:58:00	For maintenance work of RMU
220	MAPUSA	33KV Pernem	11KV City	1S01-1103	RURAL	1488	3	7212	23:16:00	To cut coconut leaf and attending one jumper at Fajanta AB switch DP. LT conductor snapped near Mangar DTC, Pernem

221	MAPUSA	220/33KV Thivim	11KV Industrial Estate	1S03-1101	URBAN				24:00:00	
222	MAPUSA	33KV Nagoa	11KV Calangute	1S07-1101	RURAL				24:00:00	
223	MAPUSA	33KV Porvorim	11KV Sangolda	1S09-1105	RURAL				24:00:00	
224	MAPUSA	33KV Saligao	11KV Gaurawaddo	1S10-1109	URBAN				24:00:00	
225	MAPUSA	33KV Valpoi	11KV City New	1S11-1105	RURAL	6380	15	11700	23:47:00	Tree cutting and New cable connecting
226	MAPUSA	33KV Sal	11KV Kasarpal	1S16-1103	RURAL	452	5	4500	23:45:00	tree cutting
227	MAPUSA	33/11 KV GIS CALANGUTE	11KV Mark Memorial	1S18-1105	URBAN				24:00:00	
228	PANJIM	33KV Campal	11KV St. Inez	2S03-1107	URBAN	551			24:00:00	
229	PANJIM	33KV Altinho	11KV Cabo	2S04-1112	URBAN	796			24:00:00	
230	PANJIM	33KV PILAR	11KV Batim	2S06-1103	RURAL				24:00:00	
231	PANJIM	33KV NIO	11KV NIO	2S08-1103	URBAN				24:00:00	
232	PANJIM	33KV Colony	11KV Bazaar	2S09-1101	URBAN	2652	0	0	24:00:00	-
233	PANJIM	33KV Bethora	11KV Industrial	2S13-1104	URBAN	420	2	180	23:57:00	Transient Fault,Planned shutdown
234	PANJIM	33KV Kundaim	11KV Kundaim	2S14-1104	RURAL	2501	5	1920	23:28:00	Breakdown/ transient Fault/Planned Maintenance/
235	MORMUGAO	33KV Kadamba	11KV Vasco city	3S02-1103	URBAN	1857	4	5400	23:57:06	Manual trip to cut coconut leaf near IDFC Bank.
236	MORMUGAO	33KV Sancoale	11KV Vasco-I	3S03-1103	URBAN	2369	5	7080	23:56:12	VCB Servicing,Tree branch fallen on line,Jumper open of Vieranagar Tank Transformer DP,33 KV conductor snapped and fallen on line.
237	MORMUGAO	110/33/11 KV Verna	11KV Oxynitro	3S04-1110	RURAL		20	19080	23:49:24	1. Manual Tripping by Verna SS for maintenance, 2. Tripped on E/F, Charged after Opening faulty Section, 3. Tripped on Sensitive Earth Fault, 4. M/T as per request L/W Mahadev SD 1 Conductor snapped near persistent Line Section AB Switch Open, 5. M/T as per request L/W Mahadev SD 1 to Close Line Section AB Switch, 6. M/T as per S/D - I To Open AB Switch Near Neaston Company remove Jumper, 7. M/T as per request ALW Denis to close AB Switch near nester Company, 8. M/T to open section ab switch by domnic linemen sub div i verna
238	MARGAO	33KV Fatorda	11KV Fatorda	4S02-1105	URBAN		0		24:00:00	
239	MARGAO	33KV Monte Hill	11KV GVN2	4S03-1101	URBAN		2	5040	23:18:00	Incoming supply was Faulty, Tree branch fallen on transformer
240	MARGAO	33KV Cuncolim	11KV IDC I	4S09-1102	RURAL				24:00:00	
241	MARGAO	33KV Velim	11KV Betul	4S10-1102	RURAL				24:00:00	
242	MARGAO	33KV Poinguinim	11KV Marli Tirval	4S12-1102	RURAL				24:00:00	
243	MARGAO	33KV Pontemol	11KV Town 1	4S13-1101	URBAN				24:00:00	
244	MARGAO	33KV Rivona	11KV Maina	4S16-1101	RURAL	726	15	54000	23:30:00	Due to frequent failure of AB cable termination kit and planned shutdown taken for tree cutting
245	MAPUSA	33KV Nagoa	11KV Baga	1S07-1107	RURAL				24:00:00	
246	MAPUSA	33KV Porvorim	11KV Soccorro	1S09-1101	RURAL	1480	1	3420	23:03:00	11kv RMU Flashed over

247	MAPUSA	33KV Saligao	11KV Industry O/H	1S10-1106	URBAN	1258	2	123	23:57:57	1. M/T for VCB servicing, load shifted on Colvale feeder. 2. M/T L.C issued to Nachinola S.O Chodankar for replacing main section ABS, outgoing ABS kept open and charged after opening Main section. Full feeder charged.
248	MAPUSA	33KV Saligao	11KV Nerul	1S10-1108	RURAL				24:00:00	
249	MAPUSA	220/33KV Amona	11 KV Pissurlem IDC	1S13-1104	RURAL	35	2	120	23:59:00	M/T for change over ,
250	MAPUSA	33/11 KV GIS CALANGUTE	11KV Shivam	1S18-1104	RURAL				24:00:00	
251	PANJIM	33KV Corlim	11KV Molar	2S01-1106	RURAL				24:00:00	
252	PANJIM	33KV Campal	11KV City	2S03-1103	RURAL	4			24:00:00	
253	PANJIM	33KV Nagali hills(IT Park)	11KV STATUS	2S07-1104	URBAN				24:00:00	
254	PANJIM	33KV Colony	11KV Curti	2S09-1105	URBAN	739	34	6960	22:04:00	32-Transient Faults 2-Breakdown
255	PANJIM	33KV Dharbandora	11KV Dharbandora	2S11-1104	RURAL	2456	64	46860	10:59:00	Transient Fault,Breakdown,Planed shutdown
256	MORMUGAO	33KV Sancoale	11KV College	3S03-1107	RURAL	1168	5	7500	23:55:58	VCB Servicing,Cable damaged by MVR, Repair of damaged cable, Faulty cable cut
257	MARGAO	33KV Benaulim	11KV Colva Exp	4S07-1107	URBAN				24:00:00	
258	MARGAO	220/33/11KV Xeldem	11KV Rivona	4S15-1102	RURAL	2528	21	28800	23:44:00	Because of birds and monkey activity in Rivona area and Failure of AB Cable termination kit.
259	MARGAO	33KV Rivona	11KV Colomba	4S16-1103	RURAL	316	8	14400	23:52:00	Ab Cbale kit failed At Shivsorem And Talsai Section
260	MARGAO	33KV Xelpem	11KV Sanguem	4S18-1101	URBAN	2670	0	0	24:00:00	NIL
261	MAPUSA	33KV Tuem	11KV Ashvem Cable	1S02-1105	RURAL	89	3	409	23:30:00	Declare shutdownPalm leaves fall on DP
262	MAPUSA	33KV Mapusa	11KV Anjuna	1S04-1106	RURAL				24:00:00	
263	MAPUSA	33KV Mapusa	11KV Assagao	1S04-1110	RURAL	2825	6	586	23:50:14	1. E/F, D/F charged after opening Church ABS at Sonarbhat. 2. E/F, D/Faulty informed to Sakharam. Charged after opening Church, Sonarbhat tapping. Stood ok. 3. M/T and outgoing ABS kept open further Agnel collage ABS kept open and load fed from Badem Substation incoming ABS oiling and greasing done by HT staff, charged and normalized by HT staff Vijay. 4. E/F, D/F charged after opening Chari ABS. 5. O/C charged after opening Agnel ABS. 6. O/C, D/Faulty, Test charged after opening Main section Agnel. Stood ok.
264	MAPUSA	33KV Bicholim	11KV Ladphem	1S05-1103	RURAL	511	3	5360	23:31:00	Transient Fault,Planed shutdown
265	MAPUSA	33KV Bicholim	11KV Narva	1S05-1106	RURAL	585	8	9780	23:39:42	MT

266	MAPUSA	33KV Nachinola	11KV Moira	1S06-1103	RURAL	3569	6	357	23:54:03	1. O/C, E/F main section open but triped O/C, E/F 2. E/F 3. Crow found on line near Tamdi Mati, same removed & charged. Stood ok. 4. E/F, immediately triped , D/F informed HT staff. Charged after opening Freddy ABS. Stood ok. 5. Charged after opening Freddy ABS. Stood ok. 6. E/F, D/F, informed HT staff Saideep. Charged after opening Bank ABS, but tripped on E/F, immediately Bastora feeder back feeded upto Bank ABS. Stood ok.
267	MAPUSA	33KV Nachinola	11KV Bastora	1S06-1104	RURAL				24:00:00	
268	MAPUSA	33KV Sal	11KV Sal	1S16-1101	RURAL	797	12	2360	23:56:44	Breakdown/ transient Fault
269	PANJIM	33KV Corlim	11KV Dhulapi	2S01-1101	RURAL				24:00:00	
270	PANJIM	33KV EDC	11KV Vidyut Bhawan	2S02-1104	URBAN	825			24:00:00	
271	PANJIM	33KV Altinho	11KV Alcon	2S04-1104	URBAN	1398			24:00:00	
272	PANJIM	33KV Bambolim	11KV Donapaula	2S05-1103	RURAL	1523	1	1680	23:32:00	Punctured Post Insulator at FM radio
273	PANJIM	33KV Curti	11KV OPA	2S10-1103	RURAL	1470	0	0	24:00:00	-
274	PANJIM	33KV Kundaim	11KV Marcel	2S14-1102	RURAL	7828	22	3360	23:04:00	Breakdown/ transient Fault/Planned Maintenace/To servicing braker
275	PANJIM	33KV Madkai	11KV Undir	2S15-1101	RURAL	2015	11	5220	22:33:00	Breakdown/ transient Fault/Planned Maintenace/To servicing braker
276	MORMUGAO	110/33/11 KV Verna	11KV Herald	3S04-1102	URBAN		24	18660	23:49:38	1. M/T as per Request of S/D - I (Pranav A/LW) Line Clearence for crane moving to install Transformer near Cipla, 2. Tripped on earth fault, 3. Tripped on overcurrent fault, 4. Tripped on earth fault. Declared Faulty Informed S/D - (Test charged) after opening 2nd Section AB Switch Holding, 5. M/T 2 nd Section AB Switch close & AB Switch Open at IFB, holding, 6. M/T to AB Switch IFB & Open 4th Section AB Switch holding, 7. M/T to close 4th Section AB Switch full feeder holding, 8. Manual tripping by S/D-III, 9. Manual Tripping by Verna SS for emergency, 10. load restriction by SLDC, 11. M/T as per S/D HT staff to open 1st Section AB Switch near Finolex (To attend jumper on 2nd AB Switch), 12. M/T as per S/D HT staff to close 1st Section AB Switch near finolex, 13. E/F Declared faulty (Fuse Blown off of Lokbeta Company)
277	MORMUGAO	110/33/11 KV Verna	11KV Jordan	3S04-1105	URBAN		12	16620	23:50:46	1. Manual tripping by S/D-I for tree cutting, 2. Manual tripping by S/D-I, 3. Manual Tripping by Verna SS for maintenance feeder data Incorporation into SCADA, 4. Manual Tripping by Verna SS for maintenance, 5. Tripped on E/F, 6. M/T for load restrictions, 7. Tripped on E/F, Full feeder charged after attending jumper near fartasy co.

278	MORMUGAO	33KV Majorda	11KV Ramesh Hotel	3S05-1101	URBAN	----	----	----	24:00:00	----
279	MARGAO	33KV Raia	11KV Raia	4S01-1101	RURAL		0		24:00:00	
280	MARGAO	33KV Raia	11KV Rachol	4S01-1104	RURAL		0		24:00:00	
281	MARGAO	33KV Fatorda	11KV Old market U/G	4S02-1102	URBAN		3	5460	23:29:40	11 KV Cabel faulty between BM DTC to sapana satellite DTC
282	MARGAO	33KV Aquem	11KV Housing Board U/G	4S04-1102	RURAL		0		24:00:00	
283	MARGAO	33KV Aquem	11KV Malbhat	4S04-1105	URBAN		1	1500	23:35:00	Tree fallen on transformer at oil factory
284	MARGAO	33KV Nessai	11KV MIE	4S06-1101	RURAL		1	10500	21:05:00	Cable fault at old macbrout company
285	MARGAO	33KV Carmona	11KV XIRO	4S08-1103	RURAL				24:00:00	
286	MARGAO	33KV Canacona	11KV Shristhal	4S11-1102	RURAL				24:00:00	
287	MARGAO	33KV Canacona	11KV Kindlem	4S11-1103	RURAL				24:00:00	
288	MARGAO	33KV Pontemol	11KV Town 2	4S13-1106	URBAN				24:00:00	
289	MARGAO	33KV Pontemol	11KV HODAR	4S13-1109	RURAL				24:00:00	
290	MARGAO	33KV Xelpem	11KV Barazan	4S18-1103	RURAL	1247	16	234960	23:59:05	Due to frequent failure of AB Cable terminations kit, AB Cable puncture,tree fallen on line,Attended the same and suply normalised
291	MAPUSA	33KV Bicholim	11KV Assnora	1S05-1110	RURAL	1963	2	3400	23:31:40	O/c, E/F due to heavy wind & Planned Shutdown for maintenance
292	MAPUSA	33KV Nagoa	11KV Sauntawada	1S07-1102	RURAL				24:00:00	
293	MAPUSA	33KV Nagoa	11KV Dharwadkar	1S07-1108	RURAL				24:00:00	
294	MAPUSA	33KV Porvorim	11KV Pundalic Nagar	1S09-1102	RURAL				24:00:00	
295	MAPUSA	220KV Amona	11KV Amona Marcel	1S13-1103	URBAN				24:00:00	
296	PANJIM	33KV Corlim	11KV Khumarjau	2S01-1107	RURAL				24:00:00	
297	PANJIM	33KV Corlim	11KV Diwar	2S01-1109	RURAL				24:00:00	
298	PANJIM	33KV EDC	11KV Ginger	2S02-1106	URBAN	405			24:00:00	
299	PANJIM	33KV Campal	11KV LA-Campal	2S03-1102	URBAN	3001			24:00:00	
300	PANJIM	33KV Campal	11KV Indoor Stadium	2S03-1104	URBAN	1023			24:00:00	
301	PANJIM	33KV Bambolim	11KV Chimbhel	2S05-1106	RURAL				24:00:00	
302	PANJIM	33KV NIO	11KV Rajbhawan	2S08-1104	URBAN				24:00:00	
303	PANJIM	33KV Colony	11KV Ponda-I	2S09-1104	URBAN	3888	0	0	24:00:00	-
304	PANJIM	33KV Dharbandora	11KV Bondla	2S11-1103	RURAL	3024	5	6900	22:05:00	Transient Fault,Breakdown,Planed shutdown
305	PANJIM	33KV Kundaim	11KV Industry III	2S14-1105	URBAN	131	5	420	23:53:00	Breakdown/ transient Fault/Planned Maintenace/
306	MORMUGAO	33KV Sancoale	11KV Industrial	3S03-1108	URBAN	585	1	2880	23:58:27	VCB Servicing
307	MARGAO	33KV Fatorda	11KV Borda	4S02-1104	URBAN		0		24:00:00	

308	MARGAO	33KV Aquem	11KV AQUEM BAIXO	4S04-1108	URBAN		1	2760	23:14:00	33KV Margao Express I failed from Xeldem Sub Station
309	MARGAO	33KV Benaulim	11KV Benaulim	4S07-1101	RURAL				24:00:00	
310	MARGAO	33KV Benaulim	11KV Trinity	4S07-1106	RURAL				24:00:00	
311	MARGAO	220/33/11KV Xeldem	11KV Quepem	4S15-1103	URBAN	4866	2	3600	23:58:00	Because of Conductor snapped and birds and monkey activity in ambaulim area
312	MARGAO	33KV Rivona	11KV Sulcorna	4S16-1102	RURAL	388	20	28800	23:44:00	Due to frequent failure of AB cable termination kit and planned shutdown taken for tree cutting
313	MARGAO	33KV Waddem	11KV Netravali	4S17-1102	RURAL	214	1	4800	23:59:00	Tripped on OCR,Tree Stems found on line,Same attended And Supply Normalised
314	MAPUSA	220/33KV Thivim	11KV Sirsaim	1S03-1106	RURAL	2358	2	347	23:54:13	1. M/T, L.C issued to shutdown, Nachinola substation for tree cutting at Main section. 2. M/T as per request of Sandeep HT staff for Planned shutdown, load shifted on Colvale feeder up to Khargale intrelink ABS L.C issued to Nachinola Substation, all ABS servicing. Charged except Bela Vista tapping centre due to contractor work.
315	MAPUSA	33KV Bicholim	11KV ADVALPAL	1S05-1105	RURAL	558	6	5700	23:44:10	Breaker maintenance, tree cutting
316	MAPUSA	33KV Bicholim	11KV City	1S05-1108	RURAL	1920	3	6500	23:23:53	Breaker maintenance, tree cutting
317	MAPUSA	33KV Bicholim	11KV Kudchirem	1S05-1111	RURAL	733	4	4800	23:40:00	e/F
318	MAPUSA	33KV Nachinola	11KV Aldona OH	1S06-1102	RURAL				24:00:00	
319	MAPUSA	33KV Sanquelim	11KV Amona	1S08-1103	URBAN	5368	5	14400	23:52:00	O/c, E/F due to heavy wind & Planned Shutdown for maintenance
320	MAPUSA	33KV Porvorim	11KV RND	1S09-1103	RURAL				24:00:00	
321	MAPUSA	33KV Porvorim	11KV Chogum	1S09-1110	RURAL				24:00:00	
322	PANJIM	33KV Corlim	11KV Carambolim	2S01-1104	RURAL				24:00:00	
323	PANJIM	33KV Campal	11KV Adarsh	2S03-1105	URBAN	193			24:00:00	
324	PANJIM	33KV Altinho	11KV National	2S04-1101	URBAN	1244	1	480	23:52:00	Tripped on O/C & E/F, Bombay Bazaar Int LBS Flashover
325	PANJIM	33KV Altinho	11KV Manoshanti	2S04-1106	URBAN	861			24:00:00	
326	PANJIM	33KV NIO	11KV NIO Colony	2S08-1105	URBAN				24:00:00	
327	PANJIM	33KV Colony	11KV Khadpabandh	2S09-1103	URBAN	4668	3	1680	23:32:00	2-Transient Faults 1-Breakdown
328	PANJIM	33KV Curti	11KV Curti	2S10-1108	URBAN	739	34	3420	23:03:00	Transient Fault & breakdown
329	PANJIM	33KV Kundaim	11KV Industry II	2S14-1106	URBAN	228	3	240	23:56:00	Breakdown/ transient Fault/Planned Maintenace/
330	PANJIM	33KV Madkai	11KV Industry II	2S15-1105	URBAN	274	17	15300	19:45:00	Breakdown/ transient Fault/Planned Maintenace/To servicing braker
331	MORMUGAO	33KV Harbour	11KV Mangor	3S01-1104	URBAN	3901	9	45240	23:37:00	Manual trip to open o/g HT AB switch S/S yard of Mata school section. HT AB switch opened, Mangor full load given from kadamba S/S. O/G HT AB switch closed in yard of Mata School section. HT AB switch closed Mangor full feeder charged at 13:23 hours. Load Normalised.

332	MORMUGAO	33KV Sancoale	11KV Dabolim	3S03-1109	URBAN		2	4320	23:57:41	VCB Servicing,To cut creepers
333	MORMUGAO	110/33/11 KV Verna	11KV Industrial	3S04-1103	URBAN		6	6360	23:56:28	1. Manual Tripping by Verna SS for Relay incorporation into SCADA, 2. Manual Tripping by Verna SS for maintenance, 3. load restriction by SLDC, 4. Tripped on E/F, 5. Tripped on Unbalance fault
334	MORMUGAO	33KV Bogda	Brahmasthal - vasco 1	3S06-1102	URBAN	4235	11	14640	23:52:00	1) 33KV Incomer II supply failed, shutdown taken by Sancoale syb station to replace jumper in the yard, 2) 33 KV Incomer II manually tripped due to meter testing at sub station by MRT, 3) 33KV Incomer II supply failed, supply failed from Sancoale S/S 4) 33KV Incomer II supply failed, supply failed from Sancoale S/S 5) 33KV Incomer II supply failed, supply failed from Sancoale S/S 6) 33KV Incomer II supply failed, supply failed from Sancoale S/S 7) 33KV Incomer II supply failed, supply failed from Xeldem sub station 8)Feeder tripped, jumper open; jumper is replaced at Gomteshwar temple, Baina, 9) 33KV Incomer II supply failed, supply failed from Sancoale S/S 10) 33KV Incomer II supply failed, supply failed from Sancoale S/S 11) 33KV Incomer II supply failed, shutdown taken by Kadamba substation for tree cutting

335	MORMUGAO	33KV Bogda	HARBOUR	3S06-1103	URBAN	953	15	12300	23:53:00	1) 33 KV Incomer I manually tripped due to meter testing at sub station by MRT, 2) 33KV Incomer I supply failed, supply failed from Verna sub station, 3) 33KV Incomer I supply failed, supply failed from Verna sub station, 4) 33KV Incomer I supply failed, supply failed from Verna sub station, 5) 33KV Incomer I supply failed, supply failed from Verna sub station, 6) 33KV Incomer I supply failed, supply failed from Verna sub station, 7) 33KV Incomer I supply failed, shutdown taken by Kadamba sub station to replace jumper, 8) Feeder tripped on earth fault, Reason: cable damaged near Khapreshwar temple by external agency, section isolated and load shifted to Brahmasthal, 9) 33KV Incomer I supply manually tripped to replace 33 KV PT in the yard, 10) 33KV Incomer I supply failed, supply failed from Verna sub station, 11) 33KV Incomer I supply failed, supply failed from Verna sub station, 12) 33KV Incomer I supply failed, supply failed from Verna sub station, 13) 33KV Incomer I supply failed, supply failed from Verna sub station
336	MARGAO	33KV Raia	11KV Loutalim	4S01-1102	RURAL		0		24:00:00	
337	MARGAO	33KV Monte Hill	11KV Adarsh	4S03-1104	URBAN		2	6600	23:05:00	Incoming supply was Faulty
338	MARGAO	33KV Nessai	11KV Paroda	4S06-1102	RURAL		0		24:00:00	
339	MARGAO	33KV Benaulim	11KV Varca	4S07-1105	RURAL				24:00:00	
340	MARGAO	33KV Pontemol	11KV Kalay	4S13-1104	RURAL	177	10	27540	23:44:42	Trasient trippings , Manual trippings , snapping of conductor , jumper opening , tree branches fell on line , I/C supply failure , broken of poles
341	MARGAO	220/33/11KV Xeldem	11KV Assolda	4S15-1104	RURAL	1695	2	21600	23:48:00	Tree Branch Fallen On line at Avedem Pump
342	MARGAO	33KV Waddem	11KV Bhati	4S17-1101	RURAL	635	1	8280	23:59:00	Due to failure of AB Cable terminations kit, AB Cable puncture, AB Cable insulation failure,
343	PANJIM	33KV Bambolim	11KV Cujira	2S05-1108	RURAL	501	1	1320	23:38:00	M/T, to clear fallen tree on LT line
344	PANJIM	33KV Altinho	11 KV FIRE STATION	2S04-1107	URBAN	125			24:00:00	
345	PANJIM	33KV Campal	11 KV ALFRAN PLAZA	2S03-1108	URBAN	0			24:00:00	

346	PANJIM	33KV Campal	11 KV RIO Grande	2S03-1109	URBAN	58			24:00:00	
347	PANJIM	33KV EDC	11 KV CENTRAL LIBRARY	2S02-1109	URBAN	546			24:00:00	
348	PANJIM	33KV EDC	11 KV PRINTING PRESS	2S02-1110	URBAN	2			24:00:00	
349	PANJIM	33KV EDC	11 KV SBI	2S02-1111	URBAN	2			24:00:00	
350	MAPUSA	33KV Pale	11KV Guleli	1S14-1104	RURAL	364	13	6510	23:56:00	O/c, E/F due to heavy wind & Planned Shutdown for maintenance
351	MAPUSA	33KV Sanquelim	11KV Karapur	1S08-1105	RURAL	2620	2	850	23:59:00	Breaker maintenance
352	MAPUSA	33KV Sanquelim	11KV Keri	1S08-1106	RURAL	1752	1	800	23:59:00	Breaker maintenance
353	PANJIM	33KV Madkai	11KV Industry II	2S15-1105	URBAN	274	17	15300	19:45:00	Breakdown/ transient Fault/Planned Maintenace/To servicing braker
354	PANJIM	33KV Kundaim	Kundai Rural	2S14-1108	RURAL	135	0	0	24:00:00	
355	PANJIM	33KV Kundaim	Undergound 4	2S14-1109	URBAN	67	0	0	24:00:00	
356	PANJIM	33KV Kundaim	Kunkolim-Keri	2S14-1107	RURAL	1384	63	780	23:47:00	Breakdown/ transient Fault/Planned Maintenace/